

AD-A169 781 REPORT ON SEISMIC STABILITY ONONDAGA DAM NEW YORK
ATTACHMENT NUMBER 2 (U) CORPS OF ENGINEERS BUFFALO NY
BUFFALO DISTRICT I X GRASSO ET AL. MAY 86


1/2

UNCLASSIFIED

DACW49-81-D-0011

F/G 13/2

NL



MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963-A

AD-A169 701

(8)

REPORT DOCUMENTATION PAGE			Date Entered	READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER		
4. TITLE (and Subtitle) <u>Report on Seismic Stability, Onondaga and Oneida Lakes, New York. Attachment No. 2.</u>		5. TYPE OF REPORT & PERIOD COVERED		
7. AUTHOR(s)		6. PERFORMING ORG. REPORT NUMBER		
9. PERFORMING ORGANIZATION NAME AND ADDRESS U.S. Army Engineer District, Buffalo NCBED-DF 1776 Niagara St., Buffalo, NY 14207		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS <i>May 86</i>		
11. CONTROLLING OFFICE NAME AND ADDRESS		12. REPORT DATE <i>May 1986</i>		
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		13. NUMBER OF PAGES 357		
16. DISTRIBUTION STATEMENT (of this Report)		15. SECURITY CLASS. (of this report) Unclassified		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		18. DECLASSIFICATION/DOWNGRADING SCHEDULE		
19. SUPPLEMENTARY NOTES		B		
20. KEY WORDS (Continue on reverse side if necessary and identify by block number) Seismic Stability, Earth Dam, Flood Control Dam, Liquification, Dam Failure, Dam Stability, Seepage, Slope Protection, Periodic Inspection, Continuing Evaluation, Civil Works Projects. DTIC FILE COPY				
21. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report is a reevaluation of the Stability of the existing Onondaga Dam which is located near the city of Syracuse, NY. This is an earth and rockfill dam and provides flood protection for the city of Syracuse which is downstream of the dam. This evaluation includes a seismic evaluation (Attachment 2) and a stability analysis based upon current Corps criteria. This document contains a Main Report, six appendices (A-F), and two attachments. The Main Report contains the local and regional geology at the project site and summarizes the results of the stability analysis. Appendix A contains pertinent data (Cont'd)				

DD FORM 1 JAN 73 EDITION OF 1 NOV 68 IS OBSOLETE

86 77051

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)

20. (Cont'd)

about Onondaga Dam. Appendix B contains the rationale for the selected soil parameters used in the analysis. Appendix C contains hand calculations of the critical slip surfaces. Appendix D contains the computer input files and sample output for the slip circle analysis. Appendix E contains the wave runup analysis for the storage pool. Appendix F contains the slope protection calculations. Attachment No. 1 is the Concrete Spillway Stability analysis and Attachment No. 2 is the seismic evaluation.

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)

ONONDAGA DAM, NY

REPORT ON SEISMIC STABILITY
ONONDAGA DAM, NY
ATTACHMENT NO. 2

U.S. Army Corps of Engineers, Buffalo District
1776 Niagara Street
Buffalo, NY

PREFACE

This study was conducted by H & A of New York and was authorized by the Department of the Army, Buffalo District, Corps of Engineers under Contract No. DACW 49-81-D-0011, Work Orders No. 2 and No. 3, dated October 13, 1981 and June 15, 1982, respectively.

The work was accomplished and the report written by Thomas X. Grasso, Staff Geologist, with assistance on seismologic evaluations provided by Dr. Edward F. Chiburis, Consultant, and Dr. Edward B. Kinney of Haley & Aldrich, Inc. All work was performed under the general technical supervision of Joseph J. Rixner, Manager of H & A of New York.

This work order was performed under the technical administration of the Buffalo District, Corps of Engineers, Geotechnical Section.

Accession For	
NTIS GRA&I	<input checked="" type="checkbox"/>
DTIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By _____	
Distribution/ _____	
Availability Codes	
Dist	Avail and/or Special
A-1	



FILE NO 1473 CORRECT
PER MR. THOMAS
WAN WART, ARMY
ENGINEERS BUFFALO NY

TABLE OF CONTENTS

	<u>Page</u>
PREFACE	i
TABLE OF CONTENTS	ii
LIST OF TABLES	iv
LIST OF FIGURES	v
PART I: INTRODUCTION	1
Purpose and Scope	1
General Description of Onondaga Dam	1
PART II: GEOLOGY	3
Physiography	3
Drainage	7
Central New York Stratigraphy	8
Onondaga Dam Site Stratigraphy	10
Depositional History	14
Glaciation	15
PART III: FIELD AND LABORATORY INVESTIGATIONS	17
Subsurface Exploration Program	17
Laboratory Testing Program	20
PART IV: SUBSURFACE CONDITIONS ALONG DAM CENTERLINE	21
Dam Embankment Materials	21
Fluvial Overbank Deposits	22
Deltaic Deposits	23
Lacustrine Deposits	24
Glacial Till	25
Bedrock	25
Subsurface Water	26
Subsurface Profile	26
PART V: TECTONIC HISTORY	28
Orogenies	28
Structural Deformations	30
Joints	32
Dikes	32

TABLE OF CONTENTS (continued)

	<u>Page</u>
PART VI: EARTHQUAKE ACTIVITY	34
Historic Earthquakes	34
Geographic Distribution of Earthquakes	34
PART VII: EVALUATION FOR ACTIVE FAULTS	36
Association of Earthquakes with Tectonism and Faults	36
Lineations	37
PART VIII: INTENSITY OF EARTHQUAKE SHAKING AT ONONDAGA DAM	38
Earthquake Intensities and Attenuation	38
Frequency of Earthquake Occurrence and Seismic Risk.	39
PART IX: ASSESSMENT OF EARTHQUAKE EFFECT ON ONONDAGA DAM	42
PART X: CONCLUSIONS	46
REFERENCES:	48
TABLES I - VI	
FIGURES 1 - 15	
APPENDIX A: CENTRAL NEW YORK SITE STRATIGRAPHY	
APPENDIX B: ONONDAGA DAM SITE STRATIGRAPHY	
APPENDIX C: ORIGINAL SUBSURFACE PROFILE	
APPENDIX D: TEST BORING LOGS D82-101 THROUGH D82-103	
APPENDIX E: LABORATORY TEST RESULTS	
APPENDIX F: ENGINEERING ANALYSES	
. SAMPLER HAMMER RATIOS	
. LIQUEFACTION ANALYSIS	

LIST OF TABLES

<u>Table</u>	<u>Title</u>
I	Geologic Time Scale
II	Generalized Stratigraphic Column - Central New York
III	Detailed Devonian Stratigraphic Column, Syracuse Meridian - Onondaga Dam Vicinity
IV	Earthquakes Within 200 km of Onondaga Dam Site
V	Chronological List of Significant ($I_0 \geq VI$) Earthquakes Within New York State
VI	List of Earthquakes Having Attenuated Intensities Greater Than or Equal to IV at the Onondaga Dam Site

LIST OF FIGURES

<u>Figure</u>	<u>Title</u>
1	Project Locus
2	Physiographic Provinces and General Bedrock Geology of New York State
3	Geologic Map of Central New York State
4	Site Geologic Map
5	Site and Subsurface Exploration Plan
6	Boring Location Plan and Subsurface Profile
7	Seismicity Epicenters, Northeastern U.S. Vicinity
7A	Seismic Zone Map of the Contiguous States and Puerto Rico
8	Intensity, Magnitude, and Acceleration Relationship
9	New York State Seismicity Zones
10	Isoseismals for $I_0 = IX$ Event, LaMalbaie, Quebec
11	Attenuation Relationships
12	Probability of Exceedence for Peak Horizontal Ground Accelerations
13	Standard Penetration Resistance vs. Depth
14	Average Acceleration Spectra for Different Site Conditions
15	Liquefaction Potential for Dam Foundation Soils
15A	Liquefaction Potential of Dam Foundation Soils Correlated to Different Earthquake Magnitudes

GEOLOGICAL AND SEISMOLOGICAL INVESTIGATIONS
AT ONONDAGA DAM, NEW YORK

PART I: INTRODUCTION

Purpose and Scope

1. The purpose of this study was to investigate and evaluate the potential earthquake hazard at Onondaga Dam located in Central New York. This study was conducted in compliance with ER1110-2-1806 "Earthquake Design and Analysis for Corps of Engineers Dams" (by the Office of the Chief of Engineers, dated April 1977).
2. The study included geological, seismological, and subsurface investigations, and geotechnical engineering analyses. The study consisted of the following elements:
 - a. an evaluation of the regional and local geology,
 - b. performance of subsurface explorations and laboratory testing to further define the nature and density of soil deposits,
 - c. an evaluation of the regional and local tectonic history with respect to structural deformation including faults,
 - d. a review of historical regional seismicity,
 - e. the determination of the maximum earthquake that will effect the site,
 - f. an assessment of earthquake effects on Onondaga Dam, including an evaluation of liquefaction potential of the subsurface soils.

General Description of Onondaga Dam

3. Onondaga Dam is located on Onondaga Creek, a tributary to the Seneca River in Onondaga County, New York (Figure 1). It is about four miles southwest of the southern limits of the City of Syracuse, New York and about 3,000 feet south of N.Y. Route 80.

4. Onondaga Dam is a flood control structure consisting of a rolled earth fill embankment with a concrete overflow side channel spillway on the right (east) abutment. The overall length of the rolled fill embankment is 1,780 feet and the maximum height is 67 feet. An 1,100 ft. long spillway channel has been cut into rock along the right abutment. Rock cuts, ranging from about 15 to 40 ft. high, are exposed along the spillway channel.

5. The dam was completed in August 1949. It was designed and constructed by the Syracuse District of the U.S. Army Corps of Engineers.

PART II: GEOLOGY

Physiography

6. Figure 2 shows the physiographic provinces of New York State. Onondaga Dam is located in the northern part of the Allegheny (Appalachian) Plateau Physiographic Province. The physiographic province immediately north of the site is the Lake Plain Physiographic Province.

Lake Plain Province

7. Bordering Lakes Erie and Ontario is a region of low relief known as the Lake Plain Province. This plain is underlain by sedimentary rocks of Late Ordovician to Devonian age that dip gently southward at 30 to 50 feet per mile. Refer to Table I for a geologic time scale. This province is bordered on the South by the Appalachian Plateau with a more or less abrupt boundary.

8. Three escarpments or "cuestas" strike east-west across the Lake Ontario portion of the plain, especially west of Rochester to the Niagara Peninsula. They are, from north to south:

- a. Medina Escarpment - Formed in the resistant Grimsby and Thorold Sandstones. This ridge is of minor topographic relief being only some 30 to 50 feet high. Wherever streams cross this feature, waterfalls result such as those at Medina, Albion and Holley. The escarpment cannot be recognized east of the Genesee River. The line of the Barge Canal rests atop this escarpment from Spencerport to Lockport.
- b. Lockport or Niagara Escarpment - This ridge is the most prominent bedrock controlled topographic feature on the Lake Ontario Plain. The Lockport Dolostone forms the caprock of this "mountain ridge", the crest of which lies about 300 feet above Lake Ontario. Niagara Falls,

the Upper Falls of the Genesee at Rochester, and many other minor falls in between are also formed on the Lockport Dolostone.

- c. Onondaga Escarpment - The southernmost escarpment is about 50 feet in height, trending eastward from Buffalo through Batavia to Auburn. This escarpment is formed of resistant Onondaga Limestone. A line of abandoned and existing quarries marks its trace across the state, along with relatively small waterfalls on the numerous streams that cross the escarpment.

9. The remainder of the Lake Plain is underlain predominantly by shales, with a few relatively thin sandstone and carbonate interbeds forming the prominent east-west escarpments described above.

10. In general, the rocks are structurally simple, dipping gently southward and forming the north-northwest flank of the Appalachian (Allegheny) Synclinorium or Basin. This singly-dipping, homoclinal structure is interrupted locally by a few faults and a few minor low, open folds. The most significant of these is the Clarendon-Linden Fault, which strikes southwestward from Lake Ontario across northwest Monroe County and southeast Orleans County, through Batavia in eastern Genesee County and to Attica in central Wyoming County. It is a nearly vertical fault system, downthrown to the west, cutting the Precambrian basement, and having a displacement ranging from about 30 to 90 meters (100 to 275 ft.), (Hutchinson, et al. 1979).

11. A local fault structure of perhaps significant proportions occurs in northern Cayuga County but mainly in the subsurface, although one or more of these faults are thought to have a surface expression. Not much is known about this structure at present. A new gas field, the Blue Tail Rooster, is producing from traps in this structure. A well-developed, nearly vertical joint system of two sets, one essentially north-south and the other east-west is the only major, regional, geologic structure. Locally, a third set of joints may be present in places.

12. The Paleozoic rocks of the Lake Plain are mantled by a substantial thickness of glacial deposits. The most dramatic of these is the drumlin field of glacial till lying between Rochester and Syracuse. Several morainal deposits and glacial lake shoreline deposits, such as the offshore bar of Lake Iroquois are also present. Ridge Road (Rt. 104) runs along this bar.

Allegheny (Appalachian) Plateau

13. The Allegheny Plateau covers nearly a third of the entire State, as shown on Figure 2, and is its largest physiographic province. It is a region of moderate to high relief with summits at Elevations 2000 to 4000 feet above sea level. The Catskill Mountains make up the eastern portion of the plateau while the remainder is often referred to as the Southern Tier. The entire region is underlain by Devonian shales, siltstones, and sandstones. However, the tops of the hills, south of Olean, expose sandstones and conglomerates of Mississippian and Pennsylvanian age (Figure 2 and Table 1). The eastern border of this province is the Catskill Front, an escarpment composed of Middle Devonian, massive, red sandstone of the Catskill Delta. The entire Catskill region is held up by these coarse deltaic sandstones. The Helderberg Escarpment of Lower Devonian Limestones stretches from the Albany area westward to Syracuse forming the northern and eastern boundary. West of Syracuse, in the Finger Lakes and Genesee region, the boundary with the Lake Plain province is not abrupt, but more gradual, occurring in the northern portion of the Finger Lakes across the Middle Devonian Hamilton Group. In western New York and southeast of Lake Erie, the Portage Escarpment of Upper Devonian siltstones and sandstones forms the western border.

14. The strata of the Allegheny Plateau dip gently southward at about 50 to 80 feet per mile. In south central New York, gentle warping of the Devonian rocks occurred and produced several gentle open folds along with minor faulting. Deep wells and geophysical seismic surveys, penetrating through the Upper Silurian in this region, do not reveal

the large surface anticlines at depth. This suggests that the Upper Silurian salt beds may have "absorbed" the deformation. Aside from the Clarendon-Linden structure, no major faults are known in the Allegheny Plateau. A few small reverse faults of minor displacement are known in central New York, one in particular being the Portland Point Fault north of Ithaca along Cayuga Lake. Several thin, ultrabasic, peridotite dikes are known in central New York near Ithaca and Syracuse. These dikes have migrated upward along joint planes, are of Mesozoic age, and are of limited extent. The joint system is extremely regular, especially in Central New York, and comprises a north-south set and an east-west set. A third set is well developed only in the southwestern part of the province. Most of the streams in the bedrock gorges are controlled by the north-south and east-west joints.

15. Glacial deposits are relatively thin on the upland portions of this province, but the north-south valleys are normally deep U-shaped glacial troughs that are partially filled by thick moraine, lacustrine, and glacial outwash deposits. Some of the glacial troughs are plugged at both ends, thereby forming Finger Lakes, while other valleys have subsequently drained. A major east-west trending divide in drainage between the north flowing St. Lawrence and the south flowing Susquehanna systems occurs along the Valley Heads Moraine, which loops across the province at the southern extremities of the Finger Lakes and neighboring valleys.

16. In the Onondaga (Tully) Valley, the Tully Moraine, south of the site and west of the Village of Tully, is the local development of the Valley Heads Moraine. Onondaga Creek flows north off the moraine toward Lake Ontario and the Tioughnioga River flows south through Cortland to the Susquehanna River.

Drainage

17. The major drainage system through the site is Onondaga Creek, consisting of two branches; the west branch rising in the vicinity of Cedarville Village and the main branch rising at the Tully Moraine. Both branches join just south of the Onondaga Dam (Figures 3 and 4) and flow north past the dam into Onondaga Lake, a tributary of the Seneca River and part of the St. Lawrence System.

18. Onondaga Creek occupies a deep U-shaped glaciated valley that once impounded a finger lake in the waning stages of glaciation. Therefore the valley contains glaciofluvial sand and gravel as terraces on both sides probably representing hanging deltas. Lacustrine deposits floor the valley in the vicinity of the site and probably underlie the sands and gravels of the hanging deltas.

19. The highest delta terrace is approximately at El. 800 feet, just southeast of Nichols Corners, while the lowest is approximately at El. 520 feet near Nedrow.

Central New York Stratigraphy

20. The rock formations of central New York are structurally simple and abundantly fossiliferous, thereby lending themselves to detailed stratigraphic studies over the last 100 years. The stratigraphic sequence dips gently southward at approximately 40 to 50 feet per mile such that the oldest units are exposed in the north and progressively younger formations are exposed southward.

21. Table II presents the generalized stratigraphic column for central New York. Figure 3 is a geologic map of the central New York region.

22. A brief description of the various rock formations in central New York is contained in the following paragraphs. A more detailed discussion of thicknesses, lithologies, and relationships of the various series, groups and formations noted on Table II is presented in Appendix A.

Upper Ordovician System

23. The oldest stratigraphic unit in central New York, exposed along the south shore of Lake Ontario, is the Queenston Formation. It encompasses a maximum of 700 feet of red, crumbly shale and red siltstone and sandstone in this region. The coarser beds increase in thickness eastward and southward.

Silurian System

24. Silurian rocks surround the Appalachian Plateau on the north and are found in the Lake Ontario Plain, and on the east in the western-most Hudson Valley Province. The older units of the Silurian sequence consist of the Grimsby Sandstone and Clinton and Lockport Groups of the Albion and Niagaran Series. These units are overlain by shales, dolomites and limestones of the Cayugan Series.

Devonian System

25. Devonian rocks are by far the most extensively exposed in New York State. Devonian strata underlie all of the Allegheny Plateau and regions adjacent to it, such as the Lake Erie Plain, southern Lake Ontario Plain, and the westernmost Hudson Valley Province.

26. Carbonates dominate the Lower Devonian and lower part of the Middle Devonian while clastic deposits predominate in the remainder of the section. The clastics are fine-textured marine rocks at the bottom, grading upward to coarse, red continental sandstones. These deposits, are known as the Catskill Delta and are a wedge of clastic sediments that thicken and become coarser to the east. The New York Devonian is subdivided into the Ulsterian Series (Lower Devonian), Erian Series (Middle Devonian) and Senecan and Chautauquan Series (Upper Devonian).

Onondaga Dam Site Stratigraphy

27. The stratigraphic sequence in the vicinity of the dam belongs to the Lower and Middle Devonian System described on Table II. A more detailed stratigraphic column along the Syracuse Meridian in the vicinity of the dam is summarized on Table III, and Figure 4 is a geologic map of the area surrounding the dam.

28. Older Silurian units are exposed to the north of the dam in Syracuse and younger Upper Devonian units cap the hills south of the dam, and form the valley sides and floor south of the Village of Tully.

29. A brief description of the stratigraphy exposed at the location of the dam is contained in the following paragraphs. Appendix B presents an expanded discussion of this stratigraphy, along with a discussion of the underlying or surrounding stratigraphy in the general vicinity of the dam site, as shown on Figure 4.

Lower Devonian - Ulsterian Series

Helderberg Group

30. The Helderberg group is composed of two formations; the Manlius Formation overlying the Rondout Formation (Chrysler Dolostone).

31. The Manlius Formation is subdivided, from older to younger, into the Olney Limestone Member, the Elmwood A, B, and C Dolostone Members, the Clark Reservation Limestone Member, and the Jamesville Limestone Member.

- a. The Olney Member is approximately 30 ft. of fine-grained, even bedded limestones; thin bedded in the lower portion, somewhat more thickly bedded in the upper portion.
- b. The Elmwood Member overlies the Olney and consists of a series of dolostones, waterlimes, and limestones. It is subdivided into three units. Elmwood A is a drab yellowish-brown, thin-bedded and mud cracked waterlime approximately 6 ft. thick. Elmwood B is a fine-grained,

blue limestone, approximately 3 ft. thick. Elmwood C, the uppermost unit, is approximately 4 ft. thick, and is a waterlime similar to Elmwood A.

- c. The Clark Reservation Limestone Member overlies the Elmwood and consists of a fine-grained, white weathering limestone characterized by a diagonal fracture system. It is approximately 5 ft. thick.
- d. The Jamesville Limestone Member overlies the Clark Reservation Member. It is approximately 25 ft. of fine-grained, dark blue, brittle limestone in thin even beds. It is exposed in the lower 12 ft. of the rock exposed in the spillway cut at the east end of the dam.

Tristates Group

32. The Oriskany Sandstone is the only formation of this group exposed in Central New York. It is not well developed in the vicinity of the dam. Only a few inches of reddish-orange, sandy layers of this unit are exposed at the base of the Onondaga Limestone in the spillway cut.

Middle Devonian - Erian Series

Onondaga Limestone

33. The Onondaga Limestone is the lowest Middle Devonian formation within the Syracuse area. It is a series of light bluish-gray semi-crystalline limestones in even continuous layers from 1 inch to 2 feet thick, separated by thin seams of dark calcarerous shale. Flattened nodules of dark blue or black chert, sometimes in continuous sheets or beds, are unevenly distributed throughout the formation, but occur mainly in the upper part of the formation. The total formation thickness is approximately 70 ft.

34. The Onondaga is comprised of five members which, from older to younger, are the Edgecliff Member, the Nedrow Member, the Moorehouse Member, the Tioga Bentonite Member, and the Seneca Member.

- a. The Edgecliff Member is a coarse, crystalline limestone with abundant fossils. The base of the member is a disconformity; i.e., it was deposited over an erosion surface that had removed previously deposited rock strata. The Member is approximately 15 ft. thick and may be seen in the spillway cut.
- b. The Nedrow Member is characterized by thin-bedded, shaly limestone. It is medium gray, very fine-grained, and contains a little chert unevenly distributed at top. It is approximately 10 ft. thick and is gradational with the overlying Moorehouse Member. Both the Nedrow and the Moorehouse units are exposed in the spillway cut.
- c. The Moorehouse Member is a medium gray, very fine-grained limestone, with 2-in. to 5-ft. thick beds separated in many places by thin shaly partings. Total thickness of the deposit is approximately 25 ft. Chert is common in the Member, but varies in amount.
- d. The Tioga Bentonite Member is a volcanic ash layer 6 to 9 inches thick separating the Moorehouse and Seneca Members. Neither the Tioga nor the overlying Seneca Member were observed in the spillway cut.
- e. The Seneca Member is similar in lithology to the upper portion of the Moorehouse Member, but is characterized by a slightly different fossil assemblage. Chert is less common in the upper part of the Member and the limestone beds become darker gray. The Member is approximately 25 ft. thick.

35. The Onondaga Limestone is overlain by the Hamilton Group which includes, from older to younger, the Marcellus Formation, the Skaneateles Formation, the Ludlowville Formation, and the Moscow Formation. These formations are approximately 1,100 ft. thick in total and are comprised

mostly of silty shales and siltstones. Refer to Appendix B for further details. The formations of the Hamilton Group are generally exposed in ravines and gullies on the sides of the Onondaga Valley at elevations above the spillway.

Depositional History

36. In general, the sedimentary rocks of central New York, and at the site in particular, were deposited in a shallow sea that flooded most of New York State. The sea was bounded on the east by a landmass that occupied the Hudson Valley region. This landmass was uplifted into a region of high relief during the Late Ordovician and once again in the Middle and Late Devonian Periods. These are discussed further in Part III of this report. Between these periods of uplift the landmass was an area of low relief and may even have been flooded by shallow seas from time to time. The material comprising the shales, siltstones and sandstones, such as the Hamilton Group, was sediment being transported off this landmass by westward flowing streams. When this landmass was high, coarse-grained clastics such as sandstones reached central New York, when it was low, fine-grained clastics such as shale were deposited. When this area was very low or even flooded, the sea cleared allowing for the deposition of carbonates such as the Helderberg Group and the Onondaga Limestone.

37. The abundance and diversity of organic remains attests to normal marine conditions prevailing during deposition. The sea was probably warm, shallow, well lighted, and of normal salinity and oxygen content. Notable exceptions to this would be conditions represented by the Queenston and Grimsby Formations, Salina Group, and the black and dark shales of the Marcellus Formation.

Glaciation

38. During the Pleistocene Epoch, the study area was covered by glacial ice approximately 2 miles thick. The erosional effect of the ice was to deeply scour the Valley of Onondaga Creek into a deep U-shaped trough.

39. As the ice waned northward, its margin paused momentarily south of the site, depositing the Tully Moraine, near Tully, New York. With continued northward withdrawal of the ice, a thin veneer of ground moraine or glacial till was laid down on top of bedrock. The ice margin then paused along the northern edge of the Allegheny Plateau causing a proglacial lake to form south of the ice front and north of the Tully Moraine. Since the ice acted as a dam, the impounded waters were forced to flow eastward to the adjacent north-south valley (Butternut Creek Valley) across the sharp ridge between the two. Therefore, a dramatic series of west to east meltwater channels were carved across the highland ridge between the Onondaga Valley on the west and the Butternut Creek Valley on the east. As the ice margin slowly withdrew northward, successively lower channels were cut across the northerly sloping face of the Helderberg-Onondaga Escarpment marking the northern rim of the Allegheny Plateau. One of the more spectacular of these is the extinct waterfall of Clark Reservation State Park west of Jamesville. A large horseshoe shaped rim of a once high waterfall and plunge basin below (Green Lake) is all that remains of this meltwater channel.

40. As lower meltwater channels were carved, the lake in the Onondaga Valley was lowered until the ice finally pulled back from the rim of the Allegheny Plateau allowing the pent up waters to escape eastward to the Mohawk River draining the lake from the Onondaga Valley.

41. When the lake was present in the valley south of Syracuse, and as it gradually receded, it received meltwater from waters discharging eastward from Marcellus, through Pumpkin Hollow, to Cedervale (Figure 3). As the lake received meltwaters from the west, a dramatic series of glacial lake deltas were deposited in the vicinity of the site. These are the nearly flat terraces so pronounced in the immediate vicinity

of the dam, as well as at Gwills Corners, South Onondaga, Nichols Corners and Ironsides on the south side of the valley. They are known as hanging deltas and are shown on Figure 4. The west end of the dam is tied into one of the largest hanging deltas in the Onondaga Valley having a surface elevation of approximately 620 feet. The hanging deltas are excellent sources of coarse sand and gravel and are being actively quarried northwest of South Onondaga. Many smaller hanging deltas occur at lower elevations north of the site on both sides of the valley.

42. The surfaces of the hanging deltas correspond favorably with the threshold elevations of the various west to east meltwater channels, described above, leading eastward to Butternut Creek Valley. Therefore, the surface elevation of the lowering proglacial lake can be mapped and recognized.

43. At the dam, the soil profile, based on the geologic history, should reflect till above bedrock with lacustrine deposits above till in the middle of the valley but coarser deltaic deposits on the sides of the valley. Above this should be coarse deltaic sand and gravel as the deltas came closer to the site as a result of the lowering lake. Finally, overbank deposits and organic peat from Onondaga Creek should cap the section. A detailed discussion of the soil profile beneath the dam is presented in a later section of this report.

PART III: FIELD AND LABORATORY INVESTIGATIONS

Subsurface Exploration Program

44. Subsurface conditions in the vicinity of the dam were investigated prior to dam construction. Nine test borings, Nos. DH-1 through DH-4, DH-6, DH-8, DH-10, DH-11, and DH-16, were drilled approximately along the dam centerline as shown on Figure 5, Site and Subsurface Exploration Plan. A subsurface profile along the dam centerline, prepared by the Corps of Engineers, is shown on Figure C-1, Profile Along Dam Centerline, contained in Appendix C. Strata lines and geologic descriptions were added to Figure C-1 by H & A of New York.

45. The logs of the original test borings generally indicate compact foundation soils. However, near-surface soil and one deeper strata in DH-3, are noted to be semi-compact. The criteria used in the design phase explorations for the dam to evaluate the relative density of the soils is not known. Therefore, no specific quantitative data relative to soil density, such as blow counts, were available to make evaluations of the liquefaction susceptibility of the subsurface soils. Such data is required to assess liquefaction susceptibility and foundation stability under design earthquake loadings.

46. For these reasons, H & A of New York recommended that a limited subsurface exploration program be conducted to obtain relative density data in order to conduct liquefaction susceptibility analyses. It was recommended that three test borings be made from the dam crest, through the embankment and into the foundation soils. Standard penetration test results would be obtained and split spoon soil samples recovered for laboratory soil testing. By drilling the borings from the dam crest, data on soil type and density for the embankment materials could be obtained and added to the permanent record for the dam.

47. The three test borings, Nos. D82-101 through D82-103, were conducted during the period 28 July through 27 August 1982 by Parratt-Wolff, Inc. of East Syracuse, New York. These test borings were drilled generally in accordance with Corps of Engineers "Specifications for Subsurface Drilling Sampling and Testing". H & A of New York field

personnel monitored the test borings, described soil and rock samples, and prepared written test boring logs in accordance with standard Corps of Engineers procedures. Completed test boring logs are contained in Appendix D. As-drilled locations and ground surface elevations are shown on Figure 6. They were surveyed by Rowell and Associates, P.C., of North Syracuse, New York, using base information contained in "Plans for Onondaga Dam, Onondaga Creek, Syracuse, N.Y.", dated 1947. Elevations are referenced to Mean Sea Level Datum (MSL).

48. The test borings were drilled with truck-mounted Mobile Drill B-56, CME 55 and/or CME 75 drill rigs. Hollow stem augers with 3-3/4 in. inside diameters were used to drill through the dam embankment materials. Augers were fitted with a properly sized plug to prevent soils from entering the augers during drilling. Split spoon samples were obtained through the augers. After the augers were advanced to a depth of 60 to 78 ft., NW-size (3-3/16-in. I.D.) flush-joint casing was then set within the augers and the boring continued by driving the NW casing with a 350-lb. hammer. The casing was driven to the depth at which a sample was to be obtained and washed out using a fishtail bit. Split spoon samples were obtained below the bottom of the casing. When driving of the NW casing became difficult, BW size (2.75-in. I.D.) flush joint casing was set within the NW casing and the boring continued by driving the BW casing. In D82-103, driving of the BW casing became difficult at a depth of 150 ft. This hole was completed from this depth using an open hole filled with drilling fluid consisting of bentonite powder manufactured by N.L. Baroid. The test boring logs in Appendix A contain notes relative to the specific steps taken to advance each of the test borings.

49. Split spoon samples were taken in all test borings. When soils containing an appreciable gravel content were encountered in the embankment, a 2-7/8-in. I.D. by 3.5-in. O.D. split spoon was used. It was driven into the soil with a 350-lb. hammer free falling 18 inches. This large diameter spoon could only be used through the hollow stem augers. When sampling in all other instances, a standard 1-3/8-in. I.D. by 2.0-in. O.D. split spoon, was used. It was driven by a 140-lb. safety hammer free falling 30 inches. All split spoons were generally

driven 24 inches unless refusal was encountered. Refusal was defined as 50 blows of either hammer with less than 0.5 ft. of spoon penetration. Boulder or cobble obstructions were occasionally encountered and were removed by means of fishtail bits or tricone roller bits. The test boring logs contain notes relative to specific sampling procedures and obstruction removal procedures used for each of the test borings.

50. Sampling was conducted continuously in each of the test borings from the bottom of the embankment soils to a depth of 150 ft. or to the bottom of the hole as in D82-101. Continuous sampling was also conducted through the embankment materials in D82-102. At depths below 150 ft. and through the embankment materials in D82-101 and D82-103, sampling was conducted at 5-ft. intervals. Test boring D82-101 was terminated at a depth of 105.7 ft., D82-102 at 173.0 ft., and D82-103 at 184.8 ft.

51. When sampling below the subsurface water level, efforts were taken to generally maintain a positive head of water within the casing to prevent the soils below the casing from running into the casing. Running conditions were still encountered, however, within D82-102 at a depth of 63.0 ft.

52. Bedrock was encountered in D82-101 at a depth of 103.3 ft. During core drilling operations, it was discovered that the bottom portion of the casing had become bent when the bedrock was encountered, and only 1.9 ft. of rock was cored before a BX-size (1.375-in. I.D.) core barrel was sheared off within the hole. The core barrel was later retrieved and the hole terminated.

53. Upon completion of each test boring, the hole was filled with grout from the bottom of the hole to the top of the embankment. The casing was removed as the grout was placed. The grout consisted of a cement and bentonite mixture containing a small amount of sand.

Laboratory Testing Program

54. Laboratory soil tests were performed on selected samples obtained from the test borings in order to assist in classification of the samples. Natural water contents, Atterberg Limits, and grain size distribution tests were performed. Grain size distributions were obtained by means of mechanical sieve analyses and/or hydrometer analyses. All tests were conducted in accordance with accepted practice, generally as recommended by ASTM.

55. A total of five natural water contents and five Atterberg Limits determinations were made on fine-grained soils exhibiting some degree of plasticity (i.e., containing clay). Four of the samples tested were from the uppermost natural soil strata and one was from a cohesive layer within the lacustrine deposits found in D82-103. In addition, a hydrometer analysis was performed on each of these samples. A total of thirteen mechanical sieve analyses were performed. Four of the samples were from the embankment materials and nine from underlying natural soil strata. Representative samples were selected from most of the major soil strata.

56. Laboratory test results for all of the above tests are contained in Appendix E.

PART IV: SUBSURFACE CONDITIONS ALONG DAM CENTERLINE

57. The recent test borings were designated, from east to west, D82-101, D82-102, and D82-103 as shown on Figure 6. They encountered five significant soil deposits and bedrock. These were as follows:

- . Dam Embankment Materials
- . Fluvial Overbank Deposits
- . Deltaic Deposits
- . Lacustrine Deposits
- . Glacial Till
- . Bedrock

58. Bedrock was encountered in the eastern-most boring only, D82-101. Not all soil deposits were encountered in each test boring. A subsurface profile along the dam centerline developed from both the recent test borings and the original design test borings is shown on Figure 6. The following paragraphs describe the major soil deposits encountered in the recent borings, beginning with the embankment materials and progressing downward. Refer to Paragraphs 38 through 43 for a discussion of the geologic origin of the deposits.

Dam Embankment Materials

59. The dam embankment materials may generally be described as brown, silty coarse to fine SAND, little gravel, to coarse to fine sandy GRAVEL, little silt, with an occasional layer of medium to fine SAND, trace gravel, trace silt.

- a. Embankment materials were encountered to depths of 55.0, 65.5, and 65.5 ft. in borings D82-101, D82-102, and D82-103, respectively.
- b. Penetration resistance values were generally obtained with a 2-7/8 in. I.D. by 3.5-in. O.D. split spoon sampler driven by a 350-lb. hammer falling freely

18 inches. Blow counts for one foot of penetration ranged from 19 to refusal, defined as 50 blows with less than 0.5 ft. penetration. Generally, measured penetration resistances exceeded 50 blows/ft. A granular soil of this average penetration resistance can be described as very compact.

- c. Grain size distribution curves of typical embankment samples are contained in Appendix E as Test Nos. 1, 4, 5 and 9. For the samples tested, the embankment materials consisted of 34 to 56% gravel, 31 to 39% sand, and 13 to 28% silt.
- d. As a result of the above visual descriptions and laboratory test results, the dam embankment materials would be classified as GM, SM, or SP soils according to the Unified Soils Classification System (USCS).

Fluvial Overbank Deposits

60. The fluvial overbank deposits consist of gray and brown, fine sandy SILT, little clay, to silty CLAY, with an occasional layer of silty fine SAND. Small amounts of organic material are also present. They occur immediately below the embankment material, and are the original near-surface soils of the valley bottom.

- a. The deposit was 11.0, 6.5, and 5.0 ft. thick in borings D82-101, D82-102, and D82-103, respectively.
- b. Penetration resistance values were generally obtained with a 1-3/8-in. I.D. by 2.0-in. O.D. standard split spoon driven by a 140-lb. safety hammer falling freely 30 inches. Standard penetration resistance values of 1.0 ft. of penetration ranged from 17 to 34, with an average of 24. A cohesive soil of this average penetration resistance can be described as stiff; a granular soil as medium compact.

- d. As a result of the above visual descriptions and laboratory test results, the deltaic deposits would be classified as GM, GW, SM, and SP soils according to the USCS.

Lacustrine Deposits

62. Lacustrine sediments underly the deltaic deposits. These sediments consist of red-brown, silty fine SAND, trace coarse to medium sand and fine gravel, to silty CLAY, trace coarse to fine sand, with occasional layers of coarse to fine SAND, little gravel, little silt.

- a. The lacustrine deposit was encountered in D82-102 from a depth of 120.5 to 154.0 ft. and in D82-103 from 101.5 to 181.0 ft. It was not encountered in D82-101. The deposit was 33.5 and 79.5 ft. thick in D82-102 and D82-103, respectively.
- b. Samples were recovered with a standard split spoon sampler. Standard penetration resistance values ranged from 32 to 128 blows/ft. with an average of 77 blows/ft. A granular soil with this average penetration resistance would be described as hard.
- c. Grain size distributions of representative samples of coarser portions of this deposit (silty fine SAND) are contained in Appendix E as Test Nos. 8, 12, and 13. These soils contained 60 to 72% fine sand and 28 to 40% silt. Atterberg Limits No. A-5 and hydrometer analysis H-5 reported in Appendix E were performed on a sample of silty clay soil recovered in D82-103 from the uppermost portion of the deposit. This sample had a natural water content of 13.6%, a plastic limit of 12.9%, and a liquid limit of 21.7%, and consisted of 10% sand, 30% silt, and 60% clay.
- d. As a result of the above visual descriptions and laboratory test results, the lacustrine deposits would be classified as SM, SP, ML, and CL soils according to the USCS.

Glacial Till

63. Glacial till underlies the lacustrine deposit. Descriptions of recovered samples range from gray, gravelly, coarse to fine SAND, little silt, to brown, fine sandy SILT, little coarse to medium sand and gravel. Numerous cobbles and boulders were indicated during casing advance and sampling.

- a. This deposit was penetrated 19.0 and 3.8 ft. by D82-102 and D82-103, respectively. These borings terminated within this deposit. Glacial till was not encountered in D82-101.
- b. Standard penetration resistance values ranged from 71 blows/ft. to refusal. A granular soil of this penetration resistance can be described as very compact.
- c. No grain size distributions of this deposit were obtained.
- d. As a result of the above visual descriptions, the glacial till would be described as SM, GM and GW soils according to the USCS.

Bedrock

64. Bedrock was encountered in only one test boring; D82-101 at a depth of 103.3 ft. Attempts to core the rock met with limited success due to bent casing at the bottom of the hole. A run of 1.9 ft. was made using a BXM double tube core barrel with 1.6 ft. of rock core recovered. The recovered rock core has been described as a dark gray, slightly weathered, moderately hard, dense to finely crystalline, flat-lying LIMESTONE, with a few stylolites. It has been identified as the Manlius Limestone, Olney Member.

Subsurface Water

65. At the time of the dam construction, a series of piezometers and settlement gages were installed. The settlement gages were constructed such that subsurface water level readings could also be obtained. Readings have been obtained at semi-regular intervals since the dam was constructed. These readings indicate a subsurface water level of approximately El. 460± to 465±, closely corresponding to the original ground surface. During the recent subsurface exploration program, regular water level observations were made during drilling operations and the water level in adjacent settlement gages was measured. These levels, noted on the subsurface profile on Figure 6, also correspond closely with the original ground surface.

Subsurface Profile

66. The subsurface conditions along the centerline of the dam are quite variable. The previous subsurface explorations reveal that the soils of the east and west dam abutments are deltaic deposits. These deltaic deposits form the terraces rising above the Onondaga Creek flood plain. However, the recent test borings along with the previous test borings show that, within the limits of the original flood plain beneath the dam, a deposit of fluvial overbank sediments overlie deltaic deposits, which in turn overlie lacustrine deposits. Glacial till and bedrock lie below the lacustrine deposits. The depths and thicknesses of these deposits vary from east to west.

- a. The silt and clay overbank deposits were encountered between test borings DH-6 and DH-2. The overbank sediments are approximately 5 to 13 ft. thick at test boring locations, within the flood plain, and pinch out to the east and west at the valley sides.
- b. Sand and gravel deltaic deposits underlie the overbank deposits in the central portion of the

dam and make up the east and west abutments. At the test boring locations, the deltaic sediments beneath the dam appear to vary in thickness from approximately 30 to 55 ft. This deposit thins to the east where the bedrock surface rises. The deltaic deposits of the west abutment consist of two units; a coarse-grained upper portion and a fine-grained lower portion. The deltaic deposits of the east abutment are predominantly granular and overlie bedrock.

- c. Underlying the deltaic deposit, along approximately the western one-half of the dam centerline, is a lacustrine deposit consisting of silt and fine sand. Based on test boring results, it appears the deposit thickens to 80 ft. and extends beneath the terrace at the west abutment. Towards the east it pinches out due to the rising bedrock surface.
- d. Underlying the lacustrine deposit, is a deposit of glacial till, a homogeneous mixture of silt, sand, and gravel. The top of the glacial till deposit slopes to the west as shown by the test borings and is probably closely underlain by bedrock.
- e. Test borings along approximately the eastern one-third of the dam and the east abutment encountered limestone bedrock immediately beneath the deltaic deposit. The bedrock surface appears to drop off sharply to the west, as rock was not encountered west of boring DH-2. It is H & A of New York's opinion that the rock cored in the bottom of DH-3 is a boulder in the till.

PART V: TECTONIC HISTORY

Orogenies

67. Orogenic events, or mountain building episodes, have not occurred per se in central New York. However, orogenies have occurred within and outside the state boundaries that have effected the depositional and structural history of the region.

The orogenic events are as follows:

- a. Taconic Orogeny - This is the earliest mountain building episode to strike the state and took place in the Late Ordovician and Early Silurian Periods (Table I). It resulted from compressive forces that became established as ancestral Africa and Europe began to move closer to ancestral North America. These compressive forces folded and thrust faulted the area of eastern New York and western New England forming the Taconic Mountains of New York, Berkshire Hills of Massachusetts, and the Green Mountains of Vermont. Streams flowing westward of this mountainous highland (sometimes called Vermontia) deposited a westward migrating delta or clastic wedge across the state. It is known as the Queenston Delta and the Queenston and Grimsby Formation represent the terrestrial uppermost portion of this delta.
- b. Acadian Orogeny - The Acadian Orogeny took place during Middle and Late Devonian times immediately after the deposition of the Onondaga Limestone. It continued into the succeeding Mississippian Period as well. The Acadian Orogeny struck the same general area as the earlier Taconic Orogeny. However, from the amount of clastic sediment shed from the highland area and other data, this orogeny was larger than the Taconic. It came about as a result of the collision of ancestral Africa and Europe with northeastern North America. This orogeny was the

climax of the Appalachian Mountains uplift in the north. Another delta of clastic wedge was shed westward off the Acadian Landmass known as the Catskill Delta. It begins with the clastic sedimentation of the Hamilton Group and continues into the Upper Devonian (Table II). By the end of the Devonian Period this delta had prograded westward across the entire state or nearly so.

- c. Appalachian Orogeny - This orogeny struck mostly the southern Appalachian chain as ancestral Africa rotated to collide with southeastern North America. This took place primarily during the Late Paleozoic Era, the Pennsylvanian and Permian Periods. The effect on central New York from this orogeny was to impart to the strata a dip of 40 to 50 feet per mile to the south. In addition, the joint system was formed at this time as well as the minor faults and folds discussed below.
- d. Mesozoic Events - After the Appalachian Orogeny the present Atlantic began to open as Europe and Africa rifted from North America and drifted gradually eastward. Tensional forces resulting from this breakup formed the downfaulted Triassic Lowland Province of southeastern New York (Figure 2). In addition, upward migrating magmas formed the Palisades Sill of the Hudson and also may have been responsible for the many small dikes that occur throughout central New York. These dikes are shown on Figure 3, and discussed below.

Structural Deformation

68. Superimposed on the regional dip approximately $1/2^{\circ}$ to the south are local folds, consisting of low amplitude anticlines and synclines, and faults of low displacement.

Folds

69. A broad anticline and syncline is exposed in the Chittenango Member of the Marcellus Formation on the east side of N.Y. Route 173 just south of its intersection with Slate Hill Road, south of Marcellus.

70. Along the east side of Interstate 81, south of the junction of Interstate 481, there are a series of gentle anticlines and synclines. The height of these folds is approximately 30 feet. They are a few hundred feet wide and expose the Manlius Formation (Olney, Elmwood, Clark Reservations and Jamesville Members).

71. A gentle anticline is exposed in the spillway cut at the dam. The Manlius-Onondaga contact rises to a maximum of 12 feet above the floor of the valley from the spillway northward, then descends further northward such that it is near creek level at the northern extremity of the exposure.

72. A monocline in the Onondaga Limestone is exposed on the south side of the Seneca Turnpike (NY Route 173) at Fillmore Corner, which is at the intersection of Sweet Road, about 2.5 miles east of Jamesville. The Onondaga is horizontal on each side of the monocline but is bent nearly vertical within the structure. The Onondaga is some 23 feet lower on the downside of the monocline. Outside of the Onondaga Valley region, a broad anticline is exposed along Cayuga Lake north of Ithaca, known as the Portland Point anticline.

73. The folds in the Syracuse and Central New York region are related either to mild compression as a result of the Appalachian Orogeny or to removal of salt and gypsum in the Salina and Bertie Groups due to migrating ground water. Thus some of the smaller folds may be subsidence structures and not uplift structures formed by compression.

Faults

74. A number of small faults occur in the Syracuse - Central New York region as revealed by a search of the literature augmented by field work. All of these are small in lateral extent and displacement or offset. Further, they strike approximately N70°W, dip mainly southward, are mostly thrust faults that form due to compression, and therefore, are probably Late Paleozoic Appalachian Orogeny structures (approximately 220 million years old). Overlying glacial deposits are not offset indicating that no motion has taken place on these faults at least since the last retreat of the ice, approximately 14,000 years ago.

75. A small thrust fault of 3 feet vertical displacement occurs in the Old Malley quarries south of Marcellus and a few hundred yards north of the anticline described above in the Chittenango Shale Member. The fault cuts the Onondaga Limestone.

76. A thrust fault, with a throw of about 5 feet, in the Onondaga Limestone and extending into the overlying Union Springs Member can be seen in the drainage ditch on the east side of U.S. Route 11, south of the Nedrow interchange to Interstate 81 at the intersection of Kennedy-Camping Road. The Union Springs Shale Member is highly contorted and tightly folded, apparently absorbing the fault motion. This fault is the closest thrust fault to the dam, a distance of approximately 2.5 miles, and cannot be traced beyond this one exposure.

77. A thrust fault in the Jamesville Quarry on the east side of the Butternut Creek Valley, north of Jamesville, has a vertical displacement of 16.5 feet in the Onondaga Limestone. This structure probably grades eastward into the monocline described above, exposed at Fillmore Corner.

78. One of the largest faults in the Syracuse area formerly was exposed in the old Russell's Quarry, now buried near the junction of N.Y. 173 and LaFayette Road in the southeast corner of the Syracuse West quadrangle. The fault plane dips south 20° and displaces the Manlius and Onondaga limestones 42 feet. South of Jamesville, on the east side of the Butternut Creek Valley, in the Onondaga County Penitentiary Quarry, a thrust fault of about 31 feet may be the same fault as the one

formerly exposed in Russell's Quarry. If so, the fault is approximately 3.5 miles long parallel to strike.

79. Four small thrust faults with throws of 2 to 4 feet cut the Bertie Group in the Fiddlers Green Gorge at Jamesville. Three thrust faults of comparable strike, dip, and displacement to those described above have been discovered on the Manlius Quadrangle to the east.

80. A series of small normal faults, down thrown to the north, can be seen along the southwest side of the Tully Valley in Lords Hill Ravine and Cass Hill Ravine, south (upstream) of U.S. Route 20, having a total displacement of approximately 45 feet. The fault planes strike N60°W, and are nearly vertical. The Staghorn Point and Joshua Submembers are cut by the faults.

81. The unusual thickness of the Pompey Member in Bare Mountain Ravine may also be due to normal faulting, but the lack of outstanding key beds makes this hypothesis difficult to test.

Joints

82. The joint system in the Syracuse region contains two main sets, one nearly north-south and the other nearly east-west. Most of the joints in these sets are vertical or nearly so. Two minor sets that strike northeast and northwest are also present.

83. Inclined joints that strike about N70° to 75°W and dip 30° to 80° either north or south are locally developed in the limestones in the Syracuse area. Some of the inclined joints are continuous for many tens of feet while others are limited to a single bed or group of beds and end against a shaly parting. They are well developed in parts of the Manlius Formation such as the Clark Reservation Limestone Member and the Onondaga Limestone, especially the Nedrow Member.

Dikes

84. In central New York, small dikes from a few inches to a few feet wide occupy the North-South joint set. They are composed of kimberlite

and alnoite, a high temperature, ultra-basic, igneous rock, high in iron and magnesium silicates and low in aluminum silicates such as potash feldspars.

85. One dike occurs in North Syracuse near Schiller Park, one at the DeWitt Reservoir 3 miles east of Syracuse, and another near Otisco Lake, 15 miles southwest of Syracuse. A relatively large number are exposed in Ithaca and on both sides of Cayuga Lake north of Ithaca to Taughannock Falls State Park.

PART VI: EARTHQUAKE ACTIVITY

Historic Earthquakes

86. More than 330 earthquakes with a maximum Modified Mercalli Intensity (I_o) greater than II are known to have occurred in New York State between 1720 and 1980 (Mitronovas, 1981). Figure 7 is a seismicity map for the northeast U.S. and adjacent Canada, showing all known historical and recorded events of maximum intensity greater than or equal to III for the time period 1534 to 1977. Figure 7A is a seismic zone map for the contiguous United States and Puerto Rico with the corresponding location of the dam site. An abbreviated form of the Modified Mercalli scale is shown on Figure 8, along with approximate relationships between intensity, Richter magnitude, and peak horizontal ground acceleration.

87. All earthquakes with a maximum intensity greater than or equal to IV that have occurred within 200 kilometers of the Onondaga site are listed in Table IV in order of decreasing epicentral intensity.

Geographic Distribution of Earthquakes

88. As discussed by Mitronovas (1981) and shown on Figure 9, New York State can be subdivided into three areas of relatively high seismic activity, separated by a large area of very low or no activity in the center of the State (which includes the Onondaga Dam site). These regions were designated A, B, C, and D by Mitronovas. Over 90 percent of all seismic events, and all events of maximum intensity greater than V, fall into regions A, B, and C, which have a combined area of less than 60 percent of that of the State. Table V gives a chronological list of earthquakes within New York State of maximum intensity VI or greater. The following discussions of the seismicity of the four regions of New York State are taken from Mitronovas (1981).

89. Region A is an area of moderate seismic activity. It contains the Ramapo fault system, which has been associated with recent seismic activity. One of the earliest documented large earthquakes in New York (I_o = VII) occurred in Region A near New York City on 18 or 19 December 1737.

90. The Adirondack area, region B, is the most seismically active region of the state. It is part of a larger seismic area which trends northwest-southeast and extends well into Canada. There is evidence that the Adirondacks are undergoing doming, or upward movement (Isachsen, 1975). The doming may be linked to the seismic activity of the area, but this is not known for certain. The largest known earthquake within New York State ($I_o = VIII$) occurred in this region near Massena, New York on 5 September 1944.

91. The number of known earthquakes within region C is smaller than in either of regions A or B. However, one of the two largest earthquakes in the state, near Attica, occurred in region C on 12 August 1928. The general location of this event suggests that it was associated with the southern end of the Clarendon-Linden fault system. Past and present seismicity of region C is not restricted to this fault system alone, however.

92. The central part of the state, region D, has very little seismic activity, both at present and historically. This large aseismic area separates the seismically active areas of the state into three distinct regions.

93. The available data (Mitronovas, 1981) indicates secular variation, or periodicity over time, in seismic activity in New York since 1920. Periods of greater activity, in terms of total number of events per unit of time, between 1760 and 1790, 1830 and 1880, and 1910 through the present, are separated by periods of less activity between 1790 and 1830 and 1880 and 1910. An increase since 1910 is consistent with the improvement in detection capability. Chiburis (1981) has indicated that the Adirondack region has exhibited a decreased seismic activity since 1925. The reasons for time-dependent seismicity in the northeast U.S. are not known.

PART VII: EVALUATION FOR ACTIVE FAULTS

94. Earlier sections of this report have established that mapped faults in the site vicinity are ancient ones which date back to the Appalachian Orogeny of Late Paleozoic time (over 220 million years ago). Glacial overburden and urban construction have made it all but impossible to trace faults for any great distances. The evidence indicates that all the faults are inactive at the present time and are small local occurrences of limited extent.

Assocation of Earthquakes with Tectonism and Faults

95. The earthquake distribution in New York State bears little or no proven relationship to known active or inactive faults. In region A, there is some activity that corresponds to the Ramapo fault system, but not all activity is confined to this system. In region B, the relationship to known faults or other tectonic features is not clear. The correlation between epicenters and known surface faults or other brittle structures still remains to be determined. In region C, the past and present seismicity is not restricted to the Clarendon-Linden fault system alone. Indeed, although the seismicity extends both east and west of the fault system, it does not extend northward along the fault system, which is known to extend into Lake Ontario. The relationship of most of the epicenters in region C to tectonic structures is, as in region B, not yet known.

96. The Attica seismic region (region C) has produced several events for which some possible fault types and orientations have been obtained, based on seismological data. Hermann (1978) determined similar focal mechanisms for both the 1 January 1966 and 13 June 1967 events. A plane striking NNE parallels the trend of the Clarendon-Linden fault structure. If this is indeed the fault plane, then the motion along this plane has approximately equal components of right-lateral strike slip and reverse

faulting. Composite fault-plane solutions obtained by Fletcher and Sykes (1977) for Attica events between 1972 and 1975 have one plane also oriented NNE, but their solution indicates predominantly reverse faulting.

Lineations

97. Lineations or linear features, are those that are found in tonal changes in satellite imagery, and in the alignment of rivers, terrace boundaries, etc. They may be the result of a multitude of causes and may be unrelated to faults.

98. The Brittle Structures Map of New York State, compiled by Isachsen & McKendree (1977) was reviewed to note locations of any lineations in the site vicinity. Several lineations were noted. An attempt was made to check these in the field but nothing could be discerned. They appear to be unrelated to faults but may be due to jointing or glacial erosion and deposition. None of the faults or linears show any evidence of activity in the area of the project.

PART VIII: INTENSITY OF EARTHQUAKE SHAKING AT ONONDAGA DAM

Earthquake Intensities and Attenuation

99. All earthquakes with a maximum intensity greater than or equal to IV that have occurred within 200 kilometers (km) of the site are shown in Table IV. Because larger earthquakes at distances greater than 200 km may produce significant site intensities, all 2705 events in the Chiburis (1981) earthquake catalog have been attenuated to the Onondaga site. The attenuation relation used was that of Cornell and Merz (1975):

$$I = I_0 + 3.211 - 1.3 \ln (\text{distance in km})$$

100. Table VI shows the specific events which produce site intensities greater than or equal to IV when attenuated to the site.

101. As the data clearly show, the maximum shaking intensity experienced at the Onondaga Dam site has been IV to V. (Intensities noted in Table VI are in arabic numerals because of fractional values). The peak horizontal ground acceleration was therefore in the range of 1 to 3 percent of the acceleration due to gravity (0.01g to 0.03g). The event that produced the highest intensity at the site was the 1663 La Malbaie earthquake ($I_0 = X$) at a distance of about 700 km from the site. Because of the early occurrence at this event, the assigned intensity of X, based on historical accounts (written or otherwise) is at best only an estimate. Of more concern would be the Attica and Massena earthquakes, recorded in 1929 and 1944, at distances of 180 km and 250 km from the site, respectively. The magnitude of the Massena event was reported to be 5.9, whereas the magnitude of the Attica event was estimated from historical records to range from 5.5 to 5.9 (Chiburis, 1981). However, the attenuated intensities at the dam are still only on the order of IV. A possible faulting mechanism for the Attica region was discussed earlier in this report (para. 96).

102. Isoseismals from the 1 March 1925 intensity IX event centered in La Malbaie, Quebec are shown in Figure 10. This event resulted in

intensity IV shaking at the site, and would have caused rattling of dishes and windows and disturbance of doors and cars near the site. The reduction in five levels of intensity from La Malbaie to central New York for the 1925 event is consistent with the attenuation of the 1663 La Malbaie earthquake discussed in the previous paragraph.

103. It is concluded that earthquakes with epicentral intensity greater than IV will not have epicenters near the Onondaga site. The nearest regions of concern are the Attica and Massena regions, which may produce intensities of IV to V at the site. The focal mechanism of the Attica region is most probably reverse or thrust faulting with north-easterly trending fault planes.

Frequency of Earthquake Occurrence and Seismic Risk

104. A seismic risk analysis was performed to aid in the selection of a level of earthquake shaking for use in assessing the seismic stability of Onondaga dam. The analysis was used to estimate the probability of exceeding various levels of earthquake shaking within a specified time period. These calculated probabilities allow for selection of an "analysis" earthquake that is consistent in terms of seismic risk with other similar structures.

105. The procedure used to calculate the probability of exceedence of specific levels of earthquake shaking at the site was to first divide the northeastern United States and adjacent areas into more than 50 zones or potential sources of seismic activity. Each zone has its own assigned level of seismic activity based on historical seismicity. The zones are quadrilateral in shape and are based on the regionalization given in Chiburis (1981). It is assumed that the locations of potential earthquake point sources (epicenters) are randomly distributed with each zone. In addition to the specific zones, a low-level "background" seismicity was assumed, randomly distributed over the entire northeast area. This allows for the possibility of earthquakes occurring at any location, not just in zones where historic seismicity is relatively concentrated.

106. The probability of occurrence of intensity $i \geq I_1$ shaking at the site was calculated based on the "Total Probability Theorem" as

$$P(i \geq I_1) = \sum_{\text{all source zones}} \sum_m P(i \geq I_1 | m) P(m)$$

in which:

$P(i \geq I_1)$ denotes the probability of the occurrence of intensity $i \geq I_1$ at the site;

$P(m)$ denotes the probability of occurrence of an earthquake of magnitude m or greater in a source zone;

$P(i \geq I_1 | m)$ denotes the probability of occurrence of intensity $i \geq I_1$ at site given the occurrence of a magnitude m event in the source zone.

107. The probability calculations were performed on a computer using a program developed by McGuire (1977). The procedures used to calculate the needed parameters for each zone are described in the following two paragraphs.

108. The probability of occurrence of an earthquake of magnitude m or greater within a source zone, $P(m)$, is determined from the assigned recurrence relationship for each zone. The recurrence relationship is of the form:

$$\log N = A - Bm$$

in which N is the average number of events per year of magnitude m or greater for each specific source zone, and A and B are constants for the zone. The probability of occurrence of an earthquake of magnitude m or greater is determined by numerical integration of the above recurrence relationship for each zone. The "B" parameter was assumed to be equal for all zones except La Malbaie, which exhibits much more seismic activity than other areas in the northeast. The "A" parameter was determined from historical seismic activity for each zone.

109. The probability of intensity i shaking at the site given a magnitude m event in a source zone, $P(i \geq I_1 | m)$, is related to the attenuation relationship for the site area. Attenuation is assumed to follow a normal probability distribution. The mean value of the distribution was based on Cornell and Merz (1975) as presented in paragraph 99. Chiburis (1979) compared the Cornell and Merz relationship to observed attenuation for six northeastern events, as shown on Figure 11. The relationship compares well with the observed data in the near and far fields, although it is not as good in the intermediate range. To account for the variability in the observed attenuation in the analysis, a standard deviation of 0.4 was assumed. This is more conservative than the 0.2 value used by Cornell and Merz.

110. The probability of exceedence results calculated with the computer program are based on a one-year time period. The probability of exceedence of a specified intensity I_1 in T years can be calculated from the following:

$$P(i \geq I_1) = 1 - e^{-\lambda T}$$

in which λ is the mean number of events per year of intensity I_1 . For the levels of seismic risk considered herein, λ is also equal to the probability of exceedence of intensity I_1 in one year.

111. Figure 12 depicts the results of the analysis, that is, the probability that specified earthquake intensities and corresponding peak horizontal ground accelerations will be exceeded at the site in a 50-year period. Intensity was converted to peak horizontal ground acceleration in rock using the relationship shown on Figure 8. The following is a brief summary of selected results:

PEAK HORIZONTAL GROUND ACCELERATION IN ROCK	INTENSITY	PROBABILITY OF EXCEEDENCE IN 50 YEARS
0.02g	V	7.0%
0.05g	VI	1.0%
0.10g	VII	0.8%

On the average, intensity V, VI and VII shaking would be expected to recur at the site every 650, 4,400 and 65,000 years, respectively.

PART IX: ASSESSMENT OF EARTHQUAKE EFFECTS ON ONONDAGA DAM

112. Based on the results of the seismic risk analysis and current engineering practice, the peak horizontal ground accelerations in rock recommended for use in assessing the seismic stability of the Onondaga Dam is 0.05g. This acceleration corresponds to an intensity of shaking of VI, which is one intensity level higher than the site is known to have experienced historically. The probability that this level of shaking would be exceeded in a 50-year period is 1.0 percent based on the analysis performed.

113. The duration of strong motion in an earthquake is often defined as the time interval between the times that a 0.05g acceleration is first and last achieved. This definition would result in a duration of zero for Onondaga Dam. Nuttli (1979) has defined duration as the time interval between the times that one-half the "sustained maximum" (third highest acceleration peak) acceleration is first and last achieved. This definition leads to longer durations for small earthquakes. Using this definition of duration and considering that the epicenter of the causative earthquake is likely to be more than 100 km from the site, the recommended duration of shaking is approximately 30 seconds.

114. The recommended level of earthquake shaking could only cause embankment or spillway instability, if a marginal static stability condition exists for either the embankment dam or concrete spillway. Based on the calculations presented in the U.S. Engineer Office Design Analysis for the dam (Ref. 17), the static stability of the embankment and spillway appears adequate. Significant settlement or liquefaction of foundation soils could only occur if the foundation soils are cohesionless and very loose to loose in relative density. In addition, for liquefaction to occur, the foundation soils must be saturated. The logs of the design phase (1945) borings indicate that foundation soils at the dam are predominantly compact to very compact, saturated cohesionless soils, but the criteria used to evaluate the relative density

of the soils is not known. No penetration test results or quantitative data of any kind were available. The recent test borings were undertaken as part of this study in order to provide such data. Engineering studies relative to the seismic stability of the dam were then performed using the data obtained from the borings.

115. The subsurface conditions along the dam centerline are shown on Figure 6 and have been summarized in paragraphs 57 to 66. As noted in paragraph 65, subsurface water levels are generally between El. 460 to 465.

116. A plot of Standard Penetration Resistance (N-value) versus sample depth below the top of the embankment for the recent test borings is provided in Figure 13. N-values obtained by means of standard methods, 1-3/8 in. I.D. 2.0-in. O.D. split spoon driven by a 140-lb. hammer free falling 30 inches, are shown on the plot without correction. N-values obtained by means of the large split spoon, 2.875-in. I.D. 3.5-in. O.D. driven by a 350-lb. hammer free falling 18 inches, have been converted to standard values for use on the plot. The conversion has been made on the basis of sampler-hammer ratios which take into account sampler size, hammer weight, and drop height by the following equations:

$$R_s = (D_o^3 - D_i^3)/WH \text{ (144) ft.}^2/\text{lb. for granular soils}$$
$$R_s = (D_o^2 - D_i^2)/WH \text{ (12) ft./lb. for cohesive soils}$$

where;

R_s = Sampler - Hammer Ratio

D_o = Outside Diameter of Sampler (in.)

D_i = Inside Diameter of Sampler Shoe (in.)

W = Weight of Hammer (lb.)

H = Height of Drop (in.)

Calculations of the sampler-hammer ratios and the conversion charts used are contained in Appendix F.

117. In addition, projected N-values have been used for samples which encountered refusal before reaching the required one foot of

penetration. In these cases the recorded penetration resistance values were projected by direct proportion to the one foot standard for use on the plot.

118. The liquefaction potential of the saturated cohesionless foundation soils was analyzed in accordance with the methodology of Seed and Idriss (1981). The calculations performed for the assessment of liquefaction potential are provided in Appendix F. A summary of the analytical procedure is as follows:

1. Calculate the effective ($\bar{\sigma}_{v_0}$) and total (σ_{v_0}) overburden pressures below the crest and toe of the dam.
2. Calculate the seismic shear stresses (τ) imposed by the earthquake on the foundation soils and obtain the seismic shear stress ratio, $\tau / \bar{\sigma}_{v_0}$, as a function of depth below the toe and crest of dam.
3. Correct Standard Penetration Resistance values to N_1 values, the N -value at an effective overburden pressure of one ton per sq. ft. (tsf.)
4. Plot $\tau / \bar{\sigma}_{v_0}$ versus N_1 and compare to data obtained from previous earthquakes for known cases of liquefaction and nonliquefaction.

119. To determine the seismic shear stress as a function of depth, it is necessary to estimate the amplification of the bedrock earthquake motions as caused by the presence of the overburden soils. The amplification by the dense soils at the site was estimated by taking the ratio of the response spectra peak for "stiff" soil conditions to the peak for "rock", for the spectra shown on Figure 14. The ratio of the "stiff" soil peak to the "rock" peak was 1.16. An amplification factor of 1.2 was assumed in the analysis, resulting in a peak horizontal ground acceleration of 0.06g at the natural ground surface.

120. The results of the liquefaction analysis are shown on Figures 15 and 15A, which shows the plot of $\tau / \bar{\sigma}_{v_0}$ versus N_1 for the dam foundation soils. The figures show that even the lowest N_1 values obtained at the site lie

to the "safe" side of the boundary line separating regions of observed liquefaction from nonliquefaction. Therefore, liquefaction of the foundation soils is not believed to be possible under the recommended levels of earthquake shaking.

121. It should be noted that the N_1 range shown on Figures 15 and 15A is the range of the lowest N_1 values encountered at the site. The average N_1 for the foundation soils would be significantly greater than the highest end of the range shown.

122. The embankment soils were disclosed by the borings to be medium compact to very compact, as noted earlier. In addition, these soils were found to be partially saturated. The results of the foregoing analyses provide a basis for concluding that the embankment soils would not be liquefaction-susceptible for the recommended level of shaking if they were to become saturated due to an impoundment.

PART X: CONCLUSIONS

123. The Onondaga Dam is located in a region of exposed gentle, southerly sloping Lower and Middle Devonian limestones and shales of the Helderberg Group, Onondaga Limestone and Hamilton Group. Superimposed on the dip are some minor, small faults and folds of Late Paleozoic age. Therefore, the dam is situated in an area that is structurally simple and tectonically stable.

124. The region has been glaciated, and the valley in which the dam is located is a U-shaped glacial trough. Upon retreat of the ice, large, hanging delta terraces of sand and gravel were deposited in the valley in a gradually receding proglacial lake that escaped eastward through meltwater channels.

125. The dam is located in an area that historically can be described as nearly aseismic. The intensity of ground shaking recommended for use in assessing the seismic stability of the dam and its foundations is VI, with a corresponding peak horizontal ground acceleration of 0.05g in rock and 0.06g at the surface of natural ground where the dam overlies soil deposits. The average length of time between occurrences of this degree of shaking at the site is 4,400 years, based on probability analyses. The calculated probability that the above intensity will be exceeded at the site in a 50-year period is 1.0 percent. Possible sources of earthquakes which might produce this degree of shaking are the Attica and Massena, New York areas and the La Malbaie, Quebec area.

126. To obtain qualitative and quantitative data for use in the assessment of the stability of the dam under earthquake shaking, three test borings were drilled from the crest of the embankment into the foundation soils as a part of this study.

127. The approximately 65-ft. high embankment consists of medium compact to very compact sands and gravels that were not saturated at the time of this study. Immediately below the embankment is a relatively thin layer of saturated, stiff to hard, clayey silt and silty clay.

Below this layer, foundation soils consist primarily of saturated, medium compact to very compact sand with varying amounts of gravel and silt, to a depth of approximately 35 to 65 ft. below the base of the dam. Below this granular deposit is a medium compact to very compact fine grained deposit of variable thickness overlying glacial till. On the east side, bedrock is relatively close to the bottom of the embankment.

128. The static stability of the embankment and foundation soils is adequate based on the type and relative density of the soils present and the geometry of the dam. Likewise, the stability of the concrete spillway, which bears on rock, also appears to be adequate.

129. The liquefaction susceptibility of the soils at the site was analyzed for an earthquake producing 0.06g peak acceleration at the surface of natural ground. The embankment and foundation soils are not considered to be susceptible to liquefaction for this level of earthquake shaking. Minor seismically-induced settlement of the embankment and subsoils may occur, but the settlement will not be detrimental to the performance of the structure.

130. As a result of the analyses conducted, it is the opinion of H & A of New York that a more in-depth analysis of the stability of the dam due to liquefaction or other earthquake effects is not warranted. ✓

REFERENCES

1. Applied Technology Council, "Tentative Provisions for the Development of Seismic Regulations for Buildings," ATC Publication ATC 3-06, 1978.
2. Chiburis, E.F., "Seismicity, Recurrence Rates, and Regionalization of the Northeastern United States and Adjacent Southeastern Canada," U.S. Nuclear Regulatory Commission, NUREG/cr-2309 RA, R6, 1981.
3. Chiburis, E.F., Ahner, R.O., and Graham, T., "Seismicity of the Northeastern United States," Northeastern U.S. Seismic Network Bulletins, Weston Observatory, Boston College, 1979.
4. Cornell, A. and Merz, H., "Seismic Risk Analysis of Boston," Jour. Struc. Div. Proc. Am. Soc. Civil Engineers, V. 101, No. St 10, 1975, pp. 2027-2043.
5. Fletcher, D.B. and Sykes, L.R., "Earthquakes Related to Hydraulic Mining and Natural Seismic Activity in Western New York State," J. Geophys. Res., V. 82, 1977, pp. 3767-3780.
6. Hermann, R.B., "A Seismological Study of Two Attica, New York, Earthquakes," Bull. Seism. Soc. Am., V. 68, No. 3, 1978, pp. 641-652.
7. Hutchinson, D.R., Pomeroy, P.W., Wold, R.J., and Hallis, H.C., "Geophysical Investigations Concerning the Continuation of the Clarendon Linden Fault Across Lake Ontario," Geology, V. 7, No. 4, 1979, pp. 206-210.
8. Isachsen, Y.W., "Possible Evidence For Contemporary Doming of the Adirondack Mountains, New York, and Suggested Implications For Regional Tectonics and Seismicity," Tectonophysics, V. 29, 1975, pp. 169-181.
9. Isachsen, Y.W., and McKendree, W.G., "Preliminary Brittle Structures Map of New York," New York State Museum Map and Chart Series No. 31B, 1977.
10. Krinitzky, E.L., and Patrick, D.M., "Earthquake Investigations at the Dickey-Lincoln School Damsites, Maine," U.S. Army Engineer Division, New England, Miscellaneous Paper S-77-2, Final Report, 1977.
11. McGuire, R.K., "FORTRAN Computer Program For Seismic Risk Analysis," U.S. Dept. of Interior, U.S. Geological Survey, Open File Report 76-77, 1977.

REFERENCES (continued)

12. Mitronovas, W., "Earthquake Statistics in New York State." In Press, 1981.
13. Nuttli, O.W., "The Relation of Sustained Maximum Ground Acceleration and Velocity of Earthquake Intensity and Magnitude," State-of the Art for Assessing Earthquake Hazards in the United States, Report 16, Misc. Paper S-73-1, U.S. Army Engineers W.E.S., Vicksburg, Miss., 1979.
14. Oliver, W.A., Jr., "Middle Devonian Coral Beds of Central New York," Amer. Jour. Sci., V. 249, No. 10, 1951, pp. 705-728.
15. Seed, H.B. and Indriss, I.M., "Evaluation of Liquefaction Potential of Sand Deposits Based on Observations of Performance in Previous Earthquakes," In Situ Testing to Evaluate Liquefaction Susceptibility, ASCE Preprint 81-544, ASCE National Convention, St. Louis, MO, 1981.
16. U.S. Atomic Energy Commission, "Nuclear Reactors and Earthquakes," TID-7024, Chapter 1, 1963, pp. 13-14.
17. U.S. Engineer Office, Syracuse District, "Design Analysis for Onondaga Reservoir, Onondaga Creek, New York," Oswego River Watershed Flood Control, 1945.
18. U.S. Engineer Office, Syracuse District, "Plans for Onondaga Dam, Onondaga Creek, Syracuse, New York," Oswego River Watershed Flood Control Project, 1947.

ONONDAGA DAM, NEW YORK

TABLES

U. S. Army Engineer District, Buffalo
1776 Niagara Street
Buffalo, New York 14207

TABLE I
GEOLOGIC TIME SCALE

TIME BEFORE PRESENT (MILLIONS OF YEARS)				
ERA	PERIOD	EPOCH	BEGINNING	DURATION
CENOZOIC	Quaternary	Holocene (recent)	0.01	
		Pleistocene	3 ⁺	2.99
	Tertiary	Pliocene	5	2 ⁺
		Miocene	25	20
		Oligocene	34	9
		Eocene	49	15
		Paleocene	64	15
MESOZOIC	Cretaceous		130	66
	Jurassic		180	50
	Triassic		220	40
PALEOZOIC	Permian		270	50
	Pennsylvanian		325	55
	Mississippian		355	30
	Devonian		410	55
	Silurian		430	20
	Ordovician		500	70
PRECAMBRIAN	Cambrian		600	100
	FORMATION OF THE EARTH			4,600

NOTE: Table derived from various geologic sources.

TABLE I

TABLE II
GENERALIZED STRATIGRAPHIC COLUMN - CENTRAL NEW YORK

TABLE II
GENERALIZED STRATIGRAPHIC COLUMN - CENTRAL NEW YORK

				APPROXIMATE THICKNESS IN FEET
	SYSTEM	SERIES	GROUP	FORMATION
DEVONIAN	Upper Devonian	Chautauquan	Conewango	
			Conneaut	
	Devonian	Senecan	Canadaway	(Many formations recognized in each group)
			West Falls	3000
	Middle Devonian	Erian	Sonyea	2600
			Genesee	670 to 800
	Lower Devonian	Ulsterian		900 to 1450
			Tully Ls.	15 to 100
	Silurian		Hamilton	Moscow .
				Ludlowville
SILURIAN	Upper Silurian	Cayugan	Skaneateles	160 to 240
			Marcellus	300
	Silurian		Onondaga Ls.	300 to 500
			Oriskany Ss.	100 to 500
	Middle Silurian	Niagaran	Helderberg	Onondaga Ls.
			Tristates	70 to 100
	Lower Silurian	Albion	Manlius Ls.	0 to 10
			Chrysler Dol.	200
	Upper Ordovician		Chrysler Dol.	15
			Cobleskill Ls.	10

TABLE II

TABLE III

DETAILED DEVONIAN STRATIGRAPHIC COLUMN
SYRACUSE MERIDIAN - ONONDAGA DAM VICINITY

SYSTEM	SERIES	GROUP	FORMATION	MEMBER	APPROXIMATE THICKNESS IN FEET
Upper Devonian	Senecan		Tully Ls.		30
Middle Devonian	Erian	Hamilton	Moscow	Windom Sh.	165
				Portland Point Ls.	12
			Ludlowville	Owasco Ss.	2
				Spafford Sh.	27
				Ivy Point Ss.	37
			Skaneateles	Otisco Sh.	209
				Centerfield Ls. & Ss	25
			Marcellus	Butternut Sh.	135
				Pompey Sh. & Siltst.	60
				Delphi Station Sh. & Siltst.	125
				Mottville Ls. & Sh.	6
Lower Devonian	Ulsterian	Helderberg	Onondaga Limestone	Cardiff Sh.	180
				Chittenango Bl. Sh.	80
				Cherry Valley Ls.	3
				Union Springs Bl. Sh.	12
				Seneca Ls.	25
			Tristates	Tioga Bentonite	.4
				Moorehouse Ls*	25
				Nedrow Ls*	10
			Manlius	Edgecliff Ls*	15
				Oriskany Ss*	0 to .2
				Jamesville Ls*	25
			Rondout	Clark Reserv. Ls.	5
				Elmwood Dol.	10
				Olney Ls.	30
				Chrysler Dol	30

* = Exposed in spillway of dam.

TABLE III

TABLE IV
EARTHQUAKES WITHIN 200 KM OF ONONDAGA DAM SITE

<u>Year</u>	<u>Date</u>	<u>Location</u>	<u>Maximum*</u>	<u>Richter</u>	<u>Magnitude</u>	<u>Location</u>
		<u>Lat(N)</u>	<u>Long(W)</u>	<u>Intensity</u>		
1929	Aug. 12	42.9	78.4	VIII	5.8	Attica, NY
1954	Feb. 21	41.2	75.9	VII		Wilkes-Barre, PA
1840	Jan. 16	43.0	75.0	VI		Herkimer, NY
1853	Mar. 12	43.7	75.5	VI		Lowville, NY
1857	Oct. 23	43.2	78.6	VI		Buffalo, NY
1954	Feb. 24	41.2	75.9	VI		Wilkes-Barre, PA
1966	Jan. 1	42.8	78.2	VI	4.7	Attica, NY
1966	Jun. 13	42.9	78.2	VI	3.9	Attica, NY
1916	Feb. 2	42.9	74.0	V		Mohawk Valley, NY
1916	Feb. 3	43.0	74.0	V		Mohawk Valley, NY
1922	Dec. 8	44.4	75.1	V		S. of Canton, NY
1929	Dec. 2	42.8	78.3	V		Attica, NY
1952	Aug. 25	43.0	74.5	V		Johnstown, NY
1955	Jan. 21	43.0	73.8	V		Malta, NY
1955	Aug. 16	42.9	78.3	V		Attica, NY
1971	May 23	43.8	74.5	V	3.9	Blue Mt. Lake, NY
1971	May 23	43.9	74.5	V	3.6	Blue Mt. Lake, NY
1971	Jul. 10	43.9	74.5	V	3.4	Blue Mt. Lake, NY
1907	Jan. 24	42.8	74.0	IV		Schenectady, NY
1927	Mar. 14	44.6	75.4	IV		Canton, NY
1929	Dec. 3	42.8	78.3	IV		Attica, NY
1933	Oct. 29	43.0	74.7	IV		St. Johnsville, NY
1946	Oct. 28	41.5	76.6	IV	3.6	LaPorte, PA
1946	Nov. 10	42.9	77.5	IV	3.1	Canandaigua, NY
1950	Mar. 20	41.5	75.8	IV	3.3	NW of Scranton, PA
1954	Jan. 31	42.9	77.3	IV		Canandaigua, NY
1954	Feb. 1	43.0	76.7	IV	3.3	Montezuma, NY
1958	May 6	42.7	73.8	IV		Albany, NY
1960	Jan. 22	41.5	75.5	IV	3.4	Carbondale, PA
1963	Mar. 2	41.5	75.7	IV	3.4	Scranton, PA
1963	Jul. 2	42.6	73.8	IV	3.3	Albany, NY
1965	Jul. 16	43.0	78.1	IV	3.2	Attica, NY
1965	Aug. 27	43.0	78.1	IV	3.1	Attica, NY
1969	Aug. 13	43.3	78.2	IV	2.8	Albion, NY
1971	Jun. 21	43.9	74.5	IV	3.3	Blue Mt. Lake, NY
1973	Jul. 15	43.9	74.4	IV	3.4	Blue Mt. Lake, NY
1973	Jul. 15	43.9	74.4	IV	3.2	Blue Mt. Lake, NY
1973	Jul. 16	43.8	74.5	IV	3.3	Blue Mt. Lake, NY
1975	Nov. 3	43.9	74.6	IV	3.9	Raquette Lake, NY

* Modified Mercalli Intensity

Ref.: Chiburis (1981)

TABLE V
CHRONOLOGICAL LIST OF SIGNIFICANT ($I_o \geq VI$) EARTHQUAKES WITHIN NEW YORK

<u>Year</u>	<u>Date</u>	<u>Location</u>		<u>Region</u> ⁽¹⁾	<u>I_o</u> ⁽²⁾	<u>M</u> ⁽³⁾
		<u>Lat (N)</u>	<u>Long (W)</u>			
1737	Dec. 18	40.8	74.0	A	VII	
1775	July 6	43.5	73.5	B	VI	
1853	Mar. 12	43.7	75.5	B	VI	
1857	Oct. 23	43.2	78.6	C	VI	
1867	Dec. 18	44.7	75.2	B	VI	
1877	Nov. 4	45.3	74.0	B	VII	
1884	Aug. 10	40.6	74.0	A	VII	
1897	May 27	44.5	73.5	B	VI	
1929	Aug. 12	42.9	78.3	C	VIII	5.9
1931	Apr. 20	43.4	73.7	B	VII	5.0
1944	Sept. 5	45.0	74.9	B	VIII	5.9
1944	Sept. 5	45.0	74.9	B	-	4.6
1957	Mar. 23	41.6	74.8	A	VI	4.8
1966	Jan. 1	42.8	78.2	C	VI	4.7
1967	Jun. 13	42.9	78.2	C	VI	3.9
1974	Jun. 7	41.6	73.9	A	-	3.3
1975	Jun. 9	44.9	73.6	B	-	4.2

1. See Figure 6.

2. I_o = Maximum Intensity (Modified Mercalli Scale)

3. M = Generalized Magnitude

Ref.: Mitronovas (1981)

TABLE VI
LIST OF EARTHQUAKES HAVING ATTENUATED
INTENSITIES GREATER THAN OR EQUAL TO IV
AT THE ONONDAGA DAM SITE

<u>EVENT</u>	<u>REGION</u>	<u>AT EPICENTER Intensity (1)</u>	<u>Magnitude</u>	<u>FROM SITE (KM)</u>	<u>ATTENUATED INTENSITY (2)</u>
Feb. 5, 1663	La Malbaie, Quebec	10		705	4.7
Aug. 12, 1929	Attica, N. Y.	8	5.8	182	4.4
Sept. 5, 1944	Massena, N. Y.	8	5.9	252	4.0
Oct. 20, 1870	Baie-St.-Paul, Quebec	9		668	3.8
Mar. 1, 1925	La Malbaie, Quebec	9	6.6	705	3.7
June 11, 1638	La Malbaie, Quebec	9		707	3.7
1534	Les Eboulements, Quebec	9		713	3.7
Nov. 18, 1929	Grand Banks, NF	10	7.2	1608	3.6
Sept. 16, 1732	Montreal, Quebec	8		352	3.6

(1) Modified Mercalli Intensity


(2) At Dam Site

Ref: Chuburis (1981)

ONONDAGA DAM, NEW YORK

FIGURES

U. S. Army Engineer District, Buffalo
1776 Niagara Street
Buffalo, New York 14207







FIGURE 1







FIGURE 2







FIGURE 3








FIGURE 4






I. REF. U.S. ARMY CORPS OF ENGINEERS.
(1947)

ONONDAGE DAM, NEW YORK
SITE AND SUBSURFACE
EXPLORATION PLAN

U.S. ARMY ENGINEER DISTRICT BUFFALO
TO ACCOMPANY PHASE I, GEOTYPIC STABILITY INVESTIGATION
DATED AUGUST 1968

FIGURE 5







FIGURE 6






FIGURE 7




FIGURE 7A

FIGURE 7A

MAGNITUDE M	EPICENTRAL DISTANCE km	EPICENTRAL ACCELERATION g	MODIFIED-MERCALLI INTENSITY SCALE		
			I	GROUP	ONSET ACCELERATION g
			I Detected only by sensitive instruments.		
			II Felt by a few persons at rest, especially on upper floors; delicate suspended objects may swing.	-2	
M=3	3		III Felt noticeably indoors, but not always recognized as a quake; standing autos rock slightly, vibration like passing truck.	-3	
	4			-4	
	5 .005g		IV Felt indoors by many, outdoors by a few; at night some awaken; dishes, windows, doors disturbed; motor cars rock noticeably.	-5 .005g	
	6			-6	
	7			-7	
	8			-8	
	9			-9	
	10 .01g		V Felt by most people; some breakage of dishes, windows, and plaster; disturbance of tall objects.	-10 .01g	
M=4	20			-20	
	30		VI Felt by all; many frightened and run outdoors; falling plaster and chimneys; damage small.	-30	
M=5	40			-40	
	50 .05g		VII Everybody runs outdoors; damage to buildings varies, depending on quality of construction; noticed by drivers of autos.	-50 .05g	
	60			-60	
	70			-70	
	80			-80	
	90			-90	
	100 .1g		VIII Panel walls thrown out of frames; fall of walls, monuments, chimneys; sand and mud ejected; drivers of autos disturbed.	-100 .1g	
M=6	200			-200	
	300		IX Buildings shifted off foundations, cracked, thrown out of plumb; ground cracked; underground pipes broken.	-300	
M=7	400			-400	
	500 .5g		X Most masonry and frame structures destroyed; ground cracked; rails bent; landslides.	-500 .5g	
	600			-600	
	700			-700	
	800			-800	
	900 1g			-900 1g	
	1000			-1000	
M=8	2000		XI New structures remain standing; bridges destroyed; fissures in ground; pipes broken; landslides; rails bent.	-2000	
	3000			-3000	
	4000 5g		XII Damage total; waves seen on ground surface; lines of sight and level distorted; objects thrown up into air.	-4000 5g	
				-5000 5g	
				-6000	

REF: Nuclear Reactors and
Earthquakes (1963)

ONONDAGA DAM, NEW YORK
INTENSITY, MAGNITUDE AND
ACCELERATION RELATIONSHIP

U.S. ARMY ENGINEER DISTRICT BUFFALO
TO ACCOMPANY PHASE I, SEISMIC STABILITY INVESTIGATION
DATED: AUGUST 1962

FIGURE 8




FIGURE 9




FIGURE 10





FIGURE II




NOTE:

BASED ON CORNELL AND MERZ (1975)
ATTENUATION ANALYSES USING
STANDARD DEVIATION OF 0.4

ONONDAGA DAM, NEW YORK
PROBABILITY OF EXCEEDENCE
FOR PEAK HORIZONTAL
GROUND ACCELERATIONS
U.S. ARMY ENGINEER DISTRICT BUFFALO
TO ACCOMPANY PHASE I, SEISMIC STABILITY INVESTIGATION
DATED: AUGUST 1982

FIGURE 12







FIGURE 13

ONONDAGA DAM, NEW YORK
STANDARD PENETRATION
RESISTANCE VS. DEPTH

U.S. ARMY ENGINEER DISTRICT BUFFALO
TO ACCOMPANY PHASE I, SEISMIC STABILITY INVESTIGATION
DATED: SEPTEMBER 1962

FIGURE 13




REF: APPLIED TECHNOLOGY COUNCIL
(PUBLICATION ATC 3-06, 1978)

ONONDAGA DAM, NEW YORK

AVERAGE ACCELERATION
SPECTRA FOR DIFFERENT
SITE CONDITIONS

U.S.ARMY ENGINEER DISTRICT, BUFFALO
TO ACCOMPANY PHASE I, SEISMIC STABILITY
INVESTIGATION. DATED: NOVEMBER 1982

FIGURE 14



LEGEND :


- | | |
|--|-----------------------------|
| | SOILS BELOW TOE OF
DAM |
| | SOILS BELOW CREST OF
DAM |

REF: SEED AND IDRISI (1981)

FILE NO. 7450 03

ONONDAGA DAM, NEW YORK
LIQUEFACTION POTENTIAL OF
DAM FOUNDATION SOILS
U.S. ARMY ENGINEER DISTRICT BUFFALO
TO ACCOMPANY PHASE I, SEISMIC STABILITY INVESTIGATION
DATED: AUGUST 1982

FIGURE 15



LEGEND:


- SOILS BELOW TOE OF DAM
- SOILS BELOW CREST OF DAM

REF: SEED AND IDRISI (1981)

ONONDAGA DAM, NEW YORK
LIQUEFACTION POTENTIAL
OF DAM FOUNDATION SOILS
CORRELATED TO DIFFERENT
EARTHQUAKE MAGNITUDES

U. S. ARMY ENGINEER DISTRICT BUFFALO
TO ACCOMPANY PHASE I, SEISMIC STABILITY
INVESTIGATION DATED: NOVEMBER 1982

FIGURE 15A



APPENDIX A

CENTRAL NEW YORK STRATIGRAPHY

A1. Table II presents the generalized stratigraphic column for central New York and Figure 3 is a geologic map of the central New York Region.

A2. As shown on Table II, the rocks in central New York range in age from Late Ordovician along the south shore of Lake Ontario to Late Devonian at the New York-Pennsylvania border. Refer to Table I for the geologic time scale.

Upper Ordovician System

A3. The oldest stratigraphic unit in central New York, exposed along the south shore of Lake Ontario, is the Queenston Formation. It encompasses a maximum of 700 feet of red, crumbly shale and red siltstone and sandstone in this region. The coarser beds increase in thickness eastward and southward.

Silurian System

A4. Silurian rocks surround the Appalachian Plateau on the north and are found in the Lake Ontario Plain, and on the east in the western-most Hudson Valley Province. In the Helderberg region in the northeast corner of the Allegheny Plateau, Lower Devonian rocks rest upon the Middle Ordovician and the normally intervening Silurian strata are entirely missing.

A5. For convenience, the New York Silurian can be subdivided into three parts. A lower portion, mainly of red sandstone beds (Medina Group); a middle part consisting of shales and carbonates (Clinton and Lockport Groups); and an upper division of more unusual strata, mostly hypersaline evaporites and brackish lagoonal deposits (Salina and Bertie Groups).

A6. Complexities in the Silurian rocks include numerous facies changes from west to east, the presence of many depositional breaks (disconformities), and poor exposures especially in the Upper Silurian section. Small fossils called conodonts and ostracods have been used to develop refined correlations in the Silurian System of New York State, and individual strata can now be identified from rock core of exploratory borings. These rocks have a simple geologic structure, dipping gently southward at 40 to 50 feet per mile (65 to 80 feet in the subsurface) south of Lake Ontario.

Albion Series (Lower Silurian)

A7. Lower Silurian rocks are exposed in a narrow east-west belt parallel to the south shore of Lake Ontario and just south of the exposure belt of Queenston rocks, pinching out by unconformity east of the Oswego River. The line of Barge Canal eastward from Lockport to Spencerport follows the outcrops of this unit.

A8. The Medina Group is the sole Albion-aged unit in New York State. It is made up of, in the Niagara region, the Whirlpool Sandstone (25 feet thick) below, Power Glen Formation (30 feet thick) and the Grimsby Formation or Red Medina Sandstone above (50 to 70 feet thick). East of Lockport, the Whirlpool and Power Glen rocks pass by facies change into the lower Grimsby Formation. At Rochester, the Grimsby Formation rests directly on the Queenston Formation.

A9. The Grimsby Formation consists of red, crossbedded, medium bedded to massive, medium to coarse, locally conglomeritic, arkosic sandstone with some red silty shale. East of Holly and Medina, the massive sands become thin and interbedded with finer silty shales. To the west, the silty shales become thicker.

Niagaran Series (Middle Silurian)

A10. Niagaran rocks are exposed in an east-west belt from the Niagara River through Rochester to the Helderberg region and in a northeast-

southwest belt in the western Hudson Valley Province from the Kingston area to Port Jervis. Niagaran rocks are missing around the Northeast perimeter of the Allegheny Plateau. On the Lake Ontario Plain, the Niagaran Series embraces the Clinton Group below and the Lockport Group above.

A11. The Clinton Group is a complex suite of lithologies and facies changes, with numerous disconformities. Therefore, no Clinton formation traverses the state without some change in character. In general, coarse clastic sedimentary rocks dominate this section in east central New York, with fine shales and carbonates being restricted to western New York. The section is about 120 feet thick at Niagara, 180 feet in the Rochester Gorge, 320 feet in the Oneida Lake region, and some 220 feet at its easternmost outcrops in Oneida and Herkimer Counties. It can be divided into a lower, middle and upper part based on fossil zones.

A12. Lower Clinton rocks represent a transgressive sequence of rock types, including the basal Kodak (Thorold) Sandstone (six feet thick), Oneida conglomerate (12 to 50 feet), the Neahga (six feet), Maplewood (20 feet), Bear Creek (10 feet), and Sodus (60 feet) shales, and finally terminating upward with Reynales (7 to 17 feet) and Wolcott Limestone (20 feet).

A13. Middle Clinton formations are restricted to central and east central New York, none being found west of the Sodus Bay - Seneca Lake meridian. The Sauquoit Formation is the sole Middle Clinton unit (0 to 80 feet), consisting of shales with interbedded sandstone and siltstones. The Sauquoit strata change eastward into the Otsquago Sandstone (100 to 130 feet). At the top of the Sauquoit, the fourth Clinton iron ore bed is found, the Westmoreland, south of Rome and Utica. The Otsquago and the eastern and coarsest Sauquoit beds have yielded several gas and salt water shows in Madison and Otsego Counties.

A14. Upper Clinton rocks, unlike the Middle Clinton units, are found across New York, east to west. The Irondequoit Limestone (18 to 30 feet), Williamson Black Shale (0 to 30 feet) and Willowvale Shale

(0 to 80 feet) are all facies of one another comprising the lowermost portion. In eastern New York, the Kirkland Hematite rests on top of the Dawes Dolostone (ten feet), the uppermost Clinton iron ore. The most significant portion of the Upper Clinton is made up of the Rochester Shale and its eastern facies, the Herkimer Sandstone. Rochester rocks are relatively thick, gray to dark gray, calcareous, dolomitic, silty shale containing numerous limestone and dolostone beds and lenses, especially in the upper portion. In the Genesee region, an upper dolostone is so prominent that a separate mappable unit, the Gates Dolostone, is recognized. The Rochester Shale is about 90 feet thick in the west and increases to 140 feet thick in central New York, north of Syracuse.

A15. The Herkimer Sandstone is 70 feet of gray calcareous, thin-bedded sandstone, interbedded with dark gray sandy and silty shale, and is found only in the Oneida-Utica region. To the east, this sandstone becomes a coarse, medium-bedded, gray and red sandstone with minor shale partings.

A16. The Lockport Group is a thick (75 to 200 feet, east to west) sequence of dolostones and sandy dolostones with lesser amounts of limestone. The Lockport rocks are extremely resistant and form the Niagara or Lockport Escarpment, a major topographic feature extending from Rochester to the Niagara Gorge. East of the Rome meridian, the Lockport passes into the Ilion Formation of shales with interbedded dolostones.

Cayugan Series (Upper Silurian)

A17. Rocks of Late Silurian age belong essentially to the Salina and Bertie Groups. Exposures of the Salina Group are relatively rare as it is composed primarily of weak shales and was, therefore, usually stripped by glacial erosion. The Bertie rocks are more resistant carbonates, and therefore overlying glacial deposits are thin. The Salina Group is about 300 feet thick near Buffalo, increasing to about 950 to 1000 feet near Syracuse, thereafter thinning rapidly to a featheredge near Richfield

Springs in Otsego County. Three formations are included in the Salina Group: Vernon Shale, salt of the Syracuse Formation, and the Camillus Formation.

A18. The Vernon Shale is composed of variegated red and green shale and siltstone totalling 300 to 400 feet in thickness. The base of the Vernon is Late Niagaran in age in eastern and central New York, and becomes progressively younger westward.

A19. The Syracuse Formation consists of three to four hundred feet of shale, dolostone and anhydrite which thicken rapidly southward to about 1,300 feet beneath Schuyler and Chemung Counties. With distance to the south, numerous salt beds occur, some reaching a maximum thickness of 400 feet. These salt beds rarely, if ever, outcrop at the surface, but the updip limit of the major salt beds is nearest the surface at Syracuse. This limit then strikes southwestward across the state, meaning that salt lies considerably deeper below the Genesee Valley than below Syracuse.

A20. Overlying the Syracuse Formation are 100 to 200 feet of shales, dolostones, and shaly dolostones of the Camillus Formation, containing a large quantity of interbedded anhydrite and gypsum.

A21. The remainder of the Cayugan Series above the Salina Group is composed of the Bertie Group dolostones (50 feet), Akron or Cobleskill limestones and dolostone (10 feet), and lower Chrysler Dolostone (30 feet). The Silurian-Devonian boundary occurs in the middle of the Chrysler Formation. Caverns, caves and other solution features are also common in these units.

Devonian System

A22. Devonian rocks are by far the most extensively exposed in New York State. Devonian strata underlie all of the Allegheny Plateau and regions adjacent to it, such as the Lake Erie Plain, southern Lake Ontario

Plain, and westernmost Hudson Valley Province. In addition, the beds are generally structurally simple, and the abundant fossil fauna in such rocks have led to a detailed stratigraphic description over the last fifty years.

A23. Carbonates dominate the Lower Devonian and lower part of the Middle Devonian while clastic deposits predominate in the remainder of the section. The clastics are fine-textured marine rocks at the bottom, grading upward to coarse, red continental sandstones. These deposits, are known as the Catskill Delta, and are a wedge of clastic sediments that thicken and become coarser to the east. The New York Devonian is subdivided into the Ulsterian Series (Lower Devonian), Erian Series (Middle Devonian) and Senecan and Chautauquan Series (Upper Devonian).

Ulsterian Series (Lower Devonian)

A24. Lower Devonian exposures are confined to the area west of Seneca Lake, along the north edge of the Allegheny Plateau and south along the north edge of the Allegheny Plateau and south along its eastern perimeter to Port Jervis. This largely carbonate sequence is divided into the Helderberg Group below and the Tristates Group above.

A25. The Helderberg Group is a complex of intertonguing carbonate facies. Lagoonal dolostones with minor evaporites pass eastward into an offshore shelf facies dominated by limestones, some with reefs. The Helderberg Group is about 240 feet thick in the Helderberg Mountains southwest of Albany, increasing southward to some 450 feet at Port Jervis near the New Jersey border. Westward the group thins to about 100 feet near Syracuse and is absent west of Geneva. Solution features and caverns (e.g. Howe Caverns) are common in the Helderberg Group.

A26. The Helderberg Group is succeeded in an upward direction by the Tristates Group of which the Oriskany Sandstone is the lowest unit. This formation is, in turn, succeeded by the Esopus Shale, Carlisle Center

AD-A169 701 REPORT ON SEISMIC STABILITY MONONIAGA DAM NEW YORK 2/2
ATTACHMENT NUMBER 2(U) CORPS OF ENGINEERS BUFFALO NY
BUFFALO DISTRICT I X GRASSO ET AL. MAY 86


UNCLASSIFIED

DACW49-81-D-0011

F/G 13/2

ME

END
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100
101
102
103
104
105
106
107
108
109
110
111
112
113
114
115
116
117
118
119
120
121
122
123
124
125
126
127
128
129
130
131
132
133
134
135
136
137
138
139
140
141
142
143
144
145
146
147
148
149
150
151
152
153
154
155
156
157
158
159
160
161
162
163
164
165
166
167
168
169
170
171
172
173
174
175
176
177
178
179
180
181
182
183
184
185
186
187
188
189
190
191
192
193
194
195
196
197
198
199
200
201
202
203
204
205
206
207
208
209
210
211
212
213
214
215
216
217
218
219
220
221
222
223
224
225
226
227
228
229
230
231
232
233
234
235
236
237
238
239
240
241
242
243
244
245
246
247
248
249
250
251
252
253
254
255
256
257
258
259
260
261
262
263
264
265
266
267
268
269
270
271
272
273
274
275
276
277
278
279
280
281
282
283
284
285
286
287
288
289
290
291
292
293
294
295
296
297
298
299
300
301
302
303
304
305
306
307
308
309
310
311
312
313
314
315
316
317
318
319
320
321
322
323
324
325
326
327
328
329
330
331
332
333
334
335
336
337
338
339
340
341
342
343
344
345
346
347
348
349
350
351
352
353
354
355
356
357
358
359
360
361
362
363
364
365
366
367
368
369
370
371
372
373
374
375
376
377
378
379
380
381
382
383
384
385
386
387
388
389
390
391
392
393
394
395
396
397
398
399
400
401
402
403
404
405
406
407
408
409
410
411
412
413
414
415
416
417
418
419
420
421
422
423
424
425
426
427
428
429
430
431
432
433
434
435
436
437
438
439
440
441
442
443
444
445
446
447
448
449
450
451
452
453
454
455
456
457
458
459
460
461
462
463
464
465
466
467
468
469
470
471
472
473
474
475
476
477
478
479
480
481
482
483
484
485
486
487
488
489
490
491
492
493
494
495
496
497
498
499
500
501
502
503
504
505
506
507
508
509
510
511
512
513
514
515
516
517
518
519
520
521
522
523
524
525
526
527
528
529
530
531
532
533
534
535
536
537
538
539
540
541
542
543
544
545
546
547
548
549
550
551
552
553
554
555
556
557
558
559
560
561
562
563
564
565
566
567
568
569
570
571
572
573
574
575
576
577
578
579
580
581
582
583
584
585
586
587
588
589
590
591
592
593
594
595
596
597
598
599
600
601
602
603
604
605
606
607
608
609
610
611
612
613
614
615
616
617
618
619
620
621
622
623
624
625
626
627
628
629
630
631
632
633
634
635
636
637
638
639
640
641
642
643
644
645
646
647
648
649
650
651
652
653
654
655
656
657
658
659
660
661
662
663
664
665
666
667
668
669
670
671
672
673
674
675
676
677
678
679
680
681
682
683
684
685
686
687
688
689
690
691
692
693
694
695
696
697
698
699
700
701
702
703
704
705
706
707
708
709
710
711
712
713
714
715
716
717
718
719
720
721
722
723
724
725
726
727
728
729
730
731
732
733
734
735
736
737
738
739
740
741
742
743
744
745
746
747
748
749
750
751
752
753
754
755
756
757
758
759
760
761
762
763
764
765
766
767
768
769
770
771
772
773
774
775
776
777
778
779
780
781
782
783
784
785
786
787
788
789
790
791
792
793
794
795
796
797
798
799
800
801
802
803
804
805
806
807
808
809
8010
8011
8012
8013
8014
8015
8016
8017
8018
8019
8020
8021
8022
8023
8024
8025
8026
8027
8028
8029
8030
8031
8032
8033
8034
8035
8036
8037
8038
8039
8040
8041
8042
8043
8044
8045
8046
8047
8048
8049
8050
8051
8052
8053
8054
8055
8056
8057
8058
8059
8060
8061
8062
8063
8064
8065
8066
8067
8068
8069
8070
8071
8072
8073
8074
8075
8076
8077
8078
8079
8080
8081
8082
8083
8084
8085
8086
8087
8088
8089
8090
8091
8092
8093
8094
8095
8096
8097
8098
8099
80100
80101
80102
80103
80104
80105
80106
80107
80108
80109
80110
80111
80112
80113
80114
80115
80116
80117
80118
80119
80120
80121
80122
80123
80124
80125
80126
80127
80128
80129
80130
80131
80132
80133
80134
80135
80136
80137
80138
80139
80140
80141
80142
80143
80144
80145
80146
80147
80148
80149
80150
80151
80152
80153
80154
80155
80156
80157
80158
80159
80160
80161
80162
80163
80164
80165
80166
80167
80168
80169
80170
80171
80172
80173
80174
80175
80176
80177
80178
80179
80180
80181
80182
80183
80184
80185
80186
80187
80188
80189
80190
80191
80192
80193
80194
80195
80196
80197
80198
80199
80200
80201
80202
80203
80204
80205
80206
80207
80208
80209
80210
80211
80212
80213
80214
80215
80216
80217
80218
80219
80220
80221
80222
80223
80224
80225
80226
80227
80228
80229
80230
80231
80232
80233
80234
80235
80236
80237
80238
80239
80240
80241
80242
80243
80244
80245
80246
80247
80248
80249
80250
80251
80252
80253
80254
80255
80256
80257
80258
80259
80260
80261
80262
80263
80264
80265
80266
80267
80268
80269
80270
80271
80272
80273
80274
80275
80276
80277
80278
80279
80280
80281
80282
80283
80284
80285
80286
80287
80288
80289
80290
80291
80292
80293
80294
80295
80296
80297
80298
80299
80300
80301
80302
80303
80304
80305
80306
80307
80308
80309
80310
80311
80312
80313
80314
80315
80316
80317
80318
80319
80320
80321
80322
80323
80324
80325
80326
80327
80328
80329
80330
80331
80332
80333
80334
80335
80336
80337
80338
80339
80340
80341
80342
80343
80344
80345
80346
80347
80348
80349
80350
80351
80352
80353
80354
80355
80356
80357
80358
80359
80360
80361
80362
80363
80364
80365
80366
80367
80368
80369
80370
80371
80372
80373
80374
80375
80376
80377
80378
80379
80380
80381
80382
80383
80384
80385
80386
80387
80388
80389
80390
80391
80392
80393
80394
80395
80396
80397
80398
80399
80400
80401
80402
80403
80404
80405
80406
80407
80408
80409
80410
80411
80412
80413
80414
80415
80416
80417
80418
80419
80420
80421
80422
80423
80424
80425
80426
80427
80428
80429
80430
80431
80432
80433
80434
80435
80436
80437
80438
80439
80440
80441
80442
80443
80444
80445
80446
80447
80448
80449
80450
80451
80452
80453
80454
80455
80456
80457
80458
80459
80460
80461
80462
80463
80464
80465
80466
80467
80468
80469
80470
80471
80472
80473
80474
80475
80476
80477
80478
80479
80480
80481
80482
80483
80484
80485
80486
80487
80488
80489
80490
80491
80492
80493
80494
80495
80496
80497
80498
80499
80500
80501
80502
80503
80504
80505
80506
80507
80508
80509
80510
80511
80512
80513
80514
80515
80516
80517
80518
80519
80520
80521
80522
80523
80524
80525
80526
80527
80528
80529
80530
80531
80532
80533
80534
80535
80536
80537
80538
80539
80540
80541
80542
80543
80544
80545
80546
80547
80548
80549
80550
80551
80552
80553
80554
80555
80556
80557
80558
80559
80560
80561
80562
80563
80564
80565
80566
80567
80568
80569
80570
80571
80572
80573
80574
80575
80576
80577
80578
80579
80580
80581
80582
80583
80584
80585
80586
80587
80588
80589
80590
80591
80592
80593
80594
80595
80596
80597
80598
80599
80600
80601
80602
80603
80604
80605
80606
80607
80608
80609
80610
80611
80612
80613
80614
80615
80616
80617
80618
80619
80620
80621
80622
80623
80624
80625
80626
80627
80628
80629
80630
80631
80632
80633
80634
80635
80636
80637
80638
80639
80640
80641
80642
80643
80644
80645
80646
80647
80648
80649
80650
80651
80652
80653
80654
80655
80656
80657
80658
80659
80660
80661
80662
80663
80664
80665
80666
80667
80668
80669
80670
80671
80672
80673
80674
80675
80676
80677
80678
80679
80680
80681
80682
80683
80684
80685
80686
80687
80688
80689
80690
80691
80692
80693
80694
80695
80696
80697
80698
80699
80700
80701
80702
80703
80704
80705
80706
80707
80708
80709
80710
80711
80712
80713
80714
80715
80716
80717
80718
80719
80720
80721
80722
80723
80724
80725
80726
80727
80728
80729
80730
80731
80732
80733
80734
80735
80736
80737
80738
80739
80740
80741
80742
80743
80744
80745
80746
80747
80748
80749
80750
80751
80752
80753
80754
80755
80756
80757
80758
80759
80760
80761
80762
80763
80764
80765
80766
80767
80768
80769
80770
80771
80772
80773
80774
80775
80776
80777
80778
80779
80780
80781
80782
80783
80784
80785
80786
80787
80788
80789
80790
80791
80792
80793
80794
80795
80796
80797
80798
80799
80800
80801
80802
80803
80804
80805
80806
80807
80808
80809
80810
80811
80812
80813
80814
80815
80816
80817
80818
80819
80820
80821
80822
80823
80824
80825
80826
80827
80828
80829
80830
80831
80832
80833
80834
80835
80836
80837
80838
80839
80840
80841
80842
80843
80844
80845
80846
80847
80848
80849
80850
80851
80852
80853
80854
80855
80856
80857
80858
80859
80860
80861
80862
80863
80864
80865
80866
80867
80868
80869
80870
80871
80872
80873
80874
80875
80876
80877
80878
80879
80880
80881
80882
80883
80884
80885
80886
80887
80888
80889
80890
80891
80892
80893
80894
80895
80896
80897
80898
80899
80900
80901
80902
80903
80904
80905
80906
80907
80908
80909
80910
80911
80912
80913
80914
80915
80916
80917
80918
80919
80920
80921
80922
80923
80924
80925
80926
80927
80928
80929
80930
80931
80932
80933
80934
80935
80936
80937
80938
80939
80940
80941
80942
80943
80944
80945
80946
80947
80948
80949
80950
80951
80952
80953
80954
80955
80956
80957
80958
80959
80960
80961
80962
80963
80964
80965
80966
80967
80968
80969
80970
80971
80972
80973
80974
80975
80976
80977
80978
80979
80980
80981
80982
80983
80984
80985
80986
80987
80988
80989
80990
80991
80992
80993
80994
80995
80996
80997
80998
80999
801000
801001
801002
801003
801004
801005
801006
801007
801008
801009
801010
801011
801012
801013
801014
801015
801016
801017
801018
801019
801020
801021
801022
801023
801024
801025
801026
801027
801028
801029
801030
801031
801032
801033
801034
801035
801036
801037
801038
801039
801040
801041
801042
801043
801044
801045
801046
801047
801048
801049
801050
801051
801052
801053
801054
801055
801056
801057
801058
801059
801060
801061
801062
801063
801064
801065
801066
801067
801068
801069
801070
801071
801072
801073
801074
801075
801076
801077
801078
801079
801080
801081
801082
801083
801084
801085
801086
801087
801088
801089
801090
801091
801092
801093
801094
801095
801096
801097
801098
801099
801100
801101
801102
801103
801104
801105
801106
801107
801108
801109
801110
801111
801112
801113
801114
801115
801116
801117
801118
801119
801120
801121
801122
801123
801124
801125
801126
801127
801128
801129
801130
801131
801132
801133
801134
801135
801136
801137
801138
801139
801140
801141
801142
801143
801144
801145
801146
801147
801148
801149
801150
801151
801152
801153
801154
801155
801156
801157
801158
801159
801160
801161
801162
801163
801164
8011



MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS 1963-A

Shale and Schoharie Limestone in eastern New York only. The Tristates Group is about 160 feet thick in the Albany region, thickening southward to about 750 feet at Port Jervis, and except for isolated patches of Oriskany, disappears west of Richfield Springs.

A27. The Oriskany Sandstone is the most important formation in the Tristates Group. It underlies much of the Allegheny Plateau, except in the southwest part of the state, and is 0 to 50 feet of quartzose sandstone, with calcite and silica cement. This sandstone is porous and permeable in siliceous zones and tight where calcareous. In the west, it is a prolific gas producer. Eastward in the Allegheny Plateau, there is no known gas production in the Oriskany Sandstone.

Erian Series (Middle Devonian)

A28. Two stratigraphic units make up the Middle Devonian in New York State, the Onondaga Limestone and the Hamilton Group. They are exposed across the entire state, in a continuous belt, from Lake Erie on the west to the New Jersey border near Port Jervis in the southeast.

A29. The Onondaga Limestone is a regional, blanket carbonate deposit, thinning from about 175 feet at Buffalo to only some 70 feet at Syracuse, but thickens eastward again to about 250 feet at Catskill and 300 feet at Port Jervis. It is a thin to medium bedded, medium to coarse textured, gray limestone, often containing bedded chert and chert nodules. Onondaga rocks are extensively quarried across the state.

A30. The Hamilton Group is a clastic wedge (Catskill Delta) deposited by westward flowing streams from a rising mountainous region to the east and southeast of the present Catskill region. The group is about 265 feet thick in western New York, 1,100 feet in central New York and 2,500 to 3,000 feet thick in the Catskills. At the toe of the delta complex, in an ocean basin in what is now western New York, fine-grained, bituminous, dark to black Hamilton shales were deposited. Uppermost Hamilton beds in western New York are gray calcareous shales. The shales pass eastward

into coarse, silty shales and sandstones. These, in turn, grade eastward and interfinger with mostly terrestrial, crossbedded, red and green sandstones, shales and siltstones.

A31. Three thin but persistent carbonate units (key beds) pierce the clastic wedge and were deposited over the delta at times of low sediment influx. These serve to subdivide the Hamilton into four formations, the Marcellus, Skaneateles, Ludlowville, and Moscow. The carbonate beds are from oldest to youngest, Mottville Member, Centerfield Member and Portland Point Member.

Combined Senecan and Chautauquan Series (Upper Devonian)

A32. The Upper Devonian sequence is a continuation of the Catskill Delta which was migrating westward during deposition. The same general Middle Devonian facies continue but persistent key beds are black shale tongues, not carbonate units, except for the lowest formation, the Tully Limestone. The black shales subdivide the Upper Devonian into a number of groups, totalling some 3,300 feet of thickness in southwest New York, 7,000 feet in south central New York, and 7,700 feet in the Catskills. The Upper Devonian is exposed throughout the southern tier region of the Allegheny Plateau, however the Chatauquan Series is present only in the western part, as it has been removed further eastward by erosion.


Senecan Series

A33. The Tully Limestone is the basal formation of the Senecan Series. It reaches a maximum thickness of 100 feet in east central New York and changes eastward into the Gilboa Shale and sandstone. The Tully is approximately 30 feet thick in the Syracuse region and is not present west of Canandaigua Lake due to its being removed by erosion prior to deposition of overlying units.

A34. Overlying the Tully is the Genesee, Sonyea and West Falls Groups. They are black shales in the west and red beds in the east, although each facies is found further westward in the West Falls Group.

Chautauquan Series

A35. The Chautauquan Series is made up of the Canadaway, Conneaut, and Conewango Groups. The Canadaway and Conneaut Groups contain several fresh water aquifers as well as the major oil producing sands of SW New York. They have been penetrated by numerous borings but records of many of the early wells have now been lost. Much of the oil is trapped along axis of the broad anticlinal structures that characterize the southwest portion of the Allegheny Plateau. If salt water is not present, the oil may also be found along the synclinal axes.



APPENDIX B
ONONDAGA DAM SITE STRATIGRAPHY

B1. Older Silurian units are exposed to the north of the dam in Syracuse and younger Upper Devonian units cap the hills south of the dam, and form the valley sides and floor south of the Village of Tully.

B2. Table III presents the detailed stratigraphic column along the Syracuse Meridian in the vicinity of the dam. Figure 4 is a geologic map of the area surrounding the dam. A description of the stratigraphy summarized on Table III and Figure 4 follows.

Lower Devonian - Ulsterian Series

Helderberg Group

B3. The Helderberg Group in the Onondaga Valley region is composed of two formations which, in ascending order, are the Rondout Formation (Chrysler Dolostone) and the Manlius Formation (Table III). The Rondout is poorly exposed in this area, however, a limited outcrop is exposed in the base of the rock cuts on Interstate 81, just south of the junction with Interstate 481.

B4. The Manlius Formation is subdivided from older to younger, into the Olney Limestone Member, Elmwood A, B and C Dolostone Member, Clark Reservation Limestone Member and the Jamesville Limestone Member.

- a. Olney Member - Named for Olney Station on the now abandoned Auburn and Syracuse Electric Railroad, is approximately 30 feet of fine-grained, even bedded limestones. The lower portion is thin-bedded; the upper portion is somewhat more thickly bedded, although both may have laminated beds. Fossils are neither abundant nor well diversified. The Olney underlies the spillway cut at the east end of the dam and is exposed in road cuts on Interstate 81 south of the junction with Interstate 481.

- b. Elmwood Member - Overlies the Olney Member and consists of a series of dolostones, waterlimes, and limestones. The name is derived from Elmwood Park near Onondaga Hill in the southwestern part of Syracuse. It is subdivided into 3 units known as Elmwood A, B, and C in ascending order. Elmwood A is a drab yellowish brown, thin-bedded and mud cracked waterlime, barren of fossils and about 6 feet thick. Elmwood B is a fine-grained, blue limestone, 3 feet thick, locally known as the "Diamond blue". This is overlain by 4 feet of waterlime, similar to Elmwood A, and known as Elmwood C. The Elmwood is exposed on the west side of the Onondaga Valley in Sweet's Quarry and Split Rock Quarry, in the roadcuts along Interstate 81 south of Interstate 481 junction, at Clark Reservation State Park, and in the vicinity of the Village of Jamesville. It underlies the spillway rock cut at the east edge of the flood control structure.
- c. Clark Reservation Limestone Member - Lies above the Elmwood and consists of a bed of fine-grained, dark blue, white-weathering limestone characterized by a diagonal fracture system. The name comes from Clark Reservation State Park, one mile west of Jamesville, where the type section is located. It is approximately 5 feet thick and in addition to the type locality it is exposed at Onondaga Hill on the west side of the valley and in the rock cuts along Interstate 81 mentioned above. It is also exposed at the base of the exposure on the east side of U. S. 11 just north of the Nedrow interchange to Interstate 81.
- d. Jamesville Limestone Member - Lies between the Clark Reservation and the Onondaga Limestone. It is approximately 25 feet of fine-grained, dark blue, brittle,

limestone in thin, even beds at its type exposure in Clark Reservation State Park. It makes up the lower 12 feet of the rock exposure in the spillway cut at the east edge of the dam. The lowest 2.5 feet of the Jamesville exposed at this location is a stromatoporoid biostrome which is a layer composed of enormous numbers of stromatoporoids, perhaps a type of fossil sponge. A complete section of the Jamesville is exposed on U.S. 11 just north of the Nedrow interchange to Interstate 81, and in the rock cuts on Interstate 81 south of the junction of Interstate 481.

Tristates Group

B5. The Oriskany Sandstone, the only formation of this group exposed in central New York, is not well developed in the vicinity of the dam and Onondaga Valley in general. A few inches of reddish-orange, sandy layers at the base of the Onondaga Limestone represent this unit in the spillway rock cut.

Middle Devonian - Erian Series

Onondaga Limestone

B6. The Middle Devonian sequence begins with the Onondaga Limestone which attains a thickness of approximately 70 feet in the Syracuse area. It is a series of light bluish-gray semi-crystalline limestones in even continuous layers from 1 inch to 2 feet in thickness, separated by thin seams of dark, calcareous shale. Flattened nodules of dark blue or black chert, sometimes in continuous sheets or beds are unevenly distributed throughout the Onondaga but mainly in the upper part.

B7. The Onondaga is comprised of five members as shown on Table III and discussed below:

- a. Edgecliff Member - The lowest member of the Onondaga is distinguished by its coarser, more pronounced, crystalline texture and abundant fossils. The base of the Edgecliff is a disconformity, meaning it was deposited over an erosion surface that had removed previously deposited rock strata. The member is approximately 15 ft. thick and is exposed in the spillway cut.
- b. Nedrow Member - Just above the Edgecliff, is characterized by thin-bedded, shaley limestone, marked in the lower part by abundant snail fossils. It is a medium gray, very fine-grained, argillaceous limestone containing little chert unevenly distributed at the top. It is approximately 10 ft. thick, is gradational with the overlying Moorehouse Member, and rests with a sharp contact on the Edgecliff. Both the Nedrow and the overlying Moorehouse Member occur in the spillway cut.
- c. The Moorehouse Member - Consists of 20 to 25 feet of medium gray, very fine grained limestone beds which are separated in many places by thin shaley partings ranging from 2 inches to 5 feet thick. Dark gray chert is common in this member but varies in amount. It is more common in the upper part of the member and occurs as more or less continuous strata.
- d. Tioga Bentonite Member - Occurs in the upper part of the Onondaga as a volcanic ash layer, 6 to 9 inches thick. It separates the underlying Moorehouse Limestone Member from the overlying Seneca Limestone Member. Neither the Tioga nor the Seneca Member were observed in the spillway cut.
- e. Seneca Member - Although lithologically similar to the upper Moorehouse, is characterized by a slightly different fossil assemblage. Also chert is less common in the upper part of the Seneca Member and the limestone beds are darker gray. This Member is approximately 25 feet thick.

B8. The Onondaga Limestone is exposed in the upper 50 feet of the spillway cut on the east side of the dam. Other exposures in the vicinity of the dam include Hemlock Creek northeast of Indian Village, abandoned quarries along Quarry Road on the Indian Reservation, road cuts on U.S. 11 at the Nedrow interchange to Interstate 81, road cuts on Interstate 81 north of the Nedrow exit, along the west branch of Onondaga Creek 3 miles northwest of South Onondaga and near Cedarvale. Additional exposures occur along the northern margin of the Allegheny Plateau from Jamesville through southern Syracuse and the famous quarries at Split Rock.

Hamilton Group

B9. The Hamilton Group in the Tully Valley consists of approximately 1,100 feet of mostly silty shales and siltstones lying above the Onondaga Limestone and below the Tully Limestone. Three thin carbonate beds serve to define the formation boundaries. The succession of units, their lithologies and thicknesses are shown on Table III.

B10. The Hamilton is the rock unit exposed in the dam vicinity except for the spillway cut at the dam itself. The Hamilton forms the sides of the Onondaga Valley north and south of the dam and also the floor of the valley south of the dam (Figures 3 and 4).

B11. The Hamilton rocks in the Tully Valley dip S 25° W at approximately 48 feet per mile, based upon the Centerfield Member as a datum. Formations included in the Hamilton Group are described below, in ascending order.

Marcellus Formation

B12. The Marcellus Formation is divided into four members. The lower three are composed of black shales and limestone, while the upper member is dominantly a transition from black to gray shale. The lower contact of this formation with the Onondaga Limestone is fairly

sharp throughout the area and is overlain by the Mottville Member of the Skaneateles Formation with a sharp contact.

- a. Union Springs Member - In the vicinity of the dam, the Union Springs Member is 10 feet thick. It is an alternation of black, sooty, carbonaceous, calcareous shale with thin bands and lenses of black bituminous limestone. The limestone beds range from less than 1 inch to 6 inches in thickness. Pyrite is disseminated throughout the Union Springs, many fossils being replaced by it. The contact with the overlying Cherry Valley Member is sharp.
- b. Cherry Valley Member - The Cherry Valley Limestone is a hackly, black, bituminous limestone with an orange-red stain that fills cavities, stains the surface, and coats some of the fossils. It is approximately 3 ft. thick.
- c. Chittenango Member - This member consists of about 80 feet of unfossiliferous, jet black, non-calcareous, bituminous shale that contains abundant pyrite. It is extremely thin bedded and displays excellent rectangular jointing. Wherever it is exposed it breaks into paper-thin flakes that are usually stained a rusty color. Calcareous, unfossiliferous, septarian concretions up to 6 or more feet in diameter are common in this member, as are also smaller non-septarian concretions. These shales grade upward into the overlying Cardiff.
- d. Cardiff Member - This member is named for exposures around the Village of Cardiff in the Tully Valley. It is a non-calcareous, dark gray to grayish black, medium-bedded shale at its base and grades upward into a slightly coarser shale of medium dark gray color. Toward the top, particularly the uppermost 4 feet, small, round, calcareous, non-septarian, unfossiliferous concretions are present. They range from 1 inch to 8 inches in diameter. As defined here,

the Cardiff is approximately 180 feet thick and is overlain by the Mottville Member of the Skaneateles Formation.

B13. The Marcellus Formation is exposed in the immediate vicinity of the dam. It makes up the lower slopes of the valley north of the dam, and south of the dam to a point south of Rattlesnake Gulf (Bare Mountain Ravine) approximately 6 miles south of dam. It is also exposed on the lower slopes of the valley along the west branch of Onondaga Creek westward through Pumpkin Hollow to the Village of Marcellus, the type section. Streams cascading down the sides of the Tully Valley notch ravines in which the Marcellus Formation is exposed in the lower reaches. Peppermill Gulf and Lords Hill Ravine near Ironsides are two excellent exposures, as well as ravines flowing down the east side of the valley south of the dam. Road cuts on Route 11A south of the dam expose Marcellus to a point a few miles south of Cardiff. The lower part of the formation, the Union Springs and Cherry Valley Limestone Members, are best exposed north of the dam. Two localities would be Hemlock Creek and a road cut on Interstate 81 just north of the Nedrow exit on the east side of the highway.

Skaneateles Formation

B14. In the Tully Valley, the Skaneateles Formation, with the exception of the Mottville Member, represents the intertonguing of a black shale facies to the west with a silty shale facies more fully developed to the east. Three tongues of dark shale, which are the eastern elongations of the Levanna Member of Cayuga Lake, extend into the silty facies and thereby provide the basis for subdividing this formation, above the Mottville, into three members. Each member begins with a dark, relatively unfossiliferous shale that passes upward into coarser, lighter colored, more fossiliferous beds. These are in turn sharply overlain by the next dark shale of the member above.

a. Mottville Member - In the Tully Valley, the Mottville Member is about 5 to 6 feet thick. It is highly fossiliferous, calcareous, medium gray shale containing one or two thin limestone beds.

- b. Delphi Station Member - At most localities this member is about 125 feet thick, except at Rainbow Creek where 145 feet is measured. It is a dark gray shale in its lower portions containing abundant irregularly shaped, calcareous, non-septarian, unfossiliferous concretions from 1 to 5 inches in diameter. The dark shales pass upward into slightly calcareous siltstones abounding in bivalves (clams). The contact with the overlying Pompey is sharp.
- c. Pompey Member - The Pompey Member is 60 feet thick, with the exception of the exposure in Bare Mountain Ravine, where it is about 114 feet thick, probably due to faulting. It is a dark gray to grayish black shale at its base grading upward to silty shale and finally siltstone at the top. Concretions occur more or less throughout the section, but are especially conspicuous in the upper 5 feet. Most of them are small, rounded, non-septarian and calcareous, and less than 4 or 5 inches in diameter. Although some fossils may be found on the periphery of the concretions, few are fossiliferous internally. The upper 20 feet of the Pompey contains abundant pyrite as nodules and disseminated particles
- d. Butternut Member - The characteristic feature of the lower and middle Butternut is that it is a "paper shale", i.e., it splits into thin flakes, a distinct change from the underlying Pompey Member. Upward, this lithology is gradually replaced by silty shales interbedded with thin siltstone bands and lenses. The lenses vary in size from 3 feet long with maximum thickness of 1 inch, to 24 feet long with a maximum thickness of 6 inches. The lenses are cross-bedded at their bases only. Higher in the section, the silty shale gradually gives way to siltstone and the uppermost 4 or 5 feet of the Butternut is

a calcareous flaggy siltstone. The contact with the overlying Centerfield Member is transitional and difficult to place. The Member is approximately 135 feet thick.

B15. The Skaneateles formation is exposed in virtually all the ravines mentioned above for the Marcellus, only in the middle and upper reaches of these ravines, usually above the first waterfall, which is held up by the Mottville Member. Therefore, it forms the middle slopes of the valley sides in the vicinity of the dam.

Ludlowville Formation

B16. The Ludlowville Formation is the most fossiliferous formation in the Tully Valley. It consists of intertonguing silty shales and siltstones and, on the basis of these, can be divided, above the Centerfield Member, into four members.

- a. Centerfield Member - In the Tully Valley area, the Centerfield Member is a coarse siltstone about 25 feet thick. The lower and upper 10 feet are flaggy but the middle portion is massive. Only the middle portion is highly calcareous and fossiliferous. The siltstone beds in the flaggy parts are about 1 inch thick and at some localities crossbedded. The contact with the overlying Otisco is sharp.
- b. Otisco Member - This unit is a soft, thinly bedded, slightly calcareous, silty, medium-gray to medium-dark-gray shale, which is interbedded toward the top with thin siltstone beds. The contact with the Ivy Point Member, about 165 feet above the Centerfield, is sharp. This member is especially interesting for two coral biostromes which have been given submember status by Oliver (1951). The lower, designated the Staghorn Point Submember, is about 7 feet thick in the Tully Valley. The Staghorn Point occurs about 50 feet above the top of the Centerfield and rests on a massive

calcareous siltstone platform about 3 feet thick. The upper biostrome, named the Joshua Submember, varies from 0 to 55 feet in thickness in the Tully Valley. It covers some 40 square miles, less extensive than the Staghorn Point Submember.

- c. Ivy Point Member - This member is about 36 to 37 feet thick and is dominantly a flaggy, slightly calcareous, gray siltstone, that weathers to a distinct yellowish-brown color. Most of the siltstone beds are approximately 1 inch thick. Spheroidal, calcareous, nonseptarian, unfossiliferous concretions 3 to 18 inches in diameter are present in the lower 20 feet.
- d. Spafford Member - The Spafford Member consists of 27 feet of thin-bedded, gray to dark gray shale and silty shale sharply overlying the coarse Ivy Point Member. Although the Spafford becomes coarser upward, the upper 3 feet are very fine-grained.
- e. Owasco Member - This is a calcareous, massive siltstone bed 2 feet thick.

B17. The Ludlowville Formation makes up the upper slopes of the Tully Valley and is best exposed in Lords Hill Ravine, and in Emerson Gulf and Fellow Falls Ravines south of Bare Mountain Ravine.

Moscow Formation


B18. Exposures of the lower 70 feet of the Moscow Formation are difficult to find in the Tully Valley. Even where this portion crops out in a ravine, the exposure is poor and incomplete. Therefore, this interval could not be examined thoroughly and much of the remarks pertaining to the Portland Point and lower and middle Windom Members were derived from the study of a single section. The upper 80 feet of this formation is well exposed as it occurs in high waterfalls capped by the resistant Upper Devonian Tully Limestone.


- a. Portland Point Member - The upper and lower contacts of the Portland Point Member are sharp. A basal crinoidal, shelly limestone about 1 foot thick is succeeded by 11 feet of gray, silty shale, interbedded with thin, crinoidal, shelly limestone bands 2 inches thick or less and about 8 inches apart. The silty shales are not very fossiliferous.
- b. Windom Member - The Windom Member is a thin-bedded, gray to medium-gray shale grading upward to medium-gray silty shale to a point 20 feet below the Tully. Here a sharp lithologic change to a medium-gray to dark gray or grayish black, non-calcareous, pyritiferous shale takes place and this is in turn sharply overlain by the Tully Limestone. This dark shale appears as a reddish orange zone beneath the Tully due to the weathering of the pyrite.

B19. The Windom is 163 feet thick in the Tully Valley. The Moscow Formation is exposed at the tops of the hills south of U.S. Route 20 such as Bare Mountain. It is well exposed in the vicinity of the Village of Tully in ravines and road cuts.

Upper Devonian - Senecan & Chautauquan Series

B20. The Upper Devonian sequence begins with the Tully Limestone exposed at the tops of the highest hills, at about El. 1,600 feet just south of the dam such as at Bare Mountain. However, the well developed and best exposed Upper Devonian does not occur until south of the village of Tully. The Upper Devonian is judged to be relatively far removed from the site and therefore no details of the stratigraphy will be given other than those shown on Table II and in Appendix A.






GEOLOGIC LEGEND:

<u>STRATUM NO.</u>	<u>GENERALIZED GEOLOGIC DESCRIPTION</u>
(1)	FLUVIAL OVERBANK
(2)	DELTAIC
(3)	LACUSTRINE
(4)	GLACIAL TILL
(5)	BEDROCK

PROFI

- I. STRATA LINES ARE GRAPHS FROM SUBSURFACE CORE LOCATIONS. ACTUAL CORES MAY VARY. QUESTION OF UNCERTAINTY.
 2. SEE TEXT FOR DISCUSSION.
 3. INDIVIDUAL SOIL DESCRIPTIONS CORP OF ENGINEERS PLATE STRATA LINES AND GEOLOGY OF NEW YORK, MARCH 19

WEST ← → EAST



~~REF ID: A623103~~

DRILLING LOG			PROJECT ONONDAGA DAM		LOCATION NORTH CENTRAL			PROJECT BUFFALO DISTRICT			HOLES NO. D82-101 OF 7 SHEETS		
C. PROJECT ONONDAGA DAM			E. LOCATION STA. HUSK 110 COORD N 53°2'73 E 13°56'78		F. DRILLING TYPE OF SET MSL			G. DEPTH OF HOLE MOSI DRILL D-56 SER 61674			H. NUMBER OF DRILLING CYCLES 4A		
D. DRILLER PARKER-WOLFF INC.			E. NUMBER OF DRILL CYCLES AND CYCLE TIME		F. DEPTH OF HOLE MOSI DRILL D-56 SER 61674			G. TOTAL NUMBER OF CYCLES 1			H. ELEVATION DURING CYCLES		
G. NAME OF DRILLER A. J. BECK			H. DEPTH OF HOLE MOSI DRILL D-56 SER 61674		I. DATE HOLE 28 JULY 1982			J. COMPLETED 6 AUGUST 1982			K. ELEVATION TOP OF HOLE 525.8 ft		
G. INCLINATIONS OF HOLE VERTICAL <input checked="" type="checkbox"/> INCLINED _____ DEG. FROM VERT.			L. THICKNESS OF OVERBURDEN 103.3 ft		M. TOTAL CYCLE RECOVERY FOR CYCLES			N. SIGNATURE OF INSPECTOR H. A. V. (HEAD OF NEW YORK)			O. REMARKS ADVANCE BORING W/ 375IN ID HOLLOW STEM AUGERS W/PLUG, MFG CME DRIVE 30X35X38IN SPLIT SPOON W/ 300 HAMMER FALLING FREE 18IN DRIVE 2.0 ft REC 1.6 ft LOSS 0.4 ft		
G. TOTAL DEPTH OF HOLE 1037.8			P. DEPTH DRILLED INTO ROCK 2.4 ft		Q. TOTAL CYCLE RECOVERY FOR CYCLES			R. SIGNATURE OF INSPECTOR			S. REMARKS DRIVE 2.0 ft REC 2.0 ft LOSS 0.0 ft		
ELEVATION	DEPTH	LEGEND	CLASSIFICATION OF GROUND (Description)			DRIVE CYCLES	REC CYCLES	LOSS CYCLES					
525.8	0'	SET	Coarse to fine sandy			B	JAR						
	8		GRAVEL, little silt, medium			A		1					
	15		dense, dry, brown			G							
	24		GM			I							
523.8	2	SET	Gravelly coarse to fine			B							
	48		SAND, little silt, very			A	JAR						
	52		dense, dry, brown			G		2					
	31		SM			2							
521.8	44	SET	Silty coarse to fine			B							
	9		SAND, little gravel,			A	JAR						
	10		medium dense,			G		3					
	34		damp, brown			3							
	6	SET	SM			60							
519.0	57		Gravelly SAND, little silt,			B	JAR						
	67		very dense, damp, brown			A		4					
	103		SM			68		68					
	8		Gravelly SAND, little silt,			B	JAR						
	60		very dense, damp,			A		5					
	9		brown			G		29					
	10		SM			4	JAR						
	60					6							
	9					69		8.9					
	10												
BIG FORM 1836 PREVIOUS EDITIONS ARE OBSOLETE MAR 71			PROJECT ONONDAGA DAM			PROJECT ONONDAGA DAM			HOLES NO. D82-101				

REPLACEMENT

DRILLING LOG (Cont Sheet)			SEVEN FEET OF HOLE	525.8 ft MSL	Hole No.	D82-101	
PROJECT ONONDAGA DAM			INSTALLATION BUFFALO DISTRICT		SHEET 2 OF 9 SHEETS		
ELEVATION	DEPTH	LOGGING	CLASSIFICATION OF MATERIALS (Description)		S. CORE RECOV. %	HOW OR SAMPLE NO.	REMARKS (Drilling time, water loss, depth of overburden, etc., if significant)
10	102	SET	Gravelly coarse to fine SAND		10.0	10.0	ADVANCE BORING TO 3.75 IN ID HOLLOW STEM AUGER MFG-CME
11	113		little silt, medium-dense damp, brown	SM	B	JAR 7	DRIVE 2.0 ft REC 0.0 ft LOSS 0.0 ft
12	117				A		3.0X3.5X38 SPOT SPOON SECTION W/ 350 LB HAMMER
12	128				C		
13					G		ADVANCE BORING TO 15.0ft w/ 3.75IN ID HOLLOW STEM AUGER w/PLUG. MFG-CME
14					5	NS	
15		SET	Gravelly coarse to fine SAND, little silt, very dense, damp, brown	SM	A.0		DRIVE 1.2 ft REC 1.2 ft LOSS 0.0 ft
16	138				JAR B		NOTE LARGE GRAVEL PARTICLE IN NOSE OF SPOON
16	150				C.2		
17					B		ADVANCE BORING TO 20.0ft w/ 3.75IN ID HOLLOW STEM AUGER w/PLUG. MFG-CME
18					A		
19					G	NS	
20		SET	Gravelly coarse to fine SAND, little silt, very dense damp, brown	SM	5		
20	160				20.0	20.0	DRIVE 0.9 ft REC 0.9 ft LOSS 0.0 ft
20	170				20.9	20.9	
21						NS	
22							

ENG FORM 1036-A
APR 67

PROJECT
ONONDAGA DAM

HOLE NO.
D82-101

DRILLING LOG (Cont Sheet)			LEVATION TOP OF HOLE	325.8 ft MSL	Hole No. D82-101	Page 3 of 9 Sheets
PROJECT	LOCATION	CLASSIFICATION OF MATERIALS (Description)	% CORE RECOV.	BAR OR SAMPLE NO.	REMARKS (Drilling time, cutter bit, depth of overburden, etc. if significant)	
ONONDAGA DAM	ONONDAGA DISTRICT					
503.3	22	Granular coarse to fine SAWD. fine silt, very dense, damp brown - SM	22.5			ADVANCE BORING TO 25 ft w/ 3.75 IN ID HOLLOW STEM AUGER w/PLUG MFG-CME
	23			NS		SAMPLING CONDUCTED w/ 3.0 x 3.5 x 38 IN SPIT SHOT DRILL BY 360 lb KAMMAGIIL FALCON FREE 18IN
	24					
	25	fine to sand, some SAWD, silt fine gravel, fine silt very compact, damp, brown SP	25.0 25.0	B A C 6	JAR 10	DRIVE 0.9 ft REC 0.9 ft LOSS 0.0 ft
	26		25.5	25.5		
	27			NS		DRILLER NOTES HAR LESS DENSE @ APPROX 27A, AT APPROX 28.5A HAR BECOMES MORE DENSE.
497.3	28		28.5			ADVANCE BORING TO 30.0 ft w/ 3.75 IN ID HOLLOW STEM AUGER w/PLUG. MFG-CME
	29					DRILLER NOTES HARD MATL ENCOUNTERED FROM APPROX 29 to 30 ft
	30	Coarse to fine sandy GRAN with silt, very dense, damp brown - GM	30.0 30.0	B A G 7	JAR 11 31.3	DRIVE 1.3 ft REC 1.3 ft LOSS 0.0 ft
	31	SET				
	32					
	33					
	34					

END FORM 1020-A

ONONDAGA DAM

Hole No.
D82-101

DRILLING LOG (Cont Sheet)				ELEVATION TOP OF HOLE		S35 8 ft MSL		Hole No. D82-101	
PROJECT ONONDAGA DAM				INCHES		feet		inches	
ELEVATION	DEPTH	USING	CLASSIFICATION OF MATERIALS (Description)	% CORE RECOV.	BOX OR SAMPLE NO.	DRILLER'S (Drilling time, cutter loss, depth of overburden, etc. of significance)			
"	"	"	"	"	"	"	"	"	
	34								
	35	SET	Coarse to fine sandy GRAVEL, little silt, very dense, damp, brown	B A G	JAR 12 7	ADVANCE BORING TO 35.0 ft w/ 3.75 IN ID HOLLOW STEM AUGER w/ PLUG MFG-CME			
	36	SD	GM			35.0	DRIVE 1.4 ft REC 1.9 ft LOSS 0.0 ft		
	37					36.9			
	38								
	39								
	40	SET	Coarse to fine sandy GRAVEL, little silt, very dense damp, brown			40.0	ADVANCE BORING TO 40.0 ft w/ 3.75 IN ID HOLLOW STEM AUGER w/ PLUG MFG-CME		
	40	SD	GM			40.7	SAMPLING CONDUCTED w/ 3.0 x 3.5 x 38 IN SPLIT SPOON DRIVEN BY 35016 HAMMER FALLING FREE 18 IN. MAT. APPEARS TO BE MORE DENSE AT APPROX 37 ft.		
	41								
	42								
	43								
	44								
	45	SET	Gravelly, coarse to fine SAND, little silt, very dense, damp, brown	B A G	JAR M 8	42.5	45.0	DRIVE 0.7 ft REC 0.7 ft LOSS 0.0 ft	
	45	SD	SM						
	46								
DNR FORM 1886-A REV 6/7				PROJECT		HOLE NO.		ONONDAGA DAM	
								D82-101	

DRILLING LOG (Cont Sheet)				ELEVATION TOP OF HOLE	515.86' MSL	Hole No.	D82-101
PROJECT	ONONDAGA DAM	INSTALLATION	BUFFALO TWISTED			SHEET OF 9 SHEETS	
ELEVATION	DEPTH	LOGGING	CLASSIFICATION OF MATERIALS (Description)	% CORED	NO. OR SAMPLE NO.	NOTES (Drilling time, water loss, depth of overburden, etc., if significant)	
	46	50	Gravelly coarse to fine SAND, little silt, very dense, damp, brown SM		46-3		
	47						
	48						
	49						
	50	SET	Gravelly coarse to fine SAND, little silt, very dense, moist, brown		50.0	ADVANCE BORING TO 50.0ft w/ 3.75IN ID HOLLOW STEM AUGER w/PLUG MFG-CME SAMPLING CONDUCTED BY 30x35x35DU DRIVEN W/ 33DIB HAMMER PRACTICALLY FREE 18IN.	
	51	30			JAR	DRIVE 2.0 ft REC 1.7 ft LOSS 0.3 ft	
	52	37			15		
	53	45			53.0	52.0	
	54						
470.8	55			55.0	55.0	ADVANCE BORING TO 55.0ft w/ 3.75IN ID HOLLOW STEM AUGER w/PLUG MFG-CME	
	56	SET	Fine sandy SILT, little clay, medium dense, moist, brown		56.0	DRIVE 2.0 ft REC 1.8 ft LOSS 0.2 ft	
	57	10			JAR		
	58	10			6		
	59	13			6		
	60				9		
	61				57.0	57.0	
	62						
	63						
	64						
	65						
	66						
	67						
	68						
	69						
	70						
	71						
	72						
	73						
	74						
	75						
	76						
	77						
	78						
	79						
	80						
	81						
	82						
	83						
	84						
	85						
	86						
	87						
	88						
	89						
	90						
	91						
	92						
	93						
	94						
	95						
	96						
	97						
	98						
	99						
	100						
	101						
	102						
	103						
	104						
	105						
	106						
	107						
	108						
	109						
	110						
	111						
	112						
	113						
	114						
	115						
	116						
	117						
	118						
	119						
	120						
	121						
	122						
	123						
	124						
	125						
	126						
	127						
	128						
	129						
	130						
	131						
	132						
	133						
	134						
	135						
	136						
	137						
	138						
	139						
	140						
	141						
	142						
	143						
	144						
	145						
	146						
	147						
	148						
	149						
	150						
	151						
	152						
	153						
	154						
	155						
	156						
	157						
	158						
	159						
	160						
	161						
	162						
	163						
	164						
	165						
	166						
	167						
	168						
	169						
	170						
	171						
	172						
	173						
	174						
	175						
	176						
	177						
	178						
	179						
	180						
	181						
	182						
	183						
	184						
	185						
	186						
	187						
	188						
	189						
	190						
	191						
	192						
	193						
	194						
	195						
	196						
	197						
	198						
	199						
	200						
	201						
	202						
	203						
	204						
	205						
	206						
	207						
	208						
	209						
	210						
	211						
	212						
	213						
	214						
	215						
	216						
	217						
	218						
	219						
	220						
	221						
	222						
	223						
	224						
	225						
	226						
	227						
	228						
	229						
	230						
	231						
	232						
	233						
	234						
	235						
	236						
	237						
	238						
	239						
	240						
	241						
	242						
	243						
	244						
	245						
	246						
	247						
	248						
	249						
	250						
	251						
	252						
	253						
	254						
	255						
	256						
	257						
	258						
	259						
	260						
	261						
	262						
	263						
	264						
	265						
	266						
	267						
	268						
	269						
	270						
	271						
	272						
	273						
	274						
	275						
	276						
	277						
	278						
	279						
	280						
	281						
	282						
	283						
	284						
	285						
	286						
	287						
	288						
	289						
	290						
	291						
	292						
	293						
	294						
	295						
	296						
	297						
	298						
	299						
	300						
	301						
	302						
	303					</td	

DRILLING LOG (Core Shot)				DEPTH TO TOP OF HOLE	525.8 ft MSV	Hole No. DB2-101
PROJECT	DEPTH	LEGEND	CLASSIFICATION OF MATERIALS (Description)	% CORE RECOV.	SAMPLE NO.	NOTES (Drilling time, cutter use, depth of overburden, etc., if applicable)
MONDAGA DAM	58					ADVANCE BORING TO 60.0 ft W/3.5IN ID HOLLOW STEM AUGER w/PLUG MFG CME
	59				NS	DRIVE 1 1/8 x 2.0 x 27 1/2 IN STANDARD SPLIT SPON W/140 lb SAFETY HAMMER FALLING FREE 30IN
	60.0			60.0		
465.8	60	SET	Fine sandy SILT + CLAY trace fine gravel & coarse to medium sand in layers, medium dense, moist, brown	JAR	17	DRIVE 2.0 ft REC 1.2 ft LOSS 0.8 ft
	61	9				
	62	8				
	63	8	CL			
463.8	62	SET	Silty fine SILT, loose, moist, brown	JAR	18	DRIVE 2.0 ft
	63	SM			62.5	REC 2.0 ft
	64	9	Silt CLAY, little fine sand, trace organics, hard, moist, brown	JAR	19	LOSS 0.0 ft
	65	13				
	66	17				
	67	SET	Silty CLAY, little fine sand, trace organics, hard, moist, brown	JAR	20	DRIVE 2.0 ft
	68	11				REC 1.7 ft
	69	65	CL			LOSS 0.3 ft
460.3	65	SET	Silt, CLAY, little coarse to fine sand, hard, moist, brown		65.5	
459.8	66	24	Cl		66.0	
	67	SET	Coarse to fine sandy GRAVEL, little silt, medium dense, moist, brown	JAR	21	DRIVE 2.0 ft
	68	13			68.0	REC 0.8 ft
	69	17				LOSS 1.2 ft
	70	SET	Coarse to fine sandy GRAVEL, little silt, medium dense, moist, brown	B		DRIVE 3.0 x 3.5 x 30 "
	71	15			4	SPLIT SPON WITH 3 1/2 IN HAMMER
	72	22			G	FREE FALLING 18IN
	73	21	GM		10	DRIVE 2.0 ft
						REC 1.8 ft
						LOSS 0.2 ft

DRILLING LOG (Cont Sheet)				EL ELEVATION TOP OF HOLE	525.84 MSL	Hole No. D82-101
PROJECT	ONONDAGA DAM	INSTALLATION	BUFFALO DISTRICT	SHEET	9	OF 9 SHEETS
EL ELEVATION	DEPTH	LEGEND	CLASSIFICATION OF MATERIALS (Description)	% CORE RECOV. EST.	DATA ON SAMPLE NO.	REMARKS (Drilling time, water loss, depth of overburden, etc., if applicable)
	70	SET	Coarse to fine sandy GRAVEL, little silt, medium dense, wet, brown	B	70.0	DRIVE 3.0x 3.5x 38" SPLIT SPON W/ 350lb HAMMER FALLING FREE 18IN
	18		GM	A		DRIVE 2.0 ft
	18		GM	G	24	REC 2.0 ft
	25		Coarse to fine sandy GRAVEL		72.0	LOSS 0.0 ft
	25	SET	little silt, medium dense, wet, brown	JAR		DRIVE 2.0 ft
	19		GM	25		REC 1.0
452.8	73	25	Medium to fine SAND, trace coarse sand, trace silt, dense, wet, brown	JAR	73.0	LOSS 1.0
	25	SP		26		WATER INTRODUCED IN BOREHOLE IN ORDER TO RETAIN HYDROSTATIC HEAD.
	25	SET		740		DRIVE 1 1/8x 2.0x 1 1/2"
	18					STANDARD SPLIT SPON W/ 140lb SAFETY HAMMER FALLING FREE 30IN
450.8	75	21	Coarse to fine SAND, little gravel, little silt, dense, moist, brown	JAR	75.0	DRIVE 2.0 ft
	25	SM		28		REC 0.7 ft
	25	SET	Coarse to fine sandy GRAVEL, trace silt, very dense, wet, brown	B		LOSS 1.3 ft
	31		GW	A		DRIVE 3.0x 3.5x 38" SPLIT SPON W/ 380lb HAMMER FALLING FREE 18IN.
	29		GW	G	29	DRIVE 2.0 ft
	31			11		REC 2.0 ft
447.8	78	32	Silty coarse to fine SAND little gravel, very dense damp, brown	JAR	78.0	LOSS 0.0 ft
	53		SM	30		2 AUGUST 1982 AM
	75					DEPTH TO BOTTOM OF CSG 780ft DEPTH TO WATER 470ft CONTRACTOR HAS REQUESTED THE STATION NUMBER ROTATED SERIAL # 146205 PULL NUMBER BACK TO 75# SET NEW CSG 3 1/2 IN 20 AT 77 1/2 DECREASING TO 8.0ft W/ 350lb HAMMER FILLING STREG 2 1/2" CATING CLEANED OUT W/ 12" CURE ROLLER BIT MADE TO SPECIFICATIONS
	43					1/2
	44		SM	PO.C		DRIVE 2.0 REC 0.5 LOSS 1.5
445.8	80	SET	Gravelly coarse to fine SAND, little silt, very dense, wet, brown	JAR	80.0	DRIVE 1 1/8x 2.0x 27% TN
	48			31		STANDARD SPLIT SPON W/ 140lb SAFETY HAMMER FILLING
	81		SM			FREE 30IN
	59					DRIVE 2.0 ft
	62					REC 1.2 ft
	40					LOSS 0.8 ft

DRILLING LOG (Cont'd Sheet)				REACHING TOP OF HOLE	525.8 ft. MSL	Hole No. D82-101
PROJECT ONONDAGA DAM		LOCATION BUFFALO DISTRICT				Aug 8 of 8 hours
DEPTH	WEIGHT	CLASSIFICATION OF MATERIALS (Description)	% CORE RECOVERED	NO. OR SAMPLE NO.	REMARKS (Drilling time, motor load, depth of overburden, etc., if significant)	
82	SET		81.0		3 AUGUST 1958 AM CAB @ 20.0 DEPTH TO WATER 65.1 ft BOREHOLE ADVANCED W/ CASE 75 TUCKMANIC ROTARY SENSIT 8 154115 ADVANCE BOREHOLE IN DRILLING ADVANCE BOREHOLE W/ 350 lb HAMMER FALLING FREE 2.4 IN BOREHOLE WASHER PULLED TO SAWBLADE W/ TITANIC ROLLER REC. DRIVE 2.0 REC 0.8 loss 1.2	
83	33	Gravelly coarse to fine SAND, little silt, very dense, wet, brown SM	JAR 32			
84	18		84.0		DRIVE 1 1/2X 2.0X 27 1/2 IN STANDARD SPOT SPOON	
85	17	Gravelly coarse to fine SAND, little silt, very dense, wet, brown SM	JAR 33		4 1/2X 16 SAFETY HAMMER FALLING FREE 30 IN DRIVE 2.0 ft REC 0.7 ft LOSS 1.3 ft	
86	28		86.0		DRIVE 2.0 ft REC 0.8 ft LOSS 1.2 ft	
87	26		JAR 34			
88	34	Gravelly coarse to fine SAND, little silt, very dense, wet, brown SM	88.0		DRIVE 2.0 ft REC 0.5 ft LOSS 1.5 ft	
89	35		JAR 35			
90	30	Gravelly coarse to fine SAND, little silt, very dense, wet, brown SM	90.0		DRIVE 2.0 ft REC 0.5 ft LOSS 1.5 ft	
91	26		JAR 36		NOTE: LARGE GRAVEL PIECES OFTEN FOUND LODGED IN SPOON, SAMPLES FROM 78.0 TO 76.0 ft	
92	29	Gravelly coarse to fine SAND, little silt, very dense, wet, brown SM	92.0			
433.8	92		JAR 37		DRIVE 2.0 ft REC 0.5 ft LOSS 1.5 ft	
			94.0			

END FORM 1836-A

ONONDAGA DAM D82-101

DRILLING LOG (Core Sheet)				DEPTH TO TOP OF HOLE	525.874 MSL	Hole No. D82-101
DEPTH	LEADER	CLASSIFICATION OF MATERIALS (Description)	RECORDS	BOX OR SAMPLE NO.	REMARKS	CSG FOOT
	c	d	RECOV. DTY		(Drilling date, recovery date, depth of penetration, etc., if significant)	
429.8	97	SET Silty coarse to fine SAND, little gravel, very dense, wet, brown	JAR 38	94.0	DRIVE 1 1/2 x 2 1/2 STANDARD SET SPOON W/ 350/16 SAWBL 10MM SCREWING FREE 30 IN	33
	98	35			ADVANCE BOREHOLE W/ INCIDING DRIVE W/ 350/16 HAMMER PUNCHING	
	37	SM			FREE 24 IN DRIVE 2.0 ft	74
	34		96.0	96.0	REC 0.3 ft LOSS 1.7 ft	
430.8	97	SET Coarse to fine sandy GRAVEL, little silt, dense wet, brown	JAR 39		DRIVE 2.0 ft	26
	14				REC 0.7 ft	
	25	GM			LOSS 1.3 ft	37
	27		98.0			
	98	SET Coarse to fine sandy GRAVEL, little silt	JAR 40		DRIVE 2.0 ft	33
	22	dense, wet, brown			REC 0.8 ft	
	26	GM			LOSS 1.2 ft	37
	24		100.0	100.0		
425.8	100	SET Silty coarse to fine SAND, little gravel, dense, wet, brown	JAR 41		DRIVE 2.0 ft	37
	26	SIL			REC 0.6 ft	
	23				LOSS 1.4 ft	38
	24		102.0	102.0		
423.8	102	SET Coarse to fine sandy GRAVEL, little silt	JAR 42		DRIVE 1.3 ft	45
	25	Very dense, wet, brown			REC 0.4 ft	
	103	GM			LOSS 0.9 ft	
	100	APPROXIMATE TOP OF Rock 103.3	103.3	103.3	SPOON REVERSAL 103.3 ft	151
422.8	104	MARLINS LIMESTONE, OLNEY MEMBER LIMESTONE moderately hard, dense to finely crystalline, flat lying few stylolites, slightly weathered, solid, dark gray. Frequent fractures in the core are mechanical in nature caused by drilling.	PULL 1	103.8	ADVANCE CASTING TO 103.2 ft W/ 350/16 HAMMER CLEARING FREE 103.8 ft TO CLEAR PRESUMED OBSTRUCTION CUTTING STYLOLITIC ROCK. ATTEMPTED TO CORE W/ 1/2 IN. DOUBLE TAPERED BARREL (3% ID) BUT WAS UNAVAIL, DUE TO SEAT CASING AT BOTTOM OF OBSTRUCTION. ATTEMPTED TO CORE W/ 1/2 IN. DOUBLE TAPERED BARREL (1% ID) DRILLED 1.9 ft BEFORE CORE BARREL BROKE OFF, DRILLING TIME WAS 6 MIN/ft. HOLE WAS THICKENED AND CORE BARREL RECOVERED AT A LATER DATE. CORE HOLE CROPPED TO SURFACE.	
	105	PULL #1 RAN 1.9 ft REC 1.6 ft UNACCOUNTABLE LOSS 0.3 ft		105.7	TAKE 5.2 CUTTING 103.2 ft WHERE 65.2 ft	
420.4	106	BOTTOM OF BORING C 106.7 ft				

Hole No. DB2-102

DRILLING LOG	PROJECT ONONDAGA DAM		LOCATION STA 9-14-2 R 21 C 0000 N 53-07-55 E M 00-22	COLLECTION BUFFALO DISTRICT	SHOT or 15 INCHES
1. PROJECT	2. LOCATION		3. DRILL AND TYPE OF BIT	4. DRYER FOR ELEVATION DETERMINATION OF HOLE	
ONONDAGA DAM			CORE 75' SERIAL NO 154115	NAD 27	
			5. TOTAL LENGTH OF HOLE	DEPTH TESTED	UNDISTURBED
			78'		
6. NAME OF DRILLER W. ROSE / A. J. BECK	7. DIRECTION OF HOLE □ VERTICAL <input checked="" type="checkbox"/> INCLINED deg. FROM VERT.		8. TOTAL NUMBER CORE SAMPLES	9. ELEVATION GROUND WATER	
			—	—	
			10. DATE HOLE STARTED	COMPLETED	
			5/10/82	5/16/82	
			11. ELEVATION TOP OF HOLE	525.7	
			12. TOTAL CORE RECOVERY FOR BORING	—	
			13. INFORMATION OF INSPECTOR M. M. (MAINE NEW YORK)	—	
ELEVATION	DEPTH	LEGEND	CLASSIFICATION OF MATERIALS	AMOUNT OF SAMPLE TAKEN	REMARKS
525.7	0'	SET	Coarse to fine sandy GRAVEL, little silt, very dense, dry, brown GM	0.0	ADVANCE BORING w/ 9.75" DR ID HOLLOW STEM AUGER w/ PLUG-MFG-CME DRIVE 30x35=38 SPLIT SPAN w/ 350/15/HM FALLING SPARE REAM DRIVE 2.0 ft REC 1.5 ft LOSS 0.5 ft
	13			JAR 1	
	37			JAR 2	DRIVE 1.7 ft REC 1.7 ft LOSS 0.0 ft
	27			JAR 3	DRIVE 1.4 ft REC 1.4 ft LOSS 0.0 ft
	SET			NS 4.0	ADVANCE BORING TO 4.0 ft w/ 9.75" DR HOLLOW STEM AUGER w/ PLUG-MFG-CME
	35			JAR 4	DRIVE 14 ft REC 14 ft LOSS 0.0 ft
	50			JAR 5	DRIVE 19 ft REC 19 ft LOSS 0.0 ft
	50			NS 5.4	ADVANCE BORING TO 5.4 ft w/ 9.75" ID HOLLOW STEM AUGER w/ PLUG-MFG-CME
521.7	4	SET	Silty, coarse to fine sand little gravel, very dense, dry, brown SM	5.4	DRIVE 14 ft REC 14 ft LOSS 0.0 ft
	43			JAR 6.0	DRIVE 2.0 ft REC 2.0 ft LOSS 0.0 ft
520.3	5	SET	SM	6.0	DRIVE 2.0 ft REC 2.0 ft LOSS 0.0 ft
	50			JAR 7.0	DRIVE 1.9 ft REC 1.9 ft LOSS 0.0 ft
	6	SET	Gravelly, coarse to fine SAND, little silt, dense, damp, brown SM	7.0	DRIVE 1.9 ft REC 1.9 ft LOSS 0.0 ft
	42			JAR 8.0	DRIVE 1.9 ft REC 1.9 ft LOSS 0.0 ft
	36			JAR 9.0	DRIVE 1.9 ft REC 1.9 ft LOSS 0.0 ft
	32			JAR 10.0	DRIVE 1.9 ft REC 1.9 ft LOSS 0.0 ft
	8	SET	Gravelly, coarse to fine SAND, little silt, dense, damp, brown SM	10.0	DRIVE 1.9 ft REC 1.9 ft LOSS 0.0 ft
	20			JAR 11.0	DRIVE 1.9 ft REC 1.9 ft LOSS 0.0 ft
	27			JAR 12.0	DRIVE 1.9 ft REC 1.9 ft LOSS 0.0 ft
	50			JAR 13.0	DRIVE 1.9 ft REC 1.9 ft LOSS 0.0 ft

BNG FORM 1836 PREVIOUS EDITIONS ARE OBSOLETE.
MAR 71 (TRANSPARENCY)PROJECT
ONONDAGA DAM
HOLE NO.
DB2-102

DRILLING LOG (Cont Sheet)			REACHES TOP OF HOLE	525.7 ft MSI	Hole No. DB2-102	
ELEVATION	DEPTH	LOGGED	CLASSIFICATION OF MATERIALS (Description)	B. CORE REC'D. BY	CORE NO. OR SAMPLE NO.	REMARKS (Drilling time, water loss, depth of overburden, etc., if significant)
10	35'	SET	Gravelly coarse to fine SAND, little silt, very dense, damp, brown	B	10.0	DRIVE 0.8 ft
	50			A	JAR	REC 0.8 ft
11				G	6	LOSS 0.0 ft
			SM	2	10.8	
					10.8	ADVANCE BORING TO 11.0 ft w/ 3.75 in. HOLLOW STEM AUGER w/ PLUG MFG-CME DRIVE 3.0-3.5 ft 30 ft SHEATHED w/ 35 ft. MASON FREIGHT RAIL BTW
12				NS		
				12.0	12.0	
13	SET	Gravelly coarse to fine SAND, little silt, very dense, damp, brown				
	37			JAR	7	
14	50			B		DRIVE 1.9 ft
	50		SM		13.9	REC 1.9 ft
				A	14.0	LOSS 0.0 ft
15	SET	Gravelly coarse to fine SAND, little silt, very dense, damp, brown		G		DRIVE 2.0 ft
	48			JAR	8	REC 2.0 ft
16	48			G	8	LOSS 0.0 ft
	48		SM	3		GAUG 1982
17	37					CONTR. DR. SURVEYED TO C. 1983; SECTION 4 139795
18	SET	Gravelly coarse to fine SAND, little silt, very dense, damp, brown		NS		
	58			16.0		DRIVE 0.4 ft REC 0.4 ft SHEATHED w/ 35 ft. MASON
19	50			NS		REC 0.4 ft
			SM			ADVANCE BORING TO 16.0 ft w/ 3.75 in ID HOLLOW STEM AUGER w/ PLUG MFG-CME
20	SET	Gravelly coarse to fine SAND, little silt, very dense, damp, brown		NS		
	58			8.0		DRIVE 1.3 ft
21	50			JAR	10	REC 1.3 ft
			SM		LOSS 0.0 ft	
22	SET	Gravelly coarse to fine SAND, little silt, dense, moist, brown		NS		ADVANCE BORING TO 20.0 ft w/ 3.75 in ID HOLLOW STEM AUGER w/ PLUG MFG-CME
	12			11.3		
23	21			NS		
			SM	20.0		DRIVE 2.0 ft
24	34			SAR	11	REC 1.3 ft
503.7	34					LOSS 0.7 ft

DRILLING LOG (Core Sheet)			BETWEEN TOP OF HOLE	525.7 ft MSL	Hole No. D82-102
DEPTH	LOGGING	DESCRIPTION	TESTS	RESULTS	NOTES
503.7	23	SET Coarse to fine sandy GRAVEL, little silt, dense, damp, brown	22.0 B A G 4	22.0 JAR 12	ADVANCE BORING w/ 3.75 IN ID HOLLOW STEM AUGER w/ PLUG MF6-CME DRIVE 3.0x3.5x 36" SPIT SPUD w/ 350lb HAMMER FALLING FREE 10.5N DRIVE 2.0 ft REC 2.0 ft LOSS 0.0 ft
501.7	24	SET Medium to fine SILT, little silt, trace gravel, medium dense, damp, brown SM	24.0 24.5	24.0 JAR 13 15	DRIVE 1.7 ft REC 1.7 ft LOSS 0.0 ft
501.2	25	Coarse to coarse to fine SAND, little silt, very dense, damp, brown SM	25.5	JAR 14	
500.3	30	Medium to fine SAND, little silt very dense, damp, brown SM	25.4 16.0	25.4 JAR 15	ADVANCE BORING TO 26.0 m / 3.75 ft w/ HOLLOW STEM AUGER w/ PLUG MF6-CME
499.7	26	Coarse to fine sandy GRAVEL, little silt dense, damp, brown GM	26.5	26.0 JAR 16	DRIVE 2.0 ft REC 2.0 ft LOSS 0.0 ft
499.2	27	Medium to fine SAND, trace silt, trace gravel, very dense, damp, brown SP	26.5	26.5 JAR 17	
	28	Medium to fine SAND trace to 1/4 silt, trace gravel, very dense, damp brown	28.0	JAR 18	DRIVE 1.3 ft REC 1.3 ft LOSS 0.0 ft
	29	SP	28.0		
	30	Medium to fine SAND trace silt, trace gravel, very dense, damp, brown SP	30.0	NS	ADVANCE BORING TO 30.0 ft w/ HOLLOW STEM AUGER w/ PLUG MF6-CME
494.9	31	Medium to fine SAND trace silt, trace gravel, very dense, damp, brown SP	30.0 30.8	JAR 19 30.8 30.8	DRIVE 2.0 ft REC 2.0 ft LOSS 0.0 ft
	32	Coarse to fine sandy GRAVEL little silt, very dense, damp brown GM	30.8	JAR 20 32.0	
	33	Coarse to fine sandy GRAVEL, 1/4 silt, very dense, damp, brown GM	32.0	JAR 21 33.3	DRIVE 1.3 ft REC 1.3 ft LOSS 0.0 ft
	34		34.0	NS	ADVANCE BORING TO 34.0 ft w/ 3.75 in. ID HOLLOW STEM AUGER w/ PLUG MF6-CME

ANONIMO DIAZ 182-102

DRILLING LOG (Core Sheet)				ELAVATION TOP OF HOLE	525.7 ft MSL	Hole No.	DB2-102
PROJECT	DEPTH	LOGNO	CLASSIFICATION OF MATERIALS (Description)	INSTRUMENTATION		BUFFALO DISTRICT	
ELAVENION	DEPTH	LOGNO		% CORE RECOV.	BOX OR SAMPLE NO.	REMARKS	SHRIFT OF 15 SHEETS
	46	SET	Coarse to fine sandy GRAVEL, little silt, very dense, wet, brown GM	46.0	78A 28	DRIVE 0.9 ft REC 0.5 ft LOSS 0.4 ft	
	50			46.5	46.9		
478.8	47					ADVANCE BORING TO 48.0 ft W/ 3.75 IN ID HOLLOW STEM AUGER w/ PLUG DRILLER NOTES DIFFICULT AUGERING	
	48	SET	Gravelly coarse to fine SAND, little silt, very dense, wet, brown SM	B	48.0		
	50			A	JAR 29	DRIVE 0.8 ft REC 0.8 ft LOSS 0.0 ft	
	49			G	48.8		
	50			9		ADVANCE BORING TO 50.0 ft W/ 3.75 IN ID HOLLOW STEM AUGER w/ PLUG DRILLER NOTES DIFFICULT AUGERING	
	51				50.0		
	50	SET	Gravelly coarse to fine SAND, little silt, very dense, wet, brown SM		JAR 30	DRIVE 0.9 ft REC 0.9 ft LOSS 0.0 ft	
	51				50.9		
	52	50	Gravelly coarse to fine SAND, little silt, very dense, wet, brown SM		JAR 31 32	DRIVE 0.9 ft REC 0.9 ft LOSS 0.0 ft	
	53				51.0		
	54	SET	Gravelly coarse to fine SAND, little silt, very dense, wet, brown SM		N.S.	DRIVE 0.8 ft REC 0.6 ft LOSS 0.2 ft	
	55						
	56	SET	Gravelly coarse to fine SAND, little silt, very dense, wet, brown SM		54.0		
	57				JAR 32 54.8		
	58					ADVANCE BORING TO 56.0 ft W/ 3.75 IN ID HOLLOW STEM AUGER w/ PLUG AND CMC	
					56.0	DRIVE 0.6 ft REC 0.4 ft LOSS 0.2 ft	
					N.S.	ADVANCE BORING TO 58.0 ft W/ 3.75 IN ID HOLLOW STEM AUGER W/ PLUG NOTE: AUGERING DIFFICULT	

DRILLING LOG (Core Sheet)			ELEVATION TOP OF HOLE	525.7 ft MSL	Hole No. D82-102	
PROJECT	ONONDAGA DAM	PERIOD	BOUFFALO DISTRICT	15' DEPTHS	CSG BLDG PER HOT	
ELEVATION	DEPTH	LOGGING	CLASSIFICATION OF MATERIALS (Description)	% CORE RECOVERY	BOX OR SAMPLE NO.	REMARKS (Drilling time, water level, depth of overburden, etc. if applicable)
	58	SET	Gravelly coarse to fine SAND, little silt, very dense moist, brown SM	100 JAR 34 58.5	100 NS	DRIVE 0.5 ft REC 0.5 ft LOSS 0.0 ft HOLE 3.75 IN ID HOLLOW STEM AUGER W/PLUG MFG. CME
	59				A	
	60	SET	Gravelly coarse to fine SAND, little silt, very dense, moist, brown SM	60.0	G	ADVANCE BORING TO 60.0 ft w/3.75IN ID HOLLOW STEM AUGER W/PLUG MFG. CME
	61	50			JAR 35	
	36				61.7	
	50					AUGER 4-PLUG 6 1/4 USED CALCIUM TIT-COVA ROLLER BIT FROM 61.7 TO 63.0 ft ADVANCE 3.75IN ID HOLLOW STEM AUGERS TO 63.0 ft w/PLUG. SM & ROLLING SAND IN AUGER UNABLE TO CLEAN OUT AUGERS WITH CORE RECA OF ALL AUGERS TO 60.0 ft AND SET IN CASES 3 PLUGGED DRIVE CS TO 60.0 ft AND HOSE SAME CASES W/PLUGS SAMPLING W/1 1/2 IN 2.0 ft 27 G IN PLUGS THE 60.0 ft HOLE IS 200 ft DEEP
	62					35
	63					
461.7	61			64.0	64.0	
	65	SET	Coarse to fine sandy GRAVEL, little silt, very dense, wet, brown GM	65.5	JAR 36	DRIVE 2.0 ft REC 1.1 ft LOSS 0.9 ft
	44					72.5
460.2	25		Fine sandy SILT & CLAY very stiff, damp, gray CL	65.5	JAR 37	
	66	SET			66.0	
	14					32
	67		Fine sandy SILT & CLAY very stiff, damp, brown CL	66.0	JAR 38	DRIVE 2.0 ft REC 2.0 ft LOSS 0.0 ft
	15					39
	21					68
457.7	68			68.0		
	67	SET	SILT, little clay, trace medium to fine sand, medium dense, wet brown ML	68.0	JAR 39	DRIVE 2.0 ft REC 0.4 ft LOSS 1.6 ft
	14					
	12					
455.7	70	12		70.0		

DRILLING LOG (Cont Sheet)			ELAVATION TOP OF HOLE	525.7 ft MSL	Hole No. DB2-102	
ELAVATION	DEPTH	LEGEND	CLASSIFICATION OF MATERIALS (Description)	% CORE RECOV. BY	BOX OR SAMPLE NO.	REMARKS
455.7	70	SET	Silty fine SAND, trace 70.0 organics, wood & shell fragments, dense, moist, gray	70.0	JAR 90	DRIVE 2.0 ft REC 2.0 ft LOSS 0.0 ft
	15		SM			
	71					
	19					
454.2	71.5					
454.0	71.5					
453.7	71.5					
	14		Coarse-to-fine sand GRAVEL, little silt, trace organics, stiff, moist, gray GRAN 71.7	71.5	JAR 7041	
	14		Clayey SILT, little fine sand, trace fine sand, trace organics, stiff soil, moist, gray ALL 71.9	71.7	JAR 7042	
	14		71.9	71.9	JAR 71.0	DRIVE 2.0 ft REC 1.6 ft LOSS 0.4 ft
	17					
	28					
	18					
	74					
	15	SET	Silty coarse to fine SAND, trace ground debris, wet, gray	74.0	JAR 43	BORING ADVANCED WITH AN AUGER 3 1/16 IN ID DRIVEN WI 350 lb HAMMER FALLING RATE 2 1/2 IN SOUND CONDUCTED W/ 198.20x27.6 IN STANDARD SCHOTTER DRIVEN WI 100% HAMMER RATE 222 IN
	15		SM			
	25					
449.7	76	SET	Gravelly coarse to fine SAND, little silt, dense wet, gray	76.0	JAR 44	DRIVE 2.0 ft REC 1.1 ft LOSS 0.9 ft
	25		SM			
	15					
	13					
	78	SET	Gravelly coarse to fine SAND, little silt, trace wood fragments, medium dense, wet, gray	78.0	JAR 45	DRIVE 2.0 ft REC 1.1 ft LOSS 0.9 ft
	18		SM			
	79					
	16					
	15	SET	Gravelly coarse to fine SAND, little silt, trace wood fragments, medium dense, wet, gray	79.0	JAR 46	DRIVE 2.0 ft REC 0.8 ft LOSS 1.2 ft
445.7	80	SET	Silty coarse to fine SAND, little gravel, very dense, wet, brown	80.0	JAR 47	DRIVE 2.0 ft REC 0.8 ft LOSS 1.2 ft
	31		SM			
	33					
	82	28				

DRILLING LOG (Core Sheet)				DEPTH TO TOP OF HOLE	525.7 ft MSL	HOLE NO. D82-102
DEPTH	LOGNO	CLASSIFICATION OF MATERIALS (Description)	N. CORE RECOV. %	BOX OR SAMPLE NO.	SHAKES (Drilling noise, water loss, depth of overburden, no. of exposures)	BLAH PER FOOT
82	SET	Silty coarse to fine SAND, little gravel, very dense, wet, brown	82.0	JAR 48	DRIVE 2.0 ft REC 1.8 ft LOSS 0.2 ft	BB
83	38	SM	83.0			
84	30		84.0			
85	24		85.0			
431.7	86	Silty coarse to fine SAND, little gravel, dense, wet, brown	86.0	JAR 49	ROCK ADVANCED BY NW CASING 3 1/2 IN TD DRILLED W/3500 LB HAMMER FALTING FREE 2 1/2 IN SAMPLING CONDUCTED W/4600 LB HAMMER IN STANDARD SPOT SPOON DRILLED W/1400 LB SAWFET HAMMER FALTING FREE 30 IN	BB
87	21	SM	87.0	JAR 50	DRIVE 2.0 ft REC 1.1 ft LOSS 0.9 ft	BB
88	18	SM	88.0			
437.2	15	Gravelly coarse to fine SAND, little silt, dense wet, brown	88.5	JAR 51	DRIVE 2.0 ft REC 1.2 ft LOSS 0.8 ft	BB
436.7	89	22	89.0	JAR 52		
90	26	Gravelly coarse to fine SAND, little silt, very dense, wet, brown	90.0	JAR 53		
91	26	SM	90.0			
92	36	Gravelly coarse to fine SAND, little silt, very dense, wet, brown	91.0	JAR 54	DRIVE 2.0 ft REC 1.4 ft LOSS 0.6 ft	BB
93	29	SM	91.0			
94	28		92.0			
431.7	94	27	92.0	JAR 55	11 AUG 82 AM DEPTH TO BOTTOM OF CS 920 DEPTH TO WATER 41.3 DRIVE 2.0 ft REC 1.1 ft LOSS 0.9 ft	BB
94	19	SM	94.0	JAR 56		

DD FORM 1030-A

PROJECT
ONONDAGA DAMHOLE NO.
D82-102

DRILLING LOG (Cont Sheet)				ELEVATION TOP OF HOLE	525.7 ft MSL	Hole No.	DB2-102	CSC BLW PER FOOT
PROJECT	ONONDAGA DAM	LOCATION	BUCKEY DISTRICT	DEPTH	ft / 100' DEPTH	BOREHOLE	REMARKS	
ELEVATION	DEPTH	LEGEND	CLASSIFICATION OF MATERIALS (Description)	% COKE	BORE OR SAMPLE NO.	(Drilling time, impact loss, depth of overburden, etc., if significant)		
431.7	94	SET	Silty coarse to fine SAND trace gravel, dense, wet gray SM 94.0	99.0	JAR 56	DRIVE 2.0 ft REC 1.1 ft LOSS 0.9 ft		
430.7	95	21	95.0	95.0	JAR 57			87
430.2	25	Medium to fine SAND, little silt, trace coarse sand, dense wet gray SM 95.5		95.5	JAR 58			765
	25	96	Silty fine SAND, trace coarse to medium sand, dense, wet, gray SM	96.0	JAR 59	BOREHOLE ADVANCED w/ NW CASING 3 1/16 IN ID w/ 350 lb HAMMER FALLING FREE 2.4 IN SAMPLING CONDUCTED w/ 1 7/16 IN 27 1/2		54
	21	SET	Silty fine SAND, trace coarse to medium sand, dense wet, gray SM 97.0		JAR 60	STANDARD SPLIT SPOON SAMPLER DRIVEN w/ 100 lb SAFETY HAMMER FALLING FREE 30 IN. DRIVE 2.0 ft REC 1.2 ft LOSS 0.8 ft		67
	20	20	Coarse to fine SAND, little gravel, little silt, dense, wet, gray SM		JAR 61	DRIVE 2.0 ft REC 1.1 ft LOSS 0.9 ft		57
	18	SET	Coarse to fine SAND, little silt, little gravel, dense, wet, gray SM					65
	15			100.0	JAR 62	DRIVE 2.0 ft REC 1.4 ft LOSS 0.6 ft		81
	27	SET	Medium to fine SAND, little silt, dense, wet, gray SM 101.0		JAR 63			154
	29	46	Gravelly coarse to fine SAND, little silt, very dense, wet, gray SM 102.3		JAR 65	DRIVE 2.0 ft REC 1.1 ft LOSS 0.9 ft		65
	46	SET	Silty medium to fine SAND, medium dense, wet, gray SM 102.6		JAR 66			56
423.4	103	17	Coarse to fine SAND, little silt, little gravel, medium dense, wet, gray SM 103.0		JAR 67	DRIVE 2.0 ft REC 1.4 ft LOSS 0.6 ft		47
423.1	17	17						82
	15	104	Coarse to fine SAND, little silt, little gravel SM					
	14	SET						
	18	105						
	25	106						

DRILLING LOG (Core Sheet)				REMARKS TOP OF HOLE	525.7 ft MSL	Hole No. D82-102	CORE BLOCK PEA FOOT
PROJECT	ONONDAGA DAM	BOFFOLO DISTRICT			SHIRT	70	OR 1/2 SHIRT
EL ELEVATION	DEPTH	LEGEND	C	CLASSIFICATION OF MATERIALS (Description)	% CORE RECOV- ERY	BOX OR SAMPLE NO.	REMARKS (Drilling rates, recovery loss, depth of overburden, etc., if significant)
417.7	105	SET		Coarse to fine SAND, little gravel, little silt, dense, wet, gray SM		106.0	DRIVE 2.0 ft REC 1.3 ft LOSS 0.7 ft
	107	21				JAR	50
	107	26				68	SAMPLING CONDUCTED BY 1 1/2 X 2.0 X 27 1/2 IN STANDARD SPIT SPOON
	108	28					DRIED IN MD 16 SAFETY HAMMER, FALLING FREE
	108				108.0		DOWN
	109	SET		Silty fine SAND, trace coarse to medium sand, trace gravel, dense, wet, gray SM		JAR	DRIVE 2.0 ft REC 1.4 ft LOSS 0.6 ft
	110	22				69	
	110	31				110.0	
	111	SET		Silty fine SAND, trace gravel, trace coarse to medium sand, dense, wet, gray SM		JAR	DRIVE 2.0 ft REC 1.3 ft Loss 0.7 ft
	112	19				70	
413.7	112	29				112.0	
	112	30					
	113	SET		Coarse to fine sandy GRAVEL, little silt, very dense, wet, gray GM		JAR	13 AUG 82 AM DEPTH TO BOTTOM OF CSG 110.0 DEPTH TO BOTTOM OF HOLE 112.0 ft DEPTH TO TOP OF WATER 63.4 ft
	113	74				71	DRIVE 2.0 REC 0.5 LOSS 1.5
	113	21					
	114	20				114.0	
	114	SET		Coarse to fine sandy GRAVEL, little silt, very dense, wet, gray GM		JAR	DRIVE 2.0 ft REC 1.1 ft LOSS 0.9 ft
	115	60				72	ROLLER BIT USED TO CLEAR POSSIBLE OBSTRUCTION. CASING ADVANCED TO 116.0 ft
	115	75					
	116	75				116.0	
	116	SET		Coarse to fine sandy GRAVEL, little silt, very dense, wet, gray GM		JAR	DRIVE 0.6 ft REC 0.6 ft LOSS 0.0 ft
	116	73				73	
	116	116				116.6	
	117					NS	USED THE CONE GRAVEL BIT TO 118.0 ft AND RESUMED SAMPLING.
	118						

WFO FORM 1836-A

000-1000-000-000

PROJECT

ONONDAGA DAM

HOLE NO.
D82-102

DRILLING LOG (CONT Sheet)			ELEVATION TOP OF HOLE	225.7 ft MSL	HOE NO. DB2-102	
PROJECT	ONONDAGA DAM	BUFFALO DISTRICT	DEPTH	11 015' DEPTHS	CSC BLDG PER FOOT	
ELEVATION	DEPTH	LOGNO	CLASSIFICATION OF MATERIALS (Description)	% CORE RECOVERED	BOX OR SAMPLE NO.	REMARKS (Driving force, water level, depth of overburden, etc., of significance)
405.2	118	SET			118.0	DRIVE 2.0 ft REC 0.0 ft LOSS 2.0 ft
	119	77			NS	NOTE: COBBLE DRIVEN AHEAD OF SPOON TRI-CONE ROLLER BIT WAS USED TO ADVANCE CASING TO
	120	88			120.0	120.0 ft
		25	Coarse to fine sandy GRAVEL, interbedded, very dense, wet, gray Gx 120.5		JAR 74	TAUG 1982 AM
		SET			120.5	DEPTH TO BOTTOM OF CSC 120.0
	121	21	Fine sandy SILT, dense, wet, red-brown ML		JAR 75	DEPTH TO WATER 85.9 ft
	122	10				120.0
		9				DRIVE 2.0 ft REC 1.2 ft LOSS 0.8 ft
		SET	Fine sandy SILT, trace medium sand, very stiff, damp, red-brown ML 122.5		122.0	DRIVE 2.0 ft REC 1.2 ft LOSS 0.8 ft
	123	27	Silty fine SAND, very dense wet, red-brown		JAR 76	BOILING ADVANCED W/NW FLUSH JOINT CASING SAMPLING
403.2		36	SM		122.5	CONDUCTED W/1 1/2" 20.575" IN STANDARD SPOON SPLIT SPOON SAMPLER DRIVEN W/140 LB SAFETY HAMMER, FALLING FORCE 30 TON
		34			JAR 77	DRIVE 2.0 ft REC 1.3 ft LOSS 0.7 ft
	124	SET	Silty fine SAND, trace medium sand, w/ occasional silt layers, dense, wet, red-brown		124.0	124.0
	125	22	SM		JAR 78	DRIVE 2.0 ft REC 1.3 ft LOSS 0.7 ft
		24				124.0
		33				126.0
	126	SET	Fine sandy SILT, trace medium sand, dense, wet, red-brown		JAR 79	DRIVE 2.0 ft REC 1.5 ft LOSS 0.5 ft
		34	ML	126.0	126.0	126.0
	127	33	Silty fine SAND, very dense, wet, red-brown		JAR 80	DRIVE 2.0 ft REC 1.5 ft LOSS 0.5 ft
		34	SM	127.0	127.0	127.0
399.7	128	SET			128.0	DRIVE 2.0 ft REC 0.5 ft LOSS 1.5 ft
	129	26	Silty fine SAND, very dense, wet, red-brown		JAR 81	128.0
		30	SM	130.0	130.0	130.0
	130	27				DRIVE 2.0 ft REC 0.5 ft LOSS 1.5 ft
						130.0
						130.0
SNG FORM 1834-A			PROJECT	ONONDAGA DAM	HOE NO.	DB2-102

DRILLING LOG (Cont Sheet)			ELEVATION TOP OF HOLE	525.7	INSTALATION	MSC	Hole No.	182-102
PROJECT	ONONDAGA DAM				BUFFALO DISTRICT		SHRT	12- or 15' SHRTS
ELEVATION	DEPTH	LEGEND	CLASSIFICATION OF MATERIALS (Descriptive)			% CORE RECOV. BY	BOX OR SAMPLE NO.	REMARKS (Drilling time, water level, depth of overburden, etc., if applicable)
								CSC BGS REC LOSS
383.7	108	SET	Fine sandy SILT, dense wet, red-brown	ML	130.0		SAR 82	DRIVE 2.0 ft REC 2.0 ft LOSS 0.0 ft
	21							100
	23							125
	25				132.0			
383.7	132	SET	Silty fine SAND, to fine SAND, little silt, very dense, wet, red-brown	SM				DRIVE 2.0 ft REC 1.6 ft LOSS 0.4 ft
	29						JAR 83	
	34							137
	39						134.0	
134	SET	silty fine SAND, very dense, wet, red-brown	SM					DRIVE 2.0 ft REC 1.5 ft LOSS 0.5 ft
	27							
	30							
	37							
136	SET	silty fine SAND, very dense, wet, red-brown	SM					
	25							
	27							
	34							
137	SET	silty fine SAND, dense wet, red-brown	SM					
	23							
	25							
	30							
140	SET	silty fine SAND, dense wet, red-brown with occasional silt layers	SM					
	15							
	18							
	28							
383.7	142				142.0			

DRILLING LOG (Core Sheet)			DEPTH OF HOLE	325.7 ft MSL	HOLE NO. D22-102	
DEPTH	DEPTH	LOGGING				
MONADNOCK DAM			BUFFALO DISTRICT			
DEPTH	DEPTH	LOGGING	CLASSIFICATION OF MATERIALS (Description)	T. CORE REC. BY	BOOK OR SAMPLE NO.	REMARKS (Drilling time, water loss, depth of overburden, etc., if significant)
321.7	154	SET	Silty coarse to fine SAND, little gravel very dense, moist, gray	154.0	154.0	DRIVE 2.0 ft REC 2.0 ft LOSS 0.0 ft
	53			JAR	94	SAMPLING CONDUCTED BY 1 1/2" X 2 1/2" IN. STANDARD SPLIT SPON DRIVEN W/ HORN SAFETY HAMMER FALLING FREE 30IN
	155				152.0	ADVANCE BW CASING TO 159.0 ft w/ 300 lb HAMMER FREE FALLING 24IN
	60				NS	
	51				159.0	
	156					
	157					
	158					
	159	SET	NOTE: WASH SAMPLE COBBLES & BOULDER'S ENCOUNTERED	JAR	95	DRIVE 0.8 ft REC 0.1 ft LOSS 0.7 ft
	100				158.8	OBTURATION ENCOUNTERED AT 161.1 ft WHICH ADVANCED BW CASING. OBTURATION COULD NOT BE REMOVED BY BENTONITE BIT. REMOVED BW CASING AND ADVANCED BW CASING TO 161.1 ft. TRI-CONE ROLLER BIT USED FROM 161.1 TO 162.6 ft THROUGH OBTURATION AND FROM 162.6 TO 164.0 ft THROUGH COBBLES. BW CASING SET TO 164.0 ft AND SAMPLING RESUMED
	160					
364.6	161		161.1	NS		
	162		Boulder			
363.1	163		162.6			
	164	SET	Silty coarse to fine SAND, w/ embedded gravel, very dense, moist, gray	JAR	96	DRIVE 1.3 ft REC 0.2 ft LOSS 1.1 ft
	62				165.3	SPOON REPOSITION 165.3 ft ROLLER BIT TO 166.8 ft AND ADVANCE CASING TO 166.0 ft w/ 300 lb HAMMER FALLING FREE REVERSE STANDARD SAMPLING BT 169.0 ft
	100				NS	
	165					
	166		Cobbles Encountered			

DRILLING LOGO (Cont Sheet)				REMARKS	Hole No. D82-102
FROM	TO	INTERVAL	CLASSIFICATION OF MATERIALS (Description)	% CORE RECOV. SET	REMARKS
ELEVATION	DEPTH	LOGNO		NO. OR SAMPLE NO.	(Drilling time, number hrs, depth of overburden, etc., if significant)
	166			JAR 97	WELL TO ADVANCE CASING PART 167.7 ft. PENTAIL BIT 162.7 ft. TO 167.0 ft. CORES ENCOUNTERED ADVANCED BN CASING TO 165.0 ft. W/ 350 lb HAMMER. NOTE: JAR 97 IS A WASH SAMPLE FROM 167.7 TO 169.0 ft.
	167				
	168				
	169				
	170	35	SET	169.0	DRIVE 2.0 ft
	170	36	Fine sandy SET trace clay with embedded coarse to medium sand and gravel, very dense, moist to wet, brown	JAR 98	REC 1.2 ft LOSS 0.8 ft
	171	58	ML	171.0	SAMPLE CONDUCTED BY 13 $\frac{1}{2}$ x 2.0 x 27 $\frac{1}{2}$ IN STANDARD SPLIT SPOON DISTANCE W/ 140 lb SAFETY HAMMER FAILED FREE 30 ft
	172				BN CASING ADVANCED TO REFUSAL @ 173.0 ft REMOVED BN CASING TO CHECK POSSIBLE DAMAGE. 0.0 ft OF BN CASING REMAINING IN BOREHOLE FROM 163.0 TO 173.0 ft.
352.7	173		BOTTOM OF BORING @ 173.0 ft		BOREHOLE TERMINATED AND GRADUATED TO SURFACE.
	174				
	175				
	176				
	177				
	178				

Hole No. D82-103

DRILLING LOG		PROJECT		NORTH CENTRAL		BOFFLE DISTRICT		DATE or HOURS	
1. PROJECT		2. LOCATION		3. DRILLER'S NAME		4. DRILLER'S ADDRESS		5. TOTAL NO. OF HOLE	
ONONDAGA DAM		STA 6-025 N 1-40220 W 5463-02 E MSA 561		PARKER-WOLFE INC.		CME 73		6. TOTAL NO. OF HOLE	
				D82-103				7. TOTAL NO. OF HOLE	
7. HOLE NO. (As shown on drilling log)		8. DIRECTION OF HOLE		9. HOLE NO. (As shown on drilling log)		10. TOTAL NUMBER CORES TAKEN		11. TOTAL NO. OF HOLE	
		() VERTICAL () INCLINED DEG. FROM VERT.				70		12. TOTAL NUMBER CORES TAKEN	
13. THICKNESS OF OVERBURDEN		14. DEPTH DRILLED INTO ROCK		15. ELEVATION GROUND WATER		16. ELEVATION TOP OF HOLE		17. ELEVATION TOP OF HOLE	
NOT PENETRATED		NOT ENCOUNTERED		-		525.8 ft		525.8 ft	
18. TOTAL DEPTH OF HOLE		19. DIRECTION OF HOLE		20. TOTAL CORE RECOVERY FOR BORING		21. HOLE TYPE OF INSPECTED		22. HOLE NO.	
184.8 FT		() VERTICAL () INCLINED		-		-		(AREA OF NEW YORK)	
ELEVATION	DEPTH	LEGEND	CLASSIFICATION OF MATERIALS (Described)		TYPE OF SAMPLE	NO. OF SAMPLE	TESTED	REMARKS	
525.8	0	SET	Gravelly coarse to fine SAND, little silt, dense damp, brown		B	0	0.0	ADVANCE BORING w/ 3.75 IN ID NICKEL STEM AUGER w/ REUSABLE CAGE. SAMPLE WELL RETAINED EVERY 5 FT IN THE BORING. SAMPLE SIZES OF 3.0 x 3.5 x 3.8 IN SPOON SPAN DRIVEN w/ SOIL HAMMER FACILITY ROCK 3.75 IN DRIVE 2.0 ft REC 1.5 ft LOSS 0.5 ft	
	17		SM		A	1			
	25				G	20			
	27				I				
	2				NS				
	3								
	4								
520.8	5	SET	Silty coarse to fine SAND, little gravel, dense damp, brown		B	5.0	5.0	DRIVE 1.4 ft REC 1.4 ft LOSS 0.0 ft	
	34		SM		G	2			
519.8	6	SET	Gravelly coarse to fine SAND, little silt, very dense, damp, brown		A	6.0	6.0	SPOON REFUSAL 6.4 ft	
	50		SM		G	3			
	7				B	6.4		ADVANCE BORING TO 10.0 ft w/ 3.75 IN ID NICKEL STEM AUGER w/ REUSABLE CAGE	
	8				A				
	9				G				
	10				I				
	11				NS				

ENG FORM 1836 PREVIOUS EDITIONS ARE OBSOLETE.
MAR 71 (TRANSLUCENT)

PROJECT

ONONDAGA DAM HOLE NO. D82-103

DRILLING LOG (Core Sheet)			DEPTH TO TOP OF HOLE	525.8 ft MSL	Note No. D82-103
PROJECT	ONONDAGA DAM	LOCATION	BUFFALO DISTRICT		
DEPTH	DEPT	LOGNO	CLASSIFICATION OF MATERIALS (Densest)		REMARKS
			% CORE RECOV. BY	BOX OR SAMPLE NO.	(Driving force, recovery, loss, depth of penetration, etc., if applicable)
515.3	10	SET	Gravelly coarse to fine SAND, little silt, dense, damp, brown	10.0 JAR 4	DRIVE 0.9 ft
	50		Silty coarse to fine SAND, little gravel, very dense, damp, brown	10.5 JAR 5	REC 0.9 ft
	11			10.5 JAR 5	LOSS 0.0 ft
513.3	12				ADVANCE BORING TO 15.0 ft w/ 3.75 IN ID HOLLOW STEM AUGER w/ PLUG MFG-CME
	13				SAMPLING CONDUCTED BY 3.0x3.5x36IN STANDARD SPOT SPON DRIVEN w/ 350/lb HAMMER FOLLOWING FACE 18IN.
	14				
	15	SET	Coarse to fine SAND, little gravel, trace to little silt, very dense damp, brown	15.0 JAR 6	DRIVE 2.0 ft
	25			A 17.0	REC 2.0 ft
	34				LOSS 0.0 ft
	33		SM		
	17			G	ADVANCE BORING TO 20.0 ft w/ 3.75 in ID HOLLOW STEM AUGER w/ PLUG, MFG CME
	18				
	19			NS	
	20	SET	Coarse to fine SAND, little gravel, little silt, very dense, damp, brown	20.0 JAR 7	DRIVE 1.3 ft
	49				REC 1.3 ft
	50				LOSS 0.0 ft
	21		SM	21.3 NS	ADVANCE BORING TO 25.0 ft w/ 3.75 in ID HOLLOW STEM AUGER w/ PLUG, MFG CME
	22				

DNR FORM 1836-A

000-000-000-000

PROJECT ONONDAGA DAM NOTE NO. D82-103

ONONDAGA DAM D82-103

DRILLING LOG (Cont Sheet)			ELEVATION TOP OF HOLE	525.8 ft MSL	Hole No.	D82-103
PERIOD	DEPTH	LOGGING	REMARKS			
ONONDAGA DAM			BUFFALO DISTRICT			
ELEVATION	DEPTH	LOGGING	CLASSIFICATION OF MATERIALS (Description)	% CORE REC'D. BY SET	BOX OR SAMPLE NO.	REMARKS (Drilling time, cutter bar, depth of overburden, etc., if applicable)
a	b	c	d	e	f	g
	34					
	35	so				HEATED TO SAMPLE E 35.0 ft. FROM REPOSE 35.1 ft
	36					DRIVE 0.1 ft REC 0.0 ft LOSS 0.1 ft
	37					ADVANCE BORING TO 40.0 ft w/ 3.75 IN ID HOLLOW STEM AUGER w/PLUG MFG-CME SAMPLING CONDUCTED BY 3.0X3.5X38 IN SPLIT SPER DRIVEN W/350lb HAMMER FALLING FREE 18IN
	38					
	39					
	40	SET	Gravelly coarse to fine SAND, little silt	40.0	40.0	DRIVE 2.0 ft REC 2.0 ft LOSS 0.0 ft
	41	27	very dense, damp, brown	B	JAR	
	48		SM	A	11	
	50			G	42.0	ADVANCE BORING TO 45.0 ft w/3.75 IN ID HOLLOW STEM AUGER w/PLUG MFG-CME
	43			5		
	44			NS		
	45	SET	Gravelly coarse to fine SAND, little silt, dense moist, brown	45.0	JAR	DRIVE 2.0 ft REC 2.0 ft LOSS 0.0 ft
	46	18	SM	12		

GSA FORM 1826-A

GPO: 1960 OPM-200-200-200

PROJECT

ONONDAGA DAM Hole No. D82-103

DRILLING LOG (Cont Sheet)			REFLECTION TOP OF HOLE	525.8 ft MSL	hole No D62-103	
PROJECT	ONONDAGA DAM	LOCATION	BUFFALO DISTRICT	SHOT	5 of 16 shots	
ELEVATION	DEPTH	LEGEND	CLASSIFICATION OF MATERIALS (Description)	% CORE RECOV. SET	BOX OR SAMPLE NO.	REMARKS (Drilling time, motor loss, depth of overburden, etc., if significant)
46	24			B A G S	JAR 12 47.0	
47	32					
48						
49						
50	SET	Sitting coarse to fine SAND, & GRAVEL, very dense, damp to moist, brown		50.0	50.0	ADVANCE BORING TO 50.0 ft w/ 3.75 IN ID HOLLOW STEM AUGER w/ PLUG MFG-CME SAMPLING CONDUCTED BY 3.0 X 3.5 X 38 IN SPLIT SPOON DRIVEN w/ 550 lb HAMMER FAUCED FREE BIN,
51	35			B A G	JAR 13	UPHOLE 2.0 ft REC 1.7 ft LOSS 0.3 ft
52	50			6		
52	47	SM - GM		52.0	52.0	ADVANCE BORING TO 55.0 ft w/ 3.75 IN ID HOLLOW STEM AUGER w/ PLUG MFG-CME
53					NS	
54						
55	SET	Gravelly coarse to fine SAND, little silt		55.0	55.0	DOVE 2.0 ft REC 1.8 ft LOSS 0.2 ft
56	16			B A G	JAR 14	
57	23	coarse, damp, brown SM		7	57.0	ADVANCE BORING TO 60.0 ft w/ 3.75 IN ID HOLLOW STEM AUGER w/ PLUG MFG-CME
58	13				NS	

DRILLING LOG (Cont Sheet)			SEPARATION TOP OF HOLE	525.8 ft MSL	Hole No. D82-103
SEPARATION	DEPTH	LEGEND	INSTALLATION	TESTING DISTRICT	SHOT ON 16.6
					ESG BLDG PER Ft
	58				
	59				
	60				
	SET	Gravelly coarse to fine SAND, trace silt, damp, very dense, brown	B	NS	
	23		A		
	61		G	60.0	
	33		7	JAR	DRIVE 2.0 ft REC 2.0 ft LOSS 0.0 ft
	32	S.M.	15		SAMPLING CONDUCTED BY 3.0x3.5x38 IN SET SPOON DRIVEN w/ 350 LB HAMMER FALLING FREE FALL.
	62		62.0	62.0	
	63			NS	SET NEW FLUSH JAR IN CASING 9 3/16 IN ID & 60.0 ft. DRIVE TO 65.0 ft WATER LEVEL CHECKED AFTER SETTING CASING BOREHOLE DRY 20 AUG 1982 PM
	64				
	65			65.0	65.0
460.8	65	SET Silt coarse to fine SAND, trace gravel, dense, damp, brown			DRIVE 2.0 ft REC 1.2 ft LOSS 0.8 ft
460.3	65.5		SAR		COMMENCE CONTINUOUS SAMPLING USING 1 1/2 x 2.0 x 27 IN STANDARD SPLIT SPOON SAMPLER DRIVEN w/ 140 LB SAFETY HAMMER FALLING FREE 30 IN.
	8		16		
	66				
	12				
	67				
	18	Silty CLAY, very stiff, damp, gray	JAR		DRIVE 2.0 ft REC 1.5 ft LOSS 0.5 ft
	CL		17		
457.8	68			68.0	
	14	SET, little fine sand, little clay, trace organics (wood fragments)	JAR		
	18	dense, damp, gray	18		
	69			69.0	
	SET	SET, little fine sand, little clay, trace gravel, trace wood fragments, medium dense, damp, gray	JAR		DRIVE 2.0 ft REC 1.7 ft LOSS 0.3 ft
	6	M	19		
	70				

ENG FORM 1836-A
REV A7
APR 67

PROJECT
ONDONDAGA DAM

HOLE NO.
D82-102

DRILLING LOG (Cont Sheet)			SEARCH TOP OF HOLE	525.8 ft MSL	Hole No. D82-103
PROJECT	ONONDAGA DAM	LOCATION	BUFFALO DISTRICT		
ELEVATION	DEPTH	LEADS	CLASSIFICATION OF MATERIALS (Description)		REMARKS
			% CORE RECOV. BY	BOX OR SAMPLE NO.	(Drilling time, water level, depth of overburden, etc., if applicable)
455.3	70			JAR 1	DRIVE 2.0 ft
	12	Silt, little fine sand, silty clay, trace gravel, trace wood fragments and dense damp, gray Mkt 70.5		JAR 2	REC 1.7 ft
	17	Silty coarse to fine SAND, trace gravel SM		JAR 20	LOSS 0.3 ft
	21	SET			
	25	Silty coarse to fine SAND, little gravel, very dense, damp, gray SM		JAR 21	DRIVE 2.0 ft
	32	SET			REC 0.3 ft
	38	Silty coarse to fine SAND, little gravel, very dense, dry, gray SM		JAR 22	LOSS 1.7 ft
	32	SET			BARING ADVANCED BY NW CASING 3 1/2 IN DRIVEN BY 350 lb HAMMER FALLING FREE 24 IN. SIGHTING CONDUCTED w/ 1/4 x 2.0 IN STANDAR STANDARD SET SPANNED BY 1/4 IN SAFETY CHAMFER FACILE FREE 50 IN
	30	SET			
	75	Silty coarse to fine SAND, little gravel, very dense, damp to wet, gray SM		JAR 23	DRIVE 2.0 ft
	77	SET			REC 0.9 ft
	77	77.0			LOSS 1.1 ft
	78	Gravelly coarse to fine SAND, little silt, very dense, wet, gray SM		JAR 24	DRIVE 2.0 ft
	80	SET			REC 0.7 ft
	80	80.0			LOSS 1.3 ft
	81	SET			
	81	81.0		JAR 25	DRIVE 2.0 ft
	82	SET			REC 0.6 ft
	82	82.0			LOSS 1.4 ft
448.8	77	SET			
	78	78.0			
	80	SET			
	81	81.0			
444.8	81	SET			
	82	82.0			

DRILLING LOG (Cont Sheet)			SEPARATION TOP OF HOLE	525.8 ft MSL	Hole No. D22-103	
PROJECT	ONONDAGA DAM	TEST NUMBER	BUFFALO DISTRICT			DATE 9/16/88
SEPARATION	DEPTH	LOGNO	CLASSIFICATION OF MATERIALS (Dowdham)		S. CORE RECOV. RTY	REMARKS
			(Dowdham)		#	(Drilling time, number core, depth of penetration, etc. if applicable)
	82	25	Gravelly coarse to fine SAND, little silt, very dense moist, to wet, brown SM		JAR 26	DRIVE 2.0 ft REC 1.2 ft LOSS 0.8 ft
	83	35			JAR 27	DRIVE 2.0 ft REC 0.1 ft LOSS 1.9 ft
	84	SET	Gravelly coarse to fine SAND, little silt, very dense moist, brown SM		JAR 28	BOREhole ADVANCED BANK CASING 3 1/8 IN ID DRIVEN W/30lb HAMMER PILING FRE 24 IN, SAMPLING CONDUCTED w/1 1/8 x 2.0 x 27 IN STANDARD SPLIT SPOON DRIVER BY HOLE SAFETY BARRIER FALLING FACE JOIN
	85	52			JAR 29	DRIVE 2.0 ft REC 0.7 ft LOSS 1.3 ft
	86	43	Gravelly coarse to fine SAND, little silt, very dense moist-wet, gray SM		JAR 30	
	87	30			JAR 31	DRIVE 2.0 ft REC 1.1 ft LOSS 0.9 ft
435.3	86.5	SET	Silty fine SAND, trace gravel, few coarse sand sand brownish red-brown		JAR 32	DRIVE 2.0 ft REC 1.4 ft LOSS 0.6 ft
438.8	87	25			JAR 33	DRIVE 2.0 ft REC 1.4 ft LOSS 0.6 ft
	88	27	Silty medium to fine SAND, very dense, wet, red-brown SM			
	89	24				
	90	23	Silty medium to fine SAND, dense, wet red-brown SM			
	91	24				
	92	30	Silty medium to fine SAND, very dense, wet, red-brown SM			
	93	25				
	94	23				
	95	24	Silty medium to fine SAND, very dense, wet red-brown SM			
	96	23				
	97	24				
	98	23				
	99	24				
	100	23				

DRILLING LOG (Core Sheet)				ELEVATION TOP OF HOLE	525.8 ft ASL	Hole No. D82-163	
PROJECT	ONONDAGA DAM	NORFOLK DISTRICT			SHIRT 0.16 in.	CSG	
ELEVATION	DEPTH	LOGNO	CLASSIFICATION OF MATERIALS (DESCRIPTION)	% CORE RECOV. BY %	BOX OR SAMPLE NO. #	REMARKS (Drilling time, number and depth of samples, etc. if applicable)	SCREW PER FOOT
	97	23	Silty medium to fine SAND, very dense, wet, red-brown SM	32	JAR 33	DRIVE 2.0 ft REC 1.4 ft LOSS 0.6 ft	144
	95	37	Silty medium to fine SAND, dense, wet, red-brown SM	25.0	JAR 34	DRIVE 2.0 ft REC 1.4 ft LOSS 0.6 ft	144
	96	22	Silty medium to fine SAND, wet, very dense, red-brown SM	25.0	JAR 34	BORING ADVISED BY NW CASTING 3 1/2 IN ID DRIVEN W/ 350 lb HAMMER FALLING FREE 24 IN. SAMPLING CONDUCTED W/ 1 1/2 X 2 0 X 27 TAPE STANDARD SPIT SHOT DROPPED BY HOLE SAFETY HAMMER FALLING FREE 20 IN	144
	97	32	Silty medium to fine SAND, wet, very dense, red-brown SM	25.0	JAR 35	24 AUG 1982 AM CSG @ 97.0 ft bottom of hole 97.0 ft depth to water 52.8 ft	144
	98	35	Silty medium to fine SAND, wet, very dense, red-brown SM	25.0	JAR 35	DRIVE 2.0 ft REC 1.3 ft LOSS 0.7 ft	144
	426.8	41	NOTE: clayey SILT layer from F 92.5 to 98.8 ft	99.0	97.0		144
	426.8	43	SET Coarse to fine SAND, little silt, wet, dense, red-brown	99.0	JAR 36	DRIVE 2.0 ft REC 1.2 ft LOSS 0.8 ft	144
	100	25	SM	101.0	JAR 37		144
	100	23		101.0	JAR 38		144
	101	25	Coarse to fine SAND, little silt, trace fine gravel, wet dense, red-brown SM 101.5	101.5	JAR 39	DRIVE 2.0 ft REC 1.3 ft LOSS 0.7 ft	144
	424.3	102	SET SILT, little fine sand, hard, wet, red-brown	101.5	JAR 40		144
	102	17		101.5	JAR 40		144
	102	19	ML	101.5	JAR 41		144
	422.8	103	25	103.0	103.0	DRIVE 2.0 ft REC 1.2 ft LOSS 0.8 ft	144
	422.8	104	SET Silty fine SAND w/ occasional gray SILT seams, wet, very dense, red-brown	104.0	104.0		144
	422.8	104	25	104.0	JAR 40		144
	422.8	34	SILT, trace gravel, trace coarse to fine sand, trace clay, hard, damp, red-brown	104.0	104.0		144
	420.3	105	37	105.5	105.0	DRILLER NOTES ROLLER HIT ENCOUNTERED BULLDOZER MUD 17 104.8 TO 105.3 ft	144
	420.3	106	SET Silty CLAY, trace embedded pebbles, trace coarse to fine sand, hard, damp, red-brown CL	105.5	JAR 41	DRIVE 1.5 ft REC 1.2 ft LOSS 0.3 ft	144

DRILLING LOG (Cont Sheet)			ELEVATION TOP OF HOLE	525.8 ft MSL	Note No.	D82-103	PSG
PROJECT	ONONDAGA DAM		PERFORATION	BUFFALO DISTRICT		SHOTS	BLAU
ELEVATION	DEPTH	LEGEND	CLASSIFICATION OF MATERIALS (Description)		% CORE RECOV. BY	BOX OR SAMPLE NO.	BALANCES
#	'	"			BTY		(Drilling time, water level, depth of weathering, etc. if significant)
106	36	S	Silty CLAY, trace coarse to fine sand, hard, damp, red-brown	CL	JAR 41	DRIVE 1.5 ft REC 1.2 ft LOSS 0.3 ft	132
107	54	SET	Silty CLAY, trace coarse to fine sand, hard, damp, red-brown	CL	JAR 42	DRIVE 2.0 ft REC 1.4 ft LOSS 0.6 ft	127
108	35	SET	Silty CLAY, trace coarse to fine sand, hard, damp, red-brown	CL	JAR 43	BORING ADVANCED BY NW CAVING 3 1/16 IN ID DRIED W/ 350 lb HAMMER FALLING FREE 24 IN. SAMPLING CONDUCTED 4 1/8 x 2 1/2 IN STANDARD SPAN SPOON DRIED BY 140 lb SAFETY HAMMER FALLING FREE 30.5 m	127
109	47				JAR 44	DRIVE 1.3 ft REC 1.1 ft LOSS 0.2 ft	112
110	50	SET	Silty CLAY, trace coarse to fine sand, hard, damp, red-brown	CL	NS	USE TRICOKE ROLLER BIT TO CLEAR POSSIBLE OBSTRUCTION TO A DEPTH OF 111.0 ft. ADVANCE NW CASING TO 111.0 ft AND RESUME CONTINUOUS SAMPLING	132
111	25	SET	Silty CLAY, trace coarse to fine sand, hard, damp, red-brown	CL	JAR 45	DRIVE 2.0 ft REC 2.0 ft LOSS 0.0 ft	135
112	35	SET	Silty CLAY, trace coarse to fine sand, hard, damp, red-brown	CL	JAR 46	SET BN CASING THROUGH NW CASING TO A DEPTH OF 115.0 ft. DRIVE CASING TO 117.0 ft W/ 350 lb HAMMER FALLING FREE 24 IN AND RESUME CONTINUOUS SAMPLING	124
113	43				JAR 47	DRIVE 2.0 ft REC 2.0 ft LOSS 0.0 ft	135
114	35	SET	Silty CLAY, trace coarse to fine sand, hard, damp, red-brown	CL	JAR 48	DRIVE 2.0 ft REC 1.9 ft LOSS 0.1 ft	131
115	40						
116	54	SET	Silty CLAY, trace coarse to fine sand, hard, damp, red-brown	CL			
117	35	SET	Silty CLAY, trace coarse to fine sand, hard, damp, red-brown	CL			
118	37						
119	75						
120.5	59	SET	Silty CLAY, trace coarse to fine sand, hard, damp, red-brown	CL			
118	59		Silty fine sand, very dense wet, red-brown	SM			

DRILLING LOG (Cont Sheet)				ELEVATION TOP OF HOLE	525.8 ft MSL	Hole No.	D82-103
PROJECT	ONONDAGA DAM	INSTALATION	BUFFALO DISTRICT	DATE	11/16/82	CSG BLAN PA	FOOT
ELEVATION	DEPTH	LEGEND	CLASSIFICATION OF MATERIALS (Description)	% CORE RECOV.	BOX OR SAMPLE NO.	REMARKS (Drilling time, water loss, depth of sounding, etc. of significance)	
a	b	c	d	e	f		
	118	69	Silt, fine SAND, very dense, wet, red-brown		JAR 48	DRIVE 2.0 ft REC 1.9 ft LOSS 0.1 ft	53
406.8	119	115	SM		119.0		
	120	SET	SILT, little fine sand occasional clayey		JAR 49	DRIVE 2.0 ft REC 2.0 ft LOSS 0.0 ft	58
	120	54	SILT seams, hard, wet, red-brown			BOREHOLE ADVANCED BY BW CASTING 2.75 IN ID DRIVEN W/ 350 lb HAMMER FALLING FREE 24 IN. SAMPLING CONDUCTED W/ 1/2 x 2.0 x 27 IN STANDARD SPOT SPOON DRIVEN BY 140 lb SAFETY HAMMER FALLING FREE 30 IN	
	121	50			121.0		189
	121	78	ML				
	122	SET	SILT, little fine sand, trace clay, occasional clayey SILT seams, hard, damp to wet, red-brown		JAR 50	25 AUG 1982 BOTTOM OF CASING 119.0 ft BOTTOM OF HOLE 121.0 ft DEPTH TO WATER 66.6 ft	185
	122	31				DRIVE 2.0 ft REC 1.6 ft LOSS 0.4 ft	143
	122	36			123.0		
	123	51	ML		JAR 51	DRIVE 2.0 ft REC 1.6 ft LOSS 0.4 ft	142
	124	SET	SILT, little fine sand, trace clay, with clayey SILT seams and layers, hard, damp to wet, red-brown				150
	124	22			125.0		
	124	39			JAR 52	DRIVE 2.0 ft REC 1.4 ft LOSS 0.6 ft	148
400.8	125	49	ML	125.0			
	125	SET	Silt, fine SAND, trace medium to coarse sand, w/ occasional clayey SILT seams, very dense, wet red-brown		JAR 53	DRIVE 2.0 ft REC 1.4 ft LOSS 0.6 ft	147
	126	39			127.0		
	126	43			JAR 54	DRIVE 2.0 ft REC 2.0 ft LOSS 0.0 ft	149
	127	54	SM	127.0			
398.8	127	SET	Clayey SILT, little fine sand, (seams), hard moist, red-brown				
	128	20			JAR 54		
	128	22	ML				
	129	25			128.0		
	129	SET	Clayey SILT, little fine sand, (seams) with occasional layers of silt, CLAY, very dense, red-brown		JAR 54	DRIVE 2.0 ft REC 2.0 ft LOSS 0.0 ft	149
	130	18					

DRILLING LOG (Cont Sheet)			DEPTH OF HOLE	555.8 ft MSL	Hole No. 103	12	CSG BOW PER FOOT
PROJECT	ONONDAGA DAM	INSTALLATION	BUFFALO DISTRICT		SHOT OR 16 SHEETS		
ELEVATION	DEPTH	LOGGING	CLASSIFICATION OF MATERIALS (Description)		% CORE RECOV. ERY.	BOX OR SAMPLE NO.	REMARKS (Drilling time, rotary time, depth of overburden, etc., if applicable)
	130		Cherry SILT, little fine sand (sandstone) w/ occasional layers of silty CLAY, very dense, damp, brown	131.0	JAR	54	DRIVE 2.0 ft REC 2.0 ft LOSS 0.0 ft
	22						
	35						
34.8	131	SET	Silty fine SAND, very dense, wet, red-brown	131.0	JAR	55	DRIVE 2.0 ft REC 1.6 ft LOSS 0.4 ft DUE TO HIGH CASTING BLOWS FISHTAIL BIT W/ SIDEPORTS UTILIZED FROM 131.0 TO 133.0 ft. CASING ADVANCED TO 133.0 ft, WASHED OUT AND CONTINUOUS SAMPLING RESUMED.
	37						
	51		SM				
	83						
	133	SET	Silty fine SAND, very dense, wet, red-brown	133.0	JAR	56	DRIVE 2.0 ft REC 1.5 ft LOSS 0.5 ft BORING ADVANCED BY BLW CASTING 2.75 IN TD DRIVEN W/ 300 LB HYDRAULIC FAILING FREE 24 IN. SAMPLING CONDUCTED W/ 1 1/2 X 2.0 X 17.5 IN STANDARD SPOT SPAN DEPENDS NO. 10 SAFETY MARKER FAILING FREE 30 IN
	32						
	39						
	51						
	135	SET	Silty fine SAND, w/ occasional SILT seams very dense, wet, red-brown	135.0	JAR	57	DRIVE 2.0 ft REC 1.4 ft LOSS 0.6 ft
	29						
	39		SM				
	55						
	137	SET	Silty fine SAND, very dense, wet, red-brown	137.0	JAR	58	DRIVE 2.0 ft REC 1.4 ft LOSS 0.6 ft UTILIZE FISHTAIL BIT W/ SIDEPORTS FROM 137.0 TO 138.7 ft. ADVANCE P/W CASING TO 139.0 ft AND RESUME CONTINUOUS SAMPLING.
	33						
	51						
	57						
	139	SET	Silty fine SAND, very dense, wet, red- brown	139.0	JAR	59	DRIVE 2.0 ft REC 1.6 ft LOSS 0.4 ft UTILIZE FISHTAIL W/ SIDEPORTS FROM 139.0 TO 140.7 ft. ADVANCE CASING TO 141.0 ft WASHOUT AND RESUME CONTINUOUS SAMPLING.
	30						
	48						
	62						
	141	SET	Silty fine SAND, very dense, wet, red-brown	141.0	JAR	60	DRIVE 2.0 ft REC 1.6 ft LOSS 0.4 ft
	33		SM				
	142						

ENR FORM 1034-A
APR 67

GPO: 1960 OPM - 160-240

PROJECT

ONONDAGA DAM

HOLE NO.

103

DRILLING LOG (Core Sheet)				LEVELING TOP OF HOLE	525.8 ft MSL	Note No. DB2-103
PROJECT	ONONDAGA DAM	BUFFALO DISTRICT		DATE	1/15 1968	TIME
DEPTH	LEAVING	CLASSIFICATION OF MATERIALS (Description)		% CORE RECOVERY BY	BOX OR SAMPLE NO.	REMARKS
"	"	"	"	"	"	"
M2	39	Silty fine SAND, very dense, wet, red-brown	SM	JAR	60	DRIVE 2.0 ft REC 1.6 ft LOSS 0.4 ft
	43				143.0	
	SET	Silty fine SAND, trace coarse to medium sand, very dense, wet, red-brown	SM	JAR	61	DRIVE 2.0 ft REC 1.9 ft LOSS 0.1 ft
	33					BORING ADVANCED BY BW CASING 2.75IN ID DRIVEN W/ 350lb HAMMER FALLING FREE 24IN, SAMPLING CONDUCTED W/ 1 1/2 x 2.0 x 17IN STANDARD SPLIT SPOON DRIVEN BY HAMMER SAFETY HAMMER, FALLING FREE 30IN
	37					
380.0	50		145.0			
	MS					
	SET	SILT, little fine sand, trace clay, hard, wet, red-brown	ML	JAR	62	16 NOV 68 AM CSE 145.0 BORING TO HOLE 145.0 ft DEAD TO HOLE 70.3 ft
	21					DRIVE 2.0 ft REC 2.0 ft LOSS 0.0 ft
	27					
	57				147.0	
	148					UTILIZED PINTAIL BIT FROM 145.0 TO 147.5 ft ADVANCE CASING TO 150.0 ft. CONVENTIONAL SAMPLING AT 5 ft. INTERVALS USING 1 1/2 x 2.0 x 27IN STANDARD SPLIT SPOON BUREAU W/ 190lb SAFETY HAMMER FREE FALLING 30IN
376.0	149		149.0			
	150	Coarse to fine SAND, little gravel, little silt, very dense, wet, red-brown	SM	JAR	150.0	DRIVE 0.2 REC 0.2 LOSS 0.0
	150.00					
	151					UTILIZED BEAUTONITE AND IN LIEU OF BW CASING FROM 150.0 ft TO BOTTOM OF BORING. WESTERN BRAND BEAUTONITE, MFG IN BARBO
	152					
	153					
371.8	154		154.0			

DRILLING LOG (Core Sheet)			ELAVATION TOP OF HOLE	525.8 ft NSL	Hole No.	DP-103
PROJECT	INSTALATION	BUCKLE DISTRICT			SHRINK	14
ONONDAGA DAM					OF 16 SHEETS	
ELAVITION	DEPTH	LOGNO	CLASSIFICATION OF MATERIALS (Drillings)	TEST NO. OR RECOVERY NO.	REMARKS (Drilling time, water loss, depth of overburden, etc., if significant)	
371.8	154	SET	Silty fine SAND, very dense, wet, red-brown	154.0	154.0	DRIVE 2.0 ft REC 1.5 ft LOSS 0.5 ft
	155	32	SM	JAR 64		
	156	38			156.0	ADVANCE BOREHOLE TO 159.0 ft w/ FISHTAIL BIT. AND DRILLING MUD. RESUME SAMPLING
	157			NS		
	158					
	159	SET	Silty fine SAND, very dense, wet, red-brown	159.0	JAR 65	DRIVE 2.0 ft REC 1.2 ft LOSS 0.8 ft
	160	27	SM			
	161	38			610	ADVANCE BOREHOLE TO 164.5 ft w/ FISHTAIL BIT AND DRILLING MUD. RESUME SAMPLING
	162	47		NS		
	163					
	164					
	165	SET	Silty fine SAND, very dense, wet, red-brown	665	JAR 66	DRIVE 2.0 ft REC 1.5 ft LOSS 0.5 ft
	166	22	SM			
	166	32				

DRILLING LOG (Cont Sheet)			DEPTH TO TOP OF HOLE	525.8 ft MSL	Hole No. D82-103	
PROJECT	ONONDAGA DAM	DRILLER	BOUFFORD DISTRICT	SHOT	15 of 16 SHOTS	
BURDON	DEPTH	LOGNO	CLASSIFICATION OF MATERIALS (Description)	% CORE RECOV. BY	BOX OR SAMPLE NO.	REMARKS (Drilling time, water loss, depth of overburden, etc., if applicable)
	166	37	Silty fine SAND, very dense, wet, red-brown	JAR 66 165	DRIVE 2.3 ft REC 1.5 ft LOSS 0.5 ft	
	167			NS	ADVANCE BORING TO 169.5 ft W/ FISH TAIL AND DRILLING MUD. REUSE MUD SAMPLING.	
	168				DRILLER NOTES GRAVEL AND/OR COBBLES ENCOUNTERED BY FISH TAIL BIT FROM 167.5 TO 168.5 ft	
	169					
	170	SET	Silty fine SAND, dense, wet, red-brown	169.5 JAR 67	DRIVE 2.0 ft REC 1.1 ft LOSS 0.9 ft	
	171	19				
	172	26				
	173	38		171.5		
	174	SET	Silty fine SAND, occasional silt, scans very dense, wet, red-brown	174.0 JAR 68	ADVANCE BORING TO 174.0 ft W/ FISH TAIL BIT AND DRILLING MUD. RESUME SAMPLING.	
	175	24				
	176	38				
	177	42		176.0	DRIVE 2.0 ft REC 1.2 ft LOSS 0.8 ft	
	178			NS	ADVANCE BORING TO 179.0 ft W/ FISH TAIL BIT AND DRILLING MUD. RESUME SAMPLING.	

ENG FORM 1836-A
JUN 67

GEN. INFO SHEET

PROJECT: ONONDAGA DAM Hole No. D82-103

DRILLING LOG (Core Sheet)				DEPTH	PROJECT	REMARKS
					525. B. D. M.	Hole No. DZ 103
DEPTH	LEGEND	CLASSIFICATION OF MATERIALS	% CORE RECOV.	DRILLING NO.	REMARKS	
ft	c	(Description)	ft	ft	(Drilling time, water level, depth of overburden, etc. if applicable)	
178					ADVANCE BOREHOLE W/ BIT TO 179.0 ft. PUSHING SAMPLING. DRILLER NOTES GRAVEL AND/OR COBBLES 178.0 - 178.2 ft	
179	SET	Silt, fine SAND, very dense, wet, red-brown		181.0	DRIVE 2.0 ft REC 1.7 ft LOSS 0.3 ft	
180	29	SM		JAR 69		
	36					
344.8	181	46	181.0			
182						
183						
184	SET	Gravelly coarse to fine SAND, little silt, very dense, moist, gray SM		181.0	ADVANCE BOREHOLE TO 184.0 ft w/ FIGHTING BIT NO DRILLING AND. RESUME SAMPLING.	
	100			JAR 70	DRILLER NOTES GRAVEL AND/OR COBBLES FROM 181.0 ft TO 184.0 ft	
341.0				181.8		
185		Bottom of BORING @ 181.8 ft			DRIVE 0.8 ft REC 0.3 ft LOSS 0.5 ft	
186						
187						
188						
189						
190						

EWS FORM 1836-A

JUN 67

GPO: 1960 OPM - 202-240

PROJECT

CRAVENDALE DAM


Hole No.
DZ 103




FORM
HBA FEB. 1966


SUMMARY OF LABORATORY TEST RESULTS										FILE NO 745003	
Onondaga Dam										SHEET 1 OF 1	
Seismic and Geologic Investigations											
BORING & SAMPLE NUMBER	DESCRIPTION	DEPTH (FEET)	TEST NO.	NATURAL WATER CONTENT %	ATTENBERG LIMITS %	UNIT WEIGHT LB/CU FT	UNCONFINED TEST COMPRESSIVE STRENGTH PSF	CONSOLIDATION MAX PAST PRESSURE TON/SQ. FT.	C C	OTHER TESTS	
D82-101/ S17	Brown, fine sandy SILT and CLAY, trace fine gravel, trace coarse to medium sand. -CL-	60.0- 62.0	A-1	19.6	23.4	13.6				Hydrometer H-1	
D82-101/ S20	Brown, silty CLAY, little fine sand. -CL-	64.0- 65.5	A-2	19.3	38.2	18.1				Hydrometer H-2	
D82-102/ S38	Brown, fine sandy SILT and CLAY.	66.0- 68.0	A-3	20.6	27.4	17.0				Hydrometer H-3	
D82-103/ S19	Gray, fine sandy SILT and CLAY, trace coarse to medium sand. -ML-CL-	69.0- 71.5	A-4	23.1	22.1	16.0				Hydrometer H-4	
D82-103/ S44	Red-brown, silty CLAY trace coarse to fine sand. -CL-	110.0- 113.0	A-5	13.6	21.7	12.9				Hydrometer H-5	

HALEY & ALDRICH, INC.
CONSULTING SOIL ENGINEERS







HALEY & ALDRICH, INC.




HALEY & ALDRICH, INC.






HALEY & ALDRICH, INC.



HALEY & ALDRICH, INC.

GRAIN SIZE DISTRIBUTION

U.S. STANDARD SIEVE SIZE



COBBLES	GRAVEL				SAND			SILT OR CLAY	
	COARSE	FINE	COARSE	MEDIUM	FINE				
UNIFIED SOIL CLASSIFICATION SYSTEM, CORPS OF ENGINEERS, U.S. ARMY									

PROJECT Onondaga Dam
Seismic and Geologic Investigations

FILE NO. 745003 DATE September 1982

Test No.	Boring/Sample	Depth (ft.)	Description
H-4	D82-103/S19	69.0-70.5	Gray, fine sandy SILT and CLAY, trace coarse to medium sand. ML-CL
H-5	D82-103/S44	111.0-113.0	Red-brown, silty CLAY, trace coarse to fine sand. -CL-

~~APPENDIX P~~


~~ENGINEERING ANALYSIS
SAMPLE - ENGINEER SERVICES
LIQUEFACTION ANALYSIS~~

SAMPLER-HAMMER RATIOS



Client: CORPS OF ENGINEERS
Project: ONONDAGA DAM

File Number 745003
Sheet 1 of 2
Date Sept 1982
Computed by DTS
Checked by SOS




Sampler driving resistance vs compactness-cohesionless sands and silts.

SAMPLER	W (lb)	H (in)	D_o (in)	D_i (in)	R_s (ft^2/lb)
Standard	140	30	2.000	1.375	0.90×10^{-5}
Large	350	18	3.500	2.875	2.11×10^{-5}



Client CORPS OF ENGINEERS
Project ONONDAGA DAM

File Number 745003
Sheet 2 of 2
Date Sept 1982
Computed by DTS
Checked by JAS



Sampler driving resistance vs consistency-cohesive soils.

SAMPLER	W (lb.)	H (in)	D_o (in)	D_i (in)	R_s ($\text{ft.}/\text{lb.}$)
Standard	140	30	2.000	1.375	4.19×10^{-5}
Large	350	18	3.500	2.875	5.27×10^{-5}

LIQUEFACTION ANALYSIS



Client J. O. E.
 Project ONONDAGA DAM

File Number 7450-02
 Sheet SUMMARY of
 Date 9 SEP 81
 Compiled by WAW
 Checked by CS

• SUMMARY OF LIQUEFACTION STUDIES FOR
ONONDAGA DAM

- SHEAR STRESS/CONFINING STRESS (τ/σ_{vo}) RATIOS WHILE CALCULATED AS: (FROM PROCEDURES BY SEED, 1976)

$$\tau/\sigma_{vo} = 0.047 \text{ to } 0.071 \text{ BELOW TOE OF DAM}$$


$$\tau/\sigma_{vo} = 0.040 \text{ to } 0.048 \text{ BELOW CREST OF DAM}$$

- FROM STUDIES BY SEED (1976) AND OTHERS, THE SPT-BLOW COUNT (CORRECTED TO 1 TSF OVERBURDEN PRESSURE) N_1 MUST BE LESS THAN 4.3 TO 6.5 FOR LIQUEFACTION TO BE A CONCERN FOR SOILS BELOW THE TOE OF THE DAM, AND N_1 MUST BE LESS THAN 3.6 TO 4.4 FOR SOILS BELOW THE CREST OF THE DAM TO BE CONSIDERED POTENTIALLY LIQUEFACTABLE.
- ONE VALUE OF N_1 EQUAL TO 6.7 WAS FOUND IN THE FOUNDATION SOILS OF DRILLING DEC-101 AT 50 FT. BELOW THE DAM CREST ABOVE G.W.L. ALL OTHER VALUES OF N_1 IN THE FOUNDATION SOILS EQUALLED OR EXCEEDED 9.
- THEREFORE, IT IS CONCLUDED THAT THE FOUNDATION SOILS AT THE DAM SITE ARE NOT SUSCEPTIBLE TO LIQUEFACTION.



Client C. O. E.
 Project ONONDAGA DAM
 File Number 7C50-032
 Sheet 1 of 3
 Date 25 AUG 82
 Computed by DJS/MAW
 Checked by WAW/ES

* STRESSES DUE TO EMBANKMENT
 (CREP. PER COFF & BARON 1976)
 pp. 682-683



- USE:
 $L = 12.5'$
 $H = 60'$
 $y/H \approx 0.2$
- SLIDE SLOPE = $1/2:1$
 $\alpha = 22^\circ$
- ASSUME $\mu = 0.3$

- a) CENTER OF EMBANKMENT $x/H = 0$
 b) TOE OF EMBANKMENT $y/H = (L + H \cot \alpha)/H$

(FT) DEPTH	y/H	$\sigma_y/\gamma H$ ($\gamma H = 60(130) = 7800 \text{ PSF}$)			
		CENTER $\alpha = 15^\circ$	CENTER $\alpha = 30^\circ$	TOE $\alpha = 15^\circ$	TOE $\alpha = 30^\circ$
60	1.00	0.82 (0.76)	0.70	0.0	(0.0)
75	1.25	-	-	-	-
90	1.50	0.78 (0.70)	0.61	0.07 (0.08)	0.10
105	1.75	-	-	-	-
120	2.00	0.71 (0.62)	0.53	0.11 (0.12)	0.14
135	2.25	-	-	-	-
150	2.50	0.65 (0.55)	0.45	0.14 (0.15)	0.17
165	2.75	-	-	-	-
180	3.00	0.61 (0.50)	0.39	0.16 (0.17)	0.19

DEPTH IN FT. OF NATU- RAL GROUND IN FT.	$\Delta \bar{\sigma}_v$ (PSF)	$\Delta \bar{\sigma}_v$ (PSF) (C)		$\Delta \bar{\sigma}_v$ (PSF) (TOE)	
		35' EMB.	55' EMB.	55' EMB.	65' EMB.
0	54 35	6,420 (6190)	0	0	0
30	50 05	5915 (5700)	575	675	
60	44 35	5240 (5045)	823	1,015	
90	39 35	4650 (4400)	1,075	1,270	
120	35 75	4230 (4070)	1,215	1,440	
		\uparrow GWT @ 65' (NAWML)			



Client C.O.E.
 Project ONONDAGA DAM

File Number 7450-5%
 Sheet 2 of 3
 Date 8 SEP 82
 Computed by WAW
 Checked by CS

* DYNAMIC SHEAR STRESSES

$$\tau = 0.65 \alpha_{max} r_d \sigma_{vo}$$

α_{max} = peak horizontal ground acceleration
at ground surface (g_z)

r_d = depth reduction factor

σ_{vo} = total overburden pressure

* REFER ATC-3 DOCUMENT - FIG. C1-8

- RATIO OF "SOFT SOIL" PEAK TO "ROCK" PEAK :

$$\frac{2.8}{2.5} \approx 1.16$$

- USE 1.2 AS AMPLIFICATION FACTOR.

- NATURAL GROUND SURFACE ACCELERATION (PEAK HORIZONTAL) = (1.2)(0.05) = 0.06 g_z

$$\alpha_{max} = 0.06 g_z$$

BELLOW TOE OF DAM
(NATURAL GROUND)

BELLOW MAST OF DAM

Depth (ft)	σ_{vo} (PSF)	r_d	τ (1.0)	r_d	τ (1.0)
1	15,000	1.0	30		
2	11,250	1.0	30		
5	10,000	0.90	50		
10	9,000	0.75	47		
20	8,000	0.9	100		
40	7,200	0.95	172		
50	6,720	0.75	116	1.0	116
75	5,760	0.8	716	0.9	751
100	5,200	0.8	416	0.95	416
125	4,800	0.8	520	1.2	520
150	4,500	0.8	624		

HALEY & ALDRICH, INC., Cambridge, Massachusetts



Client C. O. E
Project ONONDAGA DAM

File Number 7450-03
Sheet 3
Date 8 SEP 81
Computed by WA-W
Checked by CB

BORING	DEPTH below natural ground level (FT)	TEST TYPE	$\bar{\tau}_{v0}$ (PSF)			$\bar{\tau}_{v0}$ (PSF)			$\bar{\tau}_{v0}$ (PSF)			$\bar{\tau}_{v0}$ (PSF)			N	C_N	
			TEST			TOE			TEST			TEST					
			VEST	TOE	VEST	TOE	VEST	TOE	VEST	TOE	VEST	TOE	VEST	TOE	VEST		
D-82-																	
101	56	1	4765	150	8755	150	223	7	0.040	0.047	(20)12	0.558	6.7				
4NT@ 62.445 (60')	61	5	6130	695	6065	635	245	35	0.040	0.042	17	0.529	9.0				
71	16	7165	2385	6600	1705	262	82	0.043	0.052	(36)20	0.506	10.1					
77	22	7980	3180	6925	2225	301	119	0.042	0.047	(60)32	0.488	15.6					
97	42	10235	6150	7945	3055	361	266	0.045	0.053	39	0.441	17.2					
<u>NET NATURAL</u> $\sigma_{v0} = 4,420 \text{ PSF}$, $\bar{\tau}_{v0} = 1190 \text{ PSF}$																	
D-82																	
102	67	2	6645	305	6295	180	262	13	0.042	0.071	33	0.518	17.1				
4NT@ 62.445 (60')	69	4	6870	610	6195	360	270	24	0.042	0.068	26	0.512	13.3				
105	40	10890	5990	8100	3480	374	201	0.046	0.058	32	0.431	13.0					
121	56	12610	8257	8940	4740	408	461	0.046	0.057	31	0.400	12.4					
142	77	14915	11170	9960	6350	477	557	0.048	0.072	30	0.400	12.0					
<u>TEST</u>																	
101	70	5	6265	765	6450	4150	270	30	0.042	0.067	18	0.570	9.2				
4NT@ 62.445 (60')	98	1065	6705	6320	370	195	0.042	0.058	36	0.483	15.6						
130	65	13590	9510	9370	57435	415	305	0.042	0.052	40	0.395	15.4					

* VALUES ADDED BY BUFFALO DIST BY GL 6/6/83

() REPRESENTS ACTUAL UNCORRECTED PENETRATION
() RESISTANCES FOR 3.6IN DIA. SPOON

END
DATE
FILMED
8-86